



# Tsi577™ Design Notes

April 11, 2014

---



---

## About this document

This document describes design notes for the Tsi577. Design notes are unique functional characteristics of the device that may or may not be described in the *Tsi577 User Manual* and should be reviewed when designing with the Tsi577. This document should also be used with the *Tsi577 Device Errata* document.

### Revision History

April 11, 2014

Added [Packet discard on link partner failure](#)

August 2009

There have been no technical changes to this document. The formatting was changed to reflect IDT.

January 2009

The following design note was added to this document, [I2C Multi-master Clock Generation Issue](#).

August 2008

This is the first version of this document.

---

## Design Notes

### No.1. Port Power-down and Default Configuration

When a port is powered down, the port loses the port write destinationID that is stored for that particular port. Multicast settings, port write settings and other non-port specific registers return to their default power up settings after a port reset. After port reset, there is no way to determine that the configuration for a particular port is correct.

For example, if a port is shut down and then restored, the port write destination ID is reset to zero. The port write destination ID must be reset for the whole device after a port has been shut down and restored. Similarly, multicast settings for the entire device must be re-written when a port has been shut down and restored.

For more information on port power down registers that return to their default settings, refer to the *Tsi577 User Manual*.

## No.2. Four 1x Links to 4x Port Training

Connecting four 1x links to a 4x port is not supported and may result in false lane alignment. The Tsi577 correctly detects alignment characters during the 4x training process. However, connecting a four lane 1x port to the Tsi577 while the Tsi577 is expecting to train with a 4x link partner causes the Tsi577 to remain in a PORT\_UNINIT state and to never complete the training process in 1x mode.

This situation occurs because the Tsi577 is expecting align characters to be inserted on the four lanes by the link partner in order to complete the receive FIFO skew alignment process. Since the link partner is sending 1x links, it never inserts the align characters required to assist in the completion of the 4x link training process and since all four lanes are active, it never downgrades to 1x mode.

## No.3. Default Port Transmit Electrical Characteristics May Not be Optimal

The Tsi577's default transmit amplitude and pre-emphasis settings may not be optimal in all applications, depending on the trace losses on the printed wiring board. This may result in a degradation in the Bit Error Rate (BER).

The BER can be improved by overwriting the power-on default values of the SRIO MAC x SerDes Configuration Global register to increase the output amplitude and apply more pre-emphasis to the output signal.

## No.4. Masterless I<sup>2</sup>C Bus Busy

This design note applies only to designs that require the Tsi577 to load registers from an I<sup>2</sup>C EEPROM.

Because EEPROM devices do not have reset pins, if the Tsi577 is reset the EEPROM is unaffected and can continue to drive data. If the EEPROM continues to drive the I<sup>2</sup>C data signal to 0, the Tsi577 is not able to load register values after reset is removed. Unexpected operation after a reset can result if register values cannot be loaded.



The *I<sup>2</sup>C Specification* (for multiple master support) specifies that the I<sup>2</sup>C bus is considered busy when the I<sup>2</sup>C data signal is 0.

### Hardware

To avoid this condition, design the reset of the Tsi577, and all other I<sup>2</sup>C masters, so that the I<sup>2</sup>C bus is always idle before asserting reset for the Tsi577 or any I<sup>2</sup>C bus master.

### Software

A software work around can be implemented to deal with this condition. The software work around has the following steps:

1. Determine that the I<sup>2</sup>C bus is busy while there is no master
2. Issue a reset on the I<sup>2</sup>C bus
3. Trigger a reset of the Tsi577 to perform the register value loading.



To implement the software work around, the Tsi577 must be configured to allow host processor access through RapidIO after reset using the power-up configuration pins.

For more information, refer to the *Tsi577 Hardware Manual*.

### Testing

The software solution can be tested using the IDT JTAG Register Access Software (available at [www.idt.com](http://www.idt.com)). This software includes scripts which recreate the Masterless I<sup>2</sup>C Bus Busy condition.

### Step 1: Masterless I<sup>2</sup>C Bus Busy

The registers listed in the following table must be read, and the register values must match those values described in the table, to determine that the bus is busy but there is no master.

Register Name	Register Offset	Register Value Descriptions
I <sup>2</sup> C Interrupt Status Register	1D11C	BL_OK and BL_FAIL bits are both 0
Internal I <sup>2</sup> C Status Register 1	1D300	0x00001F00 ANDed with the register value = 0
Internal I <sup>2</sup> C Status Register 2	1D3D0	0x0000000F ANDed with the register value = 0x0000000B
Internal I <sup>2</sup> C Status Register 3	1D3D4	Register Value = 0x0000021
Internal I <sup>2</sup> C Status Register 3, read 200 microseconds later	1D3D4	Register Value = 0x0000020
Internal I <sup>2</sup> C Status Register 4	1D3D8	0x00000E00 ANDed with the register value = 0x00000600

### Step 2: Issue an I<sup>2</sup>C Bus Reset

Driving nine I<sup>2</sup>C clock cycles completes an interrupted transfer. An I<sup>2</sup>C clock cycle occurs whenever the I<sup>2</sup>C clock is driven low for at least five microseconds, and then is released to be high.



Multiple I<sup>2</sup>C EEPROM devices document driving nine I<sup>2</sup>C clock cycles for reset.

The register accesses listed in the following table drives I<sup>2</sup>C clock cycles to complete the interrupted I<sup>2</sup>C bus transfer. The sequence of writes in the table must be repeated nine times.

Register Name	Register Offset	Register Value
Internal I <sup>2</sup> C Control Register	1D3C0	Write 0x00000008, wait five microseconds.
Internal I <sup>2</sup> C Control Register	1D3C0	Write 0x00000000, wait five microseconds.

### Step 3: Reset the Tsi577

There are a number of different methods to reset the Tsi577 documented in the *Tsi577 User Manual*. It is also possible for the host processor to reset the Tsi577 by system specific means.

## No.5. I2C Multi-master Clock Generation Issue

When the Tsi577's I2C Interface is in a multi-master system, the I2C Interface does not generate a correct clock low period. The error can occur when all the following conditions are met:

- Both the external master and the I2C Interface are generating the clock
- The external master pulls the clock low two reference clock cycles before the I2C clock high timer expires

These conditions are possible only when an external master illegally attempts to use the bus when the Tsi577 is the bus master. In an expected configuration, two masters are unlikely to be operating at the same time. As well, experiencing this issue requires precise timing between the two masters. Because of these factors, this erratum is not likely to occur in a system.

This issue does not occur when the Tsi577's I2C Interface is the only master.

## No.6. Packet discard on link partner failure

The Tsi577 was designed to allow systems to continue operating when a link partner has been reset or otherwise failed. The device must perform two actions to allow a system to continue to operate:

- Notify the system host that a link partner has failed
- Discard packets destined for the failed link partner

Port-writes, triggered when the ERR\_RATE\_CNT bit in the RapidIO Port x Error Rate CSR exceeds the ERR\_RFT bit threshold in the RapidIO Port x Error Rate Threshold CSR, should be used to notify the system host that a failure has occurred.

Two discard mechanisms should be used:

- Set the DROP\_EN and STOP\_FAIL\_EN bits in the RapidIO Port x Control CSR to discard packets when ERR\_RATE\_CNT in the RapidIO Port x Error Rate CSR exceeds the ERR\_RFT threshold in the RapidIO Port x Error Rate Threshold CSR, and the port is not in output error-stopped state. This is known as the "standard" discard mechanism.
- Enable the Dead Link Timer with the minimum time value in order to discard packets until the link has reinitialized.

Usually, systems follow a "fail stop" philosophy. Once a fault is detected on a link, all traffic destined for the link must be discarded until software recovers the link. Packet discard due to the Dead Link Timer will cease once the link has reinitialized. If the link partner has failed only temporarily, or the link has reinitialized due to a high temporary bit error rate, the standard discard mechanism will operate after the link has reinitialized. However, if the link partner was reset, the port will detect an ackID mismatch, enter output error-stopped state, and will be unable to discard packets.

Systems that must support link partner reset must set the PORT\_LOCKOUT bit in the RapidIO Serial Port x Control CSR before the link reinitializes in order to ensure that packet discard continues. The implication is that software must be capable of receiving a port-write, processing the port write, and setting the PORT\_LOCKOUT bit in less than 80 microseconds.

Note that the board reset controller could support holding devices in reset for a period long enough to ensure that software can set the PORT\_LOCKOUT bit.



**CORPORATE HEADQUARTERS**  
6024 Silver Creek Valley Road  
San Jose, CA 95138

**for SALES:**  
800-345-7015 or 408-284-8200  
www.idt.com

**for Tech Support:**  
email: srio@idt.com

DISCLAIMER Integrated Device Technology, Inc. (IDT) and its subsidiaries reserve the right to modify the products and/or specifications described herein at any time and at IDT's sole discretion. Performance specifications and the operating parameters of the described products are determined in the independent state and are not guaranteed to perform the same way when installed in customer products. The information contained herein is provided without representation or warranty of any kind, whether express or implied, including, but not limited to, the suitability of IDT's products for any particular purpose, an implied warranty of merchantability, or non-infringement of the intellectual property rights of others. This document is presented only as a guide and does not convey any license under intellectual property rights of IDT or any third parties.

IDT's products are not intended for use in life support systems or similar devices where the failure or malfunction of an IDT product can be reasonably expected to significantly affect the health or safety of users. Anyone using an IDT product in such a manner does so at their own risk, absent an express, written agreement by IDT.

Integrated Device Technology, IDT and the IDT logo are registered trademarks of IDT. Other trademarks and service marks used herein, including protected names, logos and designs, are the property of IDT or their respective third party owners.

Copyright 2014. All rights reserved.