



Integrated Device Technology, Inc.
 6024 Silver Creek Valley Road, San Jose, CA 95138

PRODUCT/PROCESS CHANGE NOTICE (PCN)

PCN #: **TB0910-01R1** DATE: **9-Apr-2010**
 Product Affected: IDT selective Plastic packages -
 QVSOP, SSOP, TSSOP, QSOP
 Date Effective: **15-Feb-2010**

MEANS OF DISTINGUISHING CHANGED DEVICES:
 Product Mark
 Back Mark
 Date Code
 Other Shipment starting from 15-Feb-2010

Contact: Geoffrey Cortes
 Title: Product Quality
 Phone #: (408) 284-8321
 Fax #: (408) 284-1450
 E-mail: Geoffrey.Cortes@idt.com

Attachment: Yes No

Samples: Contact your local IDT sales representative for
 sample requests.

DESCRIPTION AND PURPOSE OF CHANGE:

- Die Technology
 - Wafer Fabrication Process
 - Assembly Process
 - Equipment
 - Material
 - Testing
 - Manufacturing Site
 - Data Sheet
 - Other - Product Top Mark
- Revision 1:** This revised notification is to remove all ICS part numbers from this change. Refer to Page 2 for the updated affected part numbers.
- The PCN effective date remains unchanged.
- A copy of the original PCN notification is attached for reference.

RELIABILITY/QUALIFICATION SUMMARY:
 Not applicable.

CUSTOMER ACKNOWLEDGMENT OF RECEIPT:

IDT records indicate that you require written notification of this change. Please use the acknowledgement below or E-Mail to grant approval or request additional information. If IDT does not receive acknowledgement within 30 days of this notice it will be assumed that this change is acceptable.

IDT reserves the right to ship either version manufactured after the process change effective date until the inventory on the earlier version has been depleted.

Customer: _____ *Approval for shipments prior to effective date.*
 Name/Date: _____ E-Mail Address: _____
 Title: _____ Phone # /Fax #: _____

CUSTOMER COMMENTS: _____

IDT ACKNOWLEDGMENT OF RECEIPT:

RECD. BY: _____ DATE: _____



Integrated Device Technology, Inc.
6024 Silver Creek Valley Road, San Jose, CA 95138

PRODUCT/PROCESS CHANGE NOTICE (PCN)

ATTACHMENT 2 - PCN #: TB0910-01R1

Affected Part Number

| Part Number | Part Number | Part Number | Part Number |
|--------------|--------------|---------------|---------------|
| 2305-1PGG | 2308-2HDCI | 2308A-1DCI | 2308A-4DCI |
| 2305-1PGG8 | 2308-2HDCI8 | 2308A-1DCI8 | 2308A-4DCI8 |
| 2305B-1PGG | 2308-2HPGG | 2308A-1HDCG | 2308A-5HPGG |
| 2305B-1PGG8 | 2308-2HPGG8 | 2308A-1HDCG8 | 2308A-5HPGG8 |
| 2305B-1PGGI | 2308-2HPGGI | 2308A-1HDCGI | 2308B-1DC |
| 2305B-1PGGI8 | 2308-2HPGGI8 | 2308A-1HDCGI8 | 2308B-1DC8 |
| 2308-1DC | 2308-3DC | 2308A-1HDCI | 2308B-1DCG |
| 2308-1DC8 | 2308-3DC8 | 2308A-1HDCI8 | 2308B-1DCG8 |
| 2308-1DCG | 2308-3DCG | 2308A-1HPG | 2308B-1DCGI |
| 2308-1DCG8 | 2308-3DCG8 | 2308A-1HPG8 | 2308B-1DCGI8 |
| 2308-1DCGI | 2308-3DCGI | 2308A-1HPGG | 2308B-1DCI |
| 2308-1DCGI8 | 2308-3DCGI8 | 2308A-1HPGG8 | 2308B-1DCI8 |
| 2308-1DCI | 2308-3DCI | 2308A-1HPGGI | 2308B-1HDC |
| 2308-1DCI8 | 2308-3DCI8 | 2308A-1HPGGI8 | 2308B-1HDC8 |
| 2308-1HDC | 2308-4DC | 2308A-1HPGI | 2308B-1HDCG |
| 2308-1HDC8 | 2308-4DC8 | 2308A-1HPGI8 | 2308B-1HDCG8 |
| 2308-1HDCG | 2308-4DCG | 2308A-2DC | 2308B-1HDCGI |
| 2308-1HDCG8 | 2308-4DCG8 | 2308A-2DC8 | 2308B-1HDCGI8 |
| 2308-1HDCGI | 2308-4DCGI | 2308A-2DCG | 2308B-1HDCI |
| 2308-1HDCGI8 | 2308-4DCGI8 | 2308A-2DCG8 | 2308B-1HDCI8 |
| 2308-1HDCI | 2308-4DCI | 2308A-2DCGI | 2308B-1HPG |
| 2308-1HDCI8 | 2308-4DCI8 | 2308A-2DCGI8 | 2308B-1HPG8 |
| 2308-1HPG | 2308-5HDC | 2308A-2DCI | 2308B-1HPGG |
| 2308-1HPG8 | 2308-5HDC8 | 2308A-2DCI8 | 2308B-1HPGG8 |
| 2308-1HPGG | 2308-5HDCG | 2308A-2HDC | 2308B-1HPGGI |
| 2308-1HPGG8 | 2308-5HDCG8 | 2308A-2HDC8 | 2308B-1HPGGI8 |
| 2308-1HPGGI | 2308-5HDCGI | 2308A-2HDCG | 2308B-1HPGI |
| 2308-1HPGGI8 | 2308-5HDCGI8 | 2308A-2HDCG8 | 2308B-1HPGI8 |
| 2308-1HPGI | 2308-5HDCI | 2308A-2HDCI | 2308B-2DC |
| 2308-1HPGI8 | 2308-5HDCI8 | 2308A-2HDCI8 | 2308B-2DC8 |
| 2308-2DC | 2308-5HPG | 2308A-3DC | 2308B-2DCG |
| 2308-2DC8 | 2308-5HPG8 | 2308A-3DC8 | 2308B-2DCG8 |
| 2308-2DCG | 2308-5HPGG | 2308A-3DCG | 2308B-2DCGI |
| 2308-2DCG8 | 2308-5HPGG8 | 2308A-3DCG8 | 2308B-2DCGI8 |
| 2308-2DCGI | 2308-5HPGGI | 2308A-3DCGI | 2308B-2DCI |
| 2308-2DCGI8 | 2308-5HPGGI8 | 2308A-3DCGI8 | 2308B-2DCI8 |
| 2308-2DCI | 2308-5HPGI | 2308A-3DCI | 2308B-3DC |
| 2308-2DCI8 | 2308-5HPGI8 | 2308A-3DCI8 | 2308B-3DC8 |
| 2308-2HDC | 2308A-1DC | 2308A-4DC | 2308B-3DCG |
| 2308-2HDC8 | 2308A-1DC8 | 2308A-4DC8 | 2308B-3DCG8 |
| 2308-2HDCG | 2308A-1DCG | 2308A-4DCG | 2308B-4DC |
| 2308-2HDCG8 | 2308A-1DCG8 | 2308A-4DCG8 | 2308B-4DC8 |
| 2308-2HDCGI | 2308A-1DCGI | 2308A-4DCGI | 2308B-4DCG |
| 2308-2HDCGI8 | 2308A-1DCGI8 | 2308A-4DCGI8 | 2308B-4DCG8 |



Integrated Device Technology, Inc.
6024 Silver Creek Valley Road, San Jose, CA 95138

PRODUCT/PROCESS CHANGE NOTICE (PCN)

ATTACHMENT 2 - PCN #: TB0910-01R1

Affected Part Number

| Part Number | Part Number | Part Number | Part Number |
|--------------|----------------|---------------|----------------|
| 2308B-4DCI | 2309A-1HPGG | 23S08-1DC | 23S08-4DCI |
| 2308B-4DCI8 | 2309A-1HPGG8 | 23S08-1DC8 | 23S08-4DCI8 |
| 2308B-5HPG | 2309A-1HPGGI | 23S08-1DCG | 23S08-5HDC |
| 2308B-5HPG8 | 2309A-1HPGGI8 | 23S08-1DCG8 | 23S08-5HDC8 |
| 2309-1DC | 2309A-1HPGI | 23S08-1DCGI | 23S08-5HDCG |
| 2309-1DC8 | 2309A-1HPGI8 | 23S08-1DCGI8 | 23S08-5HDCG8 |
| 2309-1DCG | 2309B-1DC | 23S08-1DCI | 23S08-5HDCGI |
| 2309-1DCG8 | 2309B-1DC8 | 23S08-1DCI8 | 23S08-5HDCGI8 |
| 2309-1DCGI | 2309B-1DCG | 23S08-1HDC | 23S08-5HPGG |
| 2309-1DCGI8 | 2309B-1DCG8 | 23S08-1HDC8 | 23S08-5HPGG8 |
| 2309-1DCI | 2309B-1DCI | 23S08-1HDCG | 23S08E-1DC |
| 2309-1DCI8 | 2309B-1DCI8 | 23S08-1HDCG8 | 23S08E-1DC8 |
| 2309-1HDC | 2309B-1HDC | 23S08-1HDCGI | 23S08E-1DCG |
| 2309-1HDC8 | 2309B-1HDC8 | 23S08-1HDCGI8 | 23S08E-1DCG8 |
| 2309-1HDCG | 2309B-1HDCG | 23S08-1HDCI | 23S08E-1DCGI |
| 2309-1HDCG8 | 2309B-1HDCG8 | 23S08-1HDCI8 | 23S08E-1DCGI8 |
| 2309-1HDCGI | 2309B-1HDCGI | 23S08-1HPGG | 23S08E-1DCI |
| 2309-1HDCGI8 | 2309B-1HDCGI8 | 23S08-1HPGG8 | 23S08E-1DCI8 |
| 2309-1HDCI | 2309B-1HDCI | 23S08-1HPGGI | 23S08E-1HDC |
| 2309-1HDCI8 | 2309B-1HDCI8 | 23S08-1HPGGI8 | 23S08E-1HDC8 |
| 2309-1HPG | 2309B-1HPG | 23S08-2DC | 23S08E-1HDCG |
| 2309-1HPG8 | 2309B-1HPG8 | 23S08-2DC8 | 23S08E-1HDCG8 |
| 2309-1HPGG | 2309B-1HPGG | 23S08-2DCG | 23S08E-1HDCGI |
| 2309-1HPGG8 | 2309B-1HPGG8 | 23S08-2DCG8 | 23S08E-1HDCGI8 |
| 2309-1HPGGI | 2309B-1HPGGI | 23S08-2DCGI | 23S08E-1HDCI |
| 2309-1HPGGI8 | 2309B-1HPGGI8 | 23S08-2DCGI8 | 23S08E-1HDCI8 |
| 2309-1HPGI | 2309B-1HPGI | 23S08-2DCI | 23S08E-1HPG |
| 2309-1HPGI8 | 2309B-1HPGI8 | 23S08-2DCI8 | 23S08E-1HPG8 |
| 2309A-1DC | 2309NZ-1HDC | 23S08-2HDC | 23S08E-1HPGG |
| 2309A-1DC8 | 2309NZ-1HDC8 | 23S08-2HDC8 | 23S08E-1HPGG8 |
| 2309A-1DCG | 2309NZ-1HDCG | 23S08-2HDCG | 23S08E-1HPGGI |
| 2309A-1DCG8 | 2309NZ-1HDCG8 | 23S08-2HDCG8 | 23S08E-1HPGGI8 |
| 2309A-1DCGI | 2309NZ-1HDCGI | 23S08-2HDCGI | 23S08E-2DC |
| 2309A-1DCGI8 | 2309NZ-1HDCGI8 | 23S08-2HDCGI8 | 23S08E-2DC8 |
| 2309A-1DCI | 2309NZ-1HDCI | 23S08-3DC | 23S08E-2DCG |
| 2309A-1DCI8 | 2309NZ-1HDCI8 | 23S08-3DC8 | 23S08E-2DCG8 |
| 2309A-1HDC | 2309NZ-1HPG | 23S08-3DCG | 23S08E-2DCGI |
| 2309A-1HDC8 | 2309NZ-1HPG8 | 23S08-3DCG8 | 23S08E-2DCGI8 |
| 2309A-1HDCG | 2309NZ-1HPGG | 23S08-3DCGI | 23S08E-2DCI |
| 2309A-1HDCG8 | 2309NZ-1HPGG8 | 23S08-3DCGI8 | 23S08E-2DCI8 |
| 2309A-1HDCI | 2309NZ-1HPGGI | 23S08-4DCG | 23S08E-2HDCG |
| 2309A-1HDCI8 | 2309NZ-1HPGGI8 | 23S08-4DCG8 | 23S08E-2HDCG8 |
| 2309A-1HPG | 2309NZ-1HPGI | 23S08-4DCGI | 23S08E-2HDCGI |
| 2309A-1HPG8 | 2309NZ-1HPGI8 | 23S08-4DCGI8 | 23S08E-2HDCGI8 |



Integrated Device Technology, Inc.
6024 Silver Creek Valley Road, San Jose, CA 95138

PRODUCT/PROCESS CHANGE NOTICE (PCN)

ATTACHMENT 2 - PCN #: TB0910-01R1

Affected Part Number

| Part Number | Part Number | Part Number | Part Number |
|----------------|-----------------|-----------------|----------------|
| 23S08E-3DC | 23S09E-1DCG | 49FCT3805AQG | 49FCT3805PYI |
| 23S08E-3DC8 | 23S09E-1DCG8 | 49FCT3805AQG8 | 49FCT3805PYI8 |
| 23S08E-3DCG | 23S09E-1DCGI | 49FCT3805AQGI | 49FCT3805Q |
| 23S08E-3DCG8 | 23S09E-1DCGI8 | 49FCT3805AQGI8 | 49FCT3805Q8 |
| 23S08E-3DCGI | 23S09E-1DCI | 49FCT3805AQI | 49FCT3805QG |
| 23S08E-3DCGI8 | 23S09E-1DCI8 | 49FCT3805AQI8 | 49FCT3805QG8 |
| 23S08E-3DCI | 23S09E-1HDC | 49FCT3805BPY | 49FCT3805QGI |
| 23S08E-3DCI8 | 23S09E-1HDC8 | 49FCT3805BPY8 | 49FCT3805QGI8 |
| 23S08E-4DC | 23S09E-1HDCGI | 49FCT3805BPYG | 49FCT3805QI |
| 23S08E-4DC8 | 23S09E-1HDCGI8 | 49FCT3805BPYG8 | 49FCT3805QI8 |
| 23S08E-4DCG | 23S09E-1HDCI | 49FCT3805BPYGI | 49FCT805APY |
| 23S08E-4DCG8 | 23S09E-1HDCI8 | 49FCT3805BPYGI8 | 49FCT805APY8 |
| 23S08E-4DCGI | 23S09E-1HPG | 49FCT3805BPYI | 49FCT805APYG |
| 23S08E-4DCGI8 | 23S09E-1HPG8 | 49FCT3805BPYI8 | 49FCT805APYG8 |
| 23S08E-5HDC | 23S09E-1HPGG | 49FCT3805BQ | 49FCT805APYGI |
| 23S08E-5HDC8 | 23S09E-1HPGG8 | 49FCT3805BQ8 | 49FCT805APYGI8 |
| 23S08E-5HDCG | 23S09E-1HPGGI | 49FCT3805BQG | 49FCT805APYI |
| 23S08E-5HDCG8 | 23S09E-1HPGGI8 | 49FCT3805BQG8 | 49FCT805APYI8 |
| 23S08E-5HDCGI | 23S09E-1HPGI | 49FCT3805BQGI | 49FCT805BTPY |
| 23S08E-5HDCGI8 | 23S09E-1HPGI8 | 49FCT3805BQGI8 | 49FCT805BTPY8 |
| 23S08E-5HPGI | 23S09T-1DC | 49FCT3805BQI | 49FCT805BTPYG |
| 23S08E-5HPGI8 | 23S09T-1DC8 | 49FCT3805BQI8 | 49FCT805BTPYG8 |
| 23S08T-1DCG | 23S09T-1DCG | 49FCT3805DPYGI | 49FCT805BTQ |
| 23S08T-1DCG8 | 23S09T-1DCG8 | 49FCT3805DPYGI8 | 49FCT805BTQ8 |
| 23S09-1DC | 29FCT2052CTQ | 49FCT3805DPYI | 49FCT805BTQG |
| 23S09-1DC8 | 29FCT2052CTQ8 | 49FCT3805DPYI8 | 49FCT805BTQG8 |
| 23S09-1DCG | 49FCT20805PYGI | 49FCT3805DQGI | 49FCT805CTPY |
| 23S09-1DCG8 | 49FCT20805PYGI8 | 49FCT3805DQGI8 | 49FCT805CTPY8 |
| 23S09-1DCGI | 49FCT20805PYI | 49FCT3805DQI | 49FCT805CTPYG |
| 23S09-1DCGI8 | 49FCT20805PYI8 | 49FCT3805DQI8 | 49FCT805CTPYG8 |
| 23S09-1HDC | 49FCT20805QGI | 49FCT3805EPYGI | 49FCT805CTQ |
| 23S09-1HDC8 | 49FCT20805QGI8 | 49FCT3805EPYGI8 | 49FCT805CTQ8 |
| 23S09-1HDCG | 49FCT20805QI | 49FCT3805EPYI | 49FCT805CTQG |
| 23S09-1HDCG8 | 49FCT20805QI8 | 49FCT3805EPYI8 | 49FCT805CTQG8 |
| 23S09-1HDCGI | 49FCT3805APY | 49FCT3805EQGI | 49FCT805PY |
| 23S09-1HDCGI8 | 49FCT3805APY8 | 49FCT3805EQGI8 | 49FCT805PY8 |
| 23S09-1HPG | 49FCT3805APYG | 49FCT3805EQI | 49FCT805PYG |
| 23S09-1HPG8 | 49FCT3805APYG8 | 49FCT3805EQI8 | 49FCT805PYG8 |
| 23S09-1HPGG | 49FCT3805APYGI | 49FCT3805PY | 49FCT805PYGI |
| 23S09-1HPGG8 | 49FCT3805APYGI8 | 49FCT3805PY8 | 49FCT805PYGI8 |
| 23S09-1HPGGI | 49FCT3805APYI | 49FCT3805PYG | 49FCT805PYI |
| 23S09-1HPGGI8 | 49FCT3805APYI8 | 49FCT3805PYG8 | 49FCT805PYI8 |
| 23S09E-1DC | 49FCT3805AQ | 49FCT3805PYGI | 49FCT806APY |
| 23S09E-1DC8 | 49FCT3805AQ8 | 49FCT3805PYGI8 | 49FCT806APY8 |



Integrated Device Technology, Inc.
6024 Silver Creek Valley Road, San Jose, CA 95138

PRODUCT/PROCESS CHANGE NOTICE (PCN)

ATTACHMENT 2 - PCN #: TB0910-01R1

Affected Part Number

| Part Number | Part Number | Part Number | Part Number |
|---------------|--------------------|-----------------|---------------|
| 49FCT806APYG | 5T9304PGG | 5V80001PGGI | 6U40R001APGG |
| 49FCT806APYG8 | 5T9304PGG8 | 5V80001PGGI8 | 6U40R001APGG8 |
| 49FCT806BTPY | 5T93GL02PGGI | 5V925QGI | 6U40R001PGG |
| 49FCT806BTPY8 | 5T93GL02PGGI8 | 5V925QGI8 | 6U40R001PGG8 |
| 49FCT806CTPY | 5T93GL02PGI | 5V925QI | 6V10001PGG |
| 49FCT806CTPY8 | 5T93GL02PGI8 | 5V925QI8 | 6V10001PGG8 |
| 49FCT806CTQ | 5T93GL04PGGI | 5V926APGGI | 6V10003APYGI |
| 49FCT806CTQ8 | 5T93GL04PGGI8 | 5V926APGGI8 | 6V10003APYGI8 |
| 49FCT806PY | 5T93GL04PGI | 5V927PGGI | 6V10003PYGI |
| 49FCT806PY8 | 5T93GL04PGI8 | 5V927PGGI8 | 6V10003PYGI8 |
| 49FCT806PYG | 5V19EE901PGGI | 5V927PGI | 6V10006APGGI |
| 49FCT806PYG8 | 5V19EE901PGGI8 | 5V927PGI8 | 6V10006APGGI8 |
| 5993A-2Q | 5V19EE903PGGI | 5V928PGGI | 6V10012PGG |
| 5993A-2Q8 | 5V19EE903PGGI8 | 5V928PGGI8 | 6V10012PGG8 |
| 5993A-5QI | 5V2305PGGI | 5V928PGI | 6V10016PGGI |
| 5993A-5QI8 | 5V2305PGGI8 | 5V928PGI8 | 6V10016PGGI8 |
| 5993A-7QI | 5V2305PGI | 5V9882PGGI | 6V10020APGG |
| 5993A-7QI8 | 5V2305PGI8 | 5V9882PGGI8 | 6V10020APGG8 |
| 5P61006PGGI | 5V2310PGGI | 5V9886-002PGGI | 6V10020PGG |
| 5P61006PGGI8 | 5V2310PGGI8 | 5V9886-002PGGI8 | 6V10020PGG8 |
| 5T30009PGGI | 5V2310PGI | 5V9886-005PGGI | 6V10022PGG |
| 5T30009PGGI8 | 5V2310PGI8 | 5V9886-005PGGI8 | 6V10022PGG8 |
| 5T9050PGGI | 5V2528APGGI | 5V9886PGGI | 6V10023PGG |
| 5T9050PGGI8 | 5V2528APGGI8 | 5V9886PGGI8 | 6V10023PGG8 |
| 5T9050PGI | 5V2528APGI | 5V993A-2Q | 6V10025PGG |
| 5T9050PGI8 | 5V2528APGI8 | 5V993A-2Q8 | 6V10025PGG8 |
| 5T90533PGGI | 5V2528PGGI | 5V993A-2QG | 6V10026PGG |
| 5T90533PGGI8 | 5V2528PGGI8 | 5V993A-2QG8 | 6V10026PGG8 |
| 5T905PGGI | 5V2528PGI | 5V993A-5QGI | 6V40006APGG |
| 5T905PGGI8 | 5V2528PGI8 | 5V993A-5QGI8 | 6V40006APGG8 |
| 5T905PGI | 5V30002DCG | 5V993A-5QI | 6V40006APGGI |
| 5T905PGI8 | 5V30002DCG8 | 5V993A-5QI8 | 6V40006APGGI8 |
| 5T9302EJGI | 5V49EE901-001PGGI | 5V993A-7QGI | 6V40006PGG |
| 5T9302EJGI8 | 5V49EE901-001PGGI8 | 5V993A-7QGI8 | 6V40006PGG8 |
| 5T9302EJI | 5V49EE901PGGI | 5V993A-7QI | 6V40016PGG |
| 5T9302EJI8 | 5V49EE901PGGI8 | 5V993A-7QI8 | 6V40016PGG8 |
| 5T9302PGG | 5V49EE903PGGI | 6P40086PGG | 6V40019PGG |
| 5T9302PGG8 | 5V49EE903PGGI8 | 6P40086PGG8 | 6V40019PGG8 |
| 5T9304EJGI | 5V50015PGG | 6P40097PGG | 6V40021PGGI |
| 5T9304EJGI8 | 5V50015PGG8 | 6P40097PGG8 | 6V40021PGGI8 |
| 5T9304EJI | 5V5216PGGI | 6P40098PGG | 6V40031PGGI |
| 5T9304EJI8 | 5V5216PGGI8 | 6P40098PGG8 | 6V40031PGGI8 |
| 5T9304PG | 5V5218PGGI | 6T40059PGG | 6V40033PGGI |
| 5T9304PG8 | 5V5218PGGI8 | 6T40059PGG8 | 6V40033PGGI8 |



Integrated Device Technology, Inc.
6024 Silver Creek Valley Road, San Jose, CA 95138

PRODUCT/PROCESS CHANGE NOTICE (PCN)

ATTACHMENT 2 - PCN #: TB0910-01R1

Affected Part Number

| Part Number | Part Number | Part Number | Part Number |
|---------------|-----------------|-----------------|----------------|
| 6V40033PGGW3 | 74CBTLV3125PGG | 74CBTLV6800QG | 74FCT244ATQG |
| 6V40033PGGW38 | 74CBTLV3125PGG8 | 74CBTLV6800QG8 | 74FCT244ATQG8 |
| 6V40036PGGI | 74CBTLV3125QG | 74FCT157ATQG | 74FCT244CTPGG |
| 6V40036PGGI8 | 74CBTLV3125QG8 | 74FCT157ATQG8 | 74FCT244CTPGG8 |
| 6V40043PGG | 74CBTLV3126PGG | 74FCT157CTQG | 74FCT244CTPYG |
| 6V40043PGG8 | 74CBTLV3126PGG8 | 74FCT157CTQG8 | 74FCT244CTPYG8 |
| 6V40046APGGI | 74CBTLV3126QG | 74FCT157DTQG | 74FCT244CTQG |
| 6V40046APGGI8 | 74CBTLV3126QG8 | 74FCT157DTQG8 | 74FCT244CTQG8 |
| 6V40046PGGI | 74CBTLV3244PGG | 74FCT20807PYGI | 74FCT245ATPGG |
| 6V40046PGGI8 | 74CBTLV3244PGG8 | 74FCT20807PYGI8 | 74FCT245ATPGG8 |
| 6V40048PGGI | 74CBTLV3244QG | 74FCT20807PYI | 74FCT245ATPYG |
| 6V40048PGGI8 | 74CBTLV3244QG8 | 74FCT20807PYI8 | 74FCT245ATPYG8 |
| 6V40052PGG | 74CBTLV3245PGG | 74FCT20807QGI | 74FCT245ATQG |
| 6V40052PGG8 | 74CBTLV3245PGG8 | 74FCT20807QGI8 | 74FCT245ATQG8 |
| 6V40054PGG | 74CBTLV3245QG | 74FCT20807QI | 74FCT245CTPGG |
| 6V40054PGG8 | 74CBTLV3245QG8 | 74FCT20807QI8 | 74FCT245CTPGG8 |
| 6V40056PGGI | 74CBTLV3251PGG | 74FCT2244ATQG | 74FCT245CTPYG |
| 6V40056PGGI8 | 74CBTLV3251PGG8 | 74FCT2244ATQG8 | 74FCT245CTPYG8 |
| 6V40058PGG | 74CBTLV3251QG | 74FCT2244CTQG | 74FCT245CTQG |
| 6V40058PGG8 | 74CBTLV3251QG8 | 74FCT2244CTQG8 | 74FCT245CTQG8 |
| 6V40074PGGI | 74CBTLV3253PGG | 74FCT2245ATQG | 74FCT257ATQG |
| 6V40074PGGI8 | 74CBTLV3253PGG8 | 74FCT2245ATQG8 | 74FCT257ATQG8 |
| 6V40096PGG | 74CBTLV3253QG | 74FCT2245CTQG | 74FCT257CTQG |
| 6V40096PGG8 | 74CBTLV3253QG8 | 74FCT2245CTQG8 | 74FCT257CTQG8 |
| 6V40105PGGI | 74CBTLV3257PGG | 74FCT2373ATQG | 74FCT257DTQG |
| 6V40105PGGI8 | 74CBTLV3257PGG8 | 74FCT2373ATQG8 | 74FCT257DTQG8 |
| 6V40107PGGW3 | 74CBTLV3257QG | 74FCT2373CTQG | 74FCT3244APGG |
| 6V40107PGGW38 | 74CBTLV3257QG8 | 74FCT2373CTQG8 | 74FCT3244APGG8 |
| 6V40112PGG | 74CBTLV3384PGG | 74FCT2374ATQG | 74FCT3244APYG |
| 6V40112PGG8 | 74CBTLV3384PGG8 | 74FCT2374ATQG8 | 74FCT3244APYG8 |
| 6V40113PGG | 74CBTLV3384QG | 74FCT2374CTQG | 74FCT3244AQQ |
| 6V40113PGG8 | 74CBTLV3384QG8 | 74FCT2374CTQG8 | 74FCT3244AQQ8 |
| 6V40114PGG | 74CBTLV3861PGG | 74FCT240ATPYG | 74FCT3244PGG |
| 6V40114PGG8 | 74CBTLV3861PGG8 | 74FCT240ATPYG8 | 74FCT3244PGG8 |
| 6V40120PGG | 74CBTLV3861QG | 74FCT240ATQG | 74FCT3244PYG |
| 6V40120PGG8 | 74CBTLV3861QG8 | 74FCT240ATQG8 | 74FCT3244PYG8 |
| 6V49108PGGI | 74CBTLV3862PGG | 74FCT240CTPYG | 74FCT3244QG |
| 6V49108PGGI8 | 74CBTLV3862PGG8 | 74FCT240CTPYG8 | 74FCT3244QG8 |
| 6V50006PGG | 74CBTLV3862PYG | 74FCT240CTQG | 74FCT3245APGG |
| 6V50006PGG8 | 74CBTLV3862PYG8 | 74FCT240CTQG8 | 74FCT3245APGG8 |
| 6V50007PGG | 74CBTLV3862QG | 74FCT244ATPGG | 74FCT3245AQQ |
| 6V50007PGG8 | 74CBTLV3862QG8 | 74FCT244ATPGG8 | 74FCT3245AQQ8 |
| 6V50008PGG | 74CBTLV6800PGG | 74FCT244ATPYG | 74FCT3245PGG |
| 6V50008PGG8 | 74CBTLV6800PGG8 | 74FCT244ATPYG8 | 74FCT3245PGG8 |



Integrated Device Technology, Inc.
6024 Silver Creek Valley Road, San Jose, CA 95138

PRODUCT/PROCESS CHANGE NOTICE (PCN)

ATTACHMENT 2 - PCN #: TB0910-01R1

Affected Part Number

| Part Number | Part Number | Part Number | Part Number |
|-----------------|-----------------|--------------------|-----------------|
| 74FCT3245QG | 74FCT3807AQI8 | 74FCT3811PYI8 | 74FCT574ATQG8 |
| 74FCT3245QG8 | 74FCT3807DPGGI | 74FCT388915T100PY | 74FCT574CTQG |
| 74FCT3573AQQ | 74FCT3807DPGGI8 | 74FCT388915T100PY8 | 74FCT574CTQG8 |
| 74FCT3573AQQ8 | 74FCT3807DPGI | 74FCT388915T133PY | 74FCT807BTPY |
| 74FCT3573QG | 74FCT3807DPGI8 | 74FCT388915T133PY8 | 74FCT807BTPY8 |
| 74FCT3573QG8 | 74FCT3807DPYGI | 74FCT388915T150PY | 74FCT807BTPYG |
| 74FCT373ATPYG | 74FCT3807DPYGI8 | 74FCT388915T150PY8 | 74FCT807BTPYG8 |
| 74FCT373ATPYG8 | 74FCT3807DPYI | 74FCT388915T70PY | 74FCT807BTPYGI |
| 74FCT373ATQG | 74FCT3807DPYI8 | 74FCT388915T70PY8 | 74FCT807BTPYGI8 |
| 74FCT373ATQG8 | 74FCT3807DQGI | 74FCT388915TBPYG | 74FCT807BTPYI |
| 74FCT373CTPYG | 74FCT3807DQGI8 | 74FCT388915TBPYG8 | 74FCT807BTPYI8 |
| 74FCT373CTPYG8 | 74FCT3807DQI | 74FCT388915TCPYG | 74FCT807BTQ |
| 74FCT373CTQG | 74FCT3807DQI8 | 74FCT388915TCPYG8 | 74FCT807BTQ8 |
| 74FCT373CTQG8 | 74FCT3807EPGGI | 74FCT388915TDPYG | 74FCT807BTQG |
| 74FCT374ATPYG | 74FCT3807EPGGI8 | 74FCT388915TDPYG8 | 74FCT807BTQG8 |
| 74FCT374ATPYG8 | 74FCT3807EPGI | 74FCT388915TEPYG | 74FCT807BTQGI |
| 74FCT374ATQG | 74FCT3807EPGI8 | 74FCT388915TEPYG8 | 74FCT807BTQGI8 |
| 74FCT374ATQG8 | 74FCT3807EPYGI | 74FCT521ATPYG | 74FCT807BTQI |
| 74FCT374CTPYG | 74FCT3807EPYGI8 | 74FCT521ATPYG8 | 74FCT807BTQI8 |
| 74FCT374CTPYG8 | 74FCT3807EPYI | 74FCT521ATQG | 74FCT807CTPY |
| 74FCT374CTQG | 74FCT3807EPYI8 | 74FCT521ATQG8 | 74FCT807CTPY8 |
| 74FCT374CTQG8 | 74FCT3807EQGI | 74FCT521CTPYG | 74FCT807CTPYG |
| 74FCT377ATQG | 74FCT3807EQGI8 | 74FCT521CTPYG8 | 74FCT807CTPYG8 |
| 74FCT377ATQG8 | 74FCT3807EQI | 74FCT521CTQG | 74FCT807CTPYGI |
| 74FCT377CTQG | 74FCT3807EQI8 | 74FCT521CTQG8 | 74FCT807CTPYGI8 |
| 74FCT377CTQG8 | 74FCT3807PY | 74FCT540ATPYG | 74FCT807CTPYI |
| 74FCT377DTQG | 74FCT3807PY8 | 74FCT540ATPYG8 | 74FCT807CTPYI8 |
| 74FCT377DTQG8 | 74FCT3807PYG | 74FCT540ATQG | 74FCT807CTQ |
| 74FCT3807APY | 74FCT3807PYG8 | 74FCT540ATQG8 | 74FCT807CTQ8 |
| 74FCT3807APY8 | 74FCT3807PYGI | 74FCT540CTPYG | 74FCT807CTQG |
| 74FCT3807APY8/C | 74FCT3807PYGI8 | 74FCT540CTPYG8 | 74FCT807CTQG8 |
| 74FCT3807APYG | 74FCT3807PYI | 74FCT540CTQG | 74FCT807CTQGI |
| 74FCT3807APYG8 | 74FCT3807PYI8 | 74FCT540CTQG8 | 74FCT807CTQGI8 |
| 74FCT3807APYGI | 74FCT3807Q | 74FCT543ATQG | 74FCT807CTQI |
| 74FCT3807APYGI8 | 74FCT3807Q8 | 74FCT543ATQG8 | 74FCT807CTQI8 |
| 74FCT3807APYI | 74FCT3807QG | 74FCT543CTQG | 74FCT810BTPY |
| 74FCT3807APYI8 | 74FCT3807QG8 | 74FCT543CTQG8 | 74FCT810BTPY8 |
| 74FCT3807AQ | 74FCT3807QGI | 74FCT543DTQG | 74FCT810BTPYG |
| 74FCT3807AQ8 | 74FCT3807QGI8 | 74FCT543DTQG8 | 74FCT810BTPYG8 |
| 74FCT3807AQQ | 74FCT3807QI | 74FCT573ATQG | 74FCT810BTQ |
| 74FCT3807AQQ8 | 74FCT3807QI8 | 74FCT573ATQG8 | 74FCT810BTQ8 |
| 74FCT3807AQQI | 74FCT3811PYGI | 74FCT573CTQG | 74FCT810BTQG |
| 74FCT3807AQQI8 | 74FCT3811PYGI8 | 74FCT573CTQG8 | 74FCT810BTQG8 |
| 74FCT3807AQI | 74FCT3811PYI | 74FCT574ATQG | 74FCT810CTPY |



Integrated Device Technology, Inc.
6024 Silver Creek Valley Road, San Jose, CA 95138

PRODUCT/PROCESS CHANGE NOTICE (PCN)

ATTACHMENT 2 - PCN #: TB0910-01R1

Affected Part Number

| Part Number | Part Number | Part Number | Part Number |
|--------------------|-----------------|-----------------|------------------|
| 74FCT810CTPY8 | 74LVC273APGG8 | CSPT855PG8 | MC100ES6130EJR2 |
| 74FCT810CTPYG | 74LVC4245APGG | CSPT855PGG | MC100ES6139DT |
| 74FCT810CTPYG8 | 74LVC4245APGG8 | CSPT855PGG8 | MC100ES6139DTR2 |
| 74FCT810CTQ | 74LVC4245APYG | CSPT855PGGI | MC100ES6139EJ |
| 74FCT810CTQ8 | 74LVC4245APYG8 | CSPT855PGGI8 | MC100ES6139EJR2 |
| 74FCT810CTQG | 74LVC4245AQG | CSPT855PGI | MC100ES6535DT |
| 74FCT810CTQG8 | 74LVC4245AQG8 | CSPT855PGI8 | MC100ES6535DTR2 |
| 74FCT823ATQG | 74LVC541AQG | CV112-3PGG | MC100ES6535EJ |
| 74FCT823ATQG8 | 74LVC541AQG8 | CV112-3PGG8 | MC100ES6535EJR2 |
| 74FCT823CTQG | 74LVCC3245APGG | CV143PY | MPC905D |
| 74FCT823CTQG8 | 74LVCC3245APGG8 | CV143PY8 | MPC905DR2 |
| 74FCT88915TT100PY | 85304-01PG | CV143PYG | MPC905EF |
| 74FCT88915TT100PY8 | 85304-01PG8 | CV143PYG8 | MPC905EFR2 |
| 74FCT88915TT133PY | 85304-01PGG | LDS6000PYGI | MPC962305DT-1H |
| 74FCT88915TT133PY8 | 85304-01PGG8 | LDS6000PYGI8 | MPC962305DT-1HR2 |
| 74FCT88915TT55PY | 85304-01PGGI | LDS6003PYGI | MPC962305EJ-1H |
| 74FCT88915TT55PY8 | 85304-01PGGI8 | LDS6003PYGI8 | MPC962305EJ-1HR2 |
| 74FCT88915TT70PY | 85304-01PGI | LDS6005PYGI | MPC962308D-1H |
| 74FCT88915TT70PY8 | 85304-01PGI8 | LDS6005PYGI8 | MPC962308D-1HR2 |
| 74FCT88915TTAPYG | 8535-01PG | LDS6020PYGI | MPC962308DT-1H |
| 74FCT88915TTAPYG8 | 8535-01PG8 | LDS6020PYGI8 | MPC962308DT-1HR2 |
| 74FCT88915TTBPYG | 8535-01PGG | LDS6023PYGI | MPC962308EF-1H |
| 74FCT88915TTBPYG8 | 8535-01PGG8 | LDS6023PYGI8 | MPC962308EF-1HR2 |
| 74FCT88915TTCPYG | 8535-01PGGI | LDS6025PYGI | MPC962308EJ-1H |
| 74FCT88915TTCPYG8 | 8535-01PGGI8 | LDS6025PYGI8 | MPC962308EJ-1HR2 |
| 74FCT88915TTDPYG | 8535-01PGI | LDS6104PYGI | MPC962309D-1 |
| 74FCT88915TTDPYG8 | 8535-01PGI8 | LDS6104PYGI8 | MPC962309D-1H |
| 74FST6800PGG | 8737-11PGG | LDS6107PYGI | MPC962309D-1HR2 |
| 74FST6800PGG8 | 8737-11PGG8 | LDS6107PYGI8 | MPC962309D-1R2 |
| 74FST6800QGG | CSP2510CPG | LDS6124PYGI | MPC962309DT-1H |
| 74FST6800QGG8 | CSP2510CPG8 | LDS6124PYGI8 | MPC962309DT-1HR2 |
| 74LVC244APGG | CSP2510CPGG | LDS6126PYGI | MPC962309EF-1H |
| 74LVC244APGG8 | CSP2510CPGG8 | LDS6126PYGI8 | MPC962309EF-1HR2 |
| 74LVC244APYG | CSP2510CPGI | MC100ES6014DT | MPC962309EJ-1H |
| 74LVC244APYG8 | CSP2510CPGI8 | MC100ES6014DTR2 | MPC962309EJ-1HR2 |
| 74LVC244AQQ | CSP2510DPG | MC100ES6014EJ | MPC9817EN |
| 74LVC244AQQ8 | CSP2510DPG8 | MC100ES6014EJR2 | MPC9817ENR2 |
| 74LVC245APGG | CSP2510DPGG | MC100ES6056DT | MPC9817SD |
| 74LVC245APGG8 | CSP2510DPGG8 | MC100ES6056DTR2 | MPC9817SDR2 |
| 74LVC245APYG | CSP2510DPGGI | MC100ES6056EJ | MPC9819EN |
| 74LVC245APYG8 | CSP2510DPGGI8 | MC100ES6056EJR2 | MPC9819ENR2 |
| 74LVC245AQQ | CSP2510DPGI | MC100ES6130DT | MPC9819SD |
| 74LVC245AQQ8 | CSP2510DPGI8 | MC100ES6130DTR2 | MPC9819SDR2 |
| 74LVC273APGG | CSPT855PG | MC100ES6130EJ | QS3125QG |



Integrated Device Technology, Inc.
6024 Silver Creek Valley Road, San Jose, CA 95138

PRODUCT/PROCESS CHANGE NOTICE (PCN)

ATTACHMENT 2 - PCN #: TB0910-01R1

Affected Part Number

| Part Number | Part Number | Part Number | Part Number |
|----------------|-----------------|---------------|-----------------|
| QS3125QG8 | QS32XVH2245Q2G8 | QS3VH2245PAG8 | QS4A110QG8 |
| QS3125S1G | QS32XVH245Q2G | QS3VH2245QG | QS4A201QG |
| QS3125S1G8 | QS32XVH245Q2G8 | QS3VH2245QG8 | QS4A201QG8 |
| QS3126QG | QS32XVH384Q1G | QS3VH244PAG | QS4A205QG |
| QS3126QG8 | QS32XVH384Q1G8 | QS3VH244PAG8 | QS4A205QG8 |
| QS3126S1G | QS3383QG | QS3VH244QG | QS4A210QG |
| QS3126S1G8 | QS3383QG8 | QS3VH244QG8 | QS4A210QG8 |
| QS32245PAG | QS3384PAG | QS3VH245PAG | QS4A215Q1G |
| QS32245PAG8 | QS3384PAG8 | QS3VH245PAG8 | QS4A215Q1G8 |
| QS32245QG | QS3384QG | QS3VH245QG | QS5917T-100TQ |
| QS32245QG8 | QS3384QG8 | QS3VH245QG8 | QS5917T-100TQ8 |
| QS32390QG | QS3390QG | QS3VH251PAG | QS5917T-100TQG |
| QS32390QG8 | QS3390QG8 | QS3VH251PAG8 | QS5917T-100TQG8 |
| QS3244PAG | QS33X257Q1G | QS3VH251QG | QS5917T-132TQ |
| QS3244PAG8 | QS33X257Q1G8 | QS3VH251QG8 | QS5917T-132TQ8 |
| QS3244QG | QS34X2245Q3G | QS3VH253PAG | QS5917T-132TQG |
| QS3244QG8 | QS34X2245Q3G8 | QS3VH253PAG8 | QS5917T-132TQG8 |
| QS3245QG | QS34X245Q3G | QS3VH253QG | QS5917T-70TQ |
| QS3245QG8 | QS34X245Q3G8 | QS3VH253QG8 | QS5917T-70TQ8 |
| QS3251QG | QS34X383Q3G | QS3VH257PAG | QS5917T-70TQG |
| QS3251QG8 | QS34X383Q3G8 | QS3VH257PAG8 | QS5917T-70TQG8 |
| QS3251S1G | QS34XVH2245Q3G | QS3VH257QG | QS5930-50TQ |
| QS3251S1G8 | QS34XVH2245Q3G8 | QS3VH257QG8 | QS5930-50TQ8 |
| QS3253QG | QS34XVH245Q3G | QS3VH257S1G | QS5930-66TQ |
| QS3253QG8 | QS34XVH245Q3G8 | QS3VH257S1G8 | QS5930-66TQ8 |
| QS3253S1G | QS3800QG | QS3VH2861QG | QS5LV919-100QG |
| QS3253S1G8 | QS3800QG8 | QS3VH2861QG8 | QS5LV919-100QG8 |
| QS3257QG | QS3861PAG | QS3VH384PAG | QS5LV919-55Q |
| QS3257QG8 | QS3861PAG8 | QS3VH384PAG8 | QS5LV919-55Q8 |
| QS3257S1G | QS3861QG | QS3VH384QG | QS5LV919-70Q |
| QS3257S1G8 | QS3861QG8 | QS3VH384QG8 | QS5LV919-70Q8 |
| QS32X2245Q2G | QS3L384PAG | QS3VH800PAG | QS5LV931-80QG |
| QS32X2245Q2G8 | QS3L384PAG8 | QS3VH800PAG8 | QS5LV931-80QG8 |
| QS32X2384Q1G | QS3L384QG | QS3VH800QG | VS330DCG |
| QS32X2384Q1G8 | QS3L384QG8 | QS3VH800QG8 | VS330DCG8 |
| QS32X245Q2G | QS3VH125QG | QS3VH861QG | VS330QG |
| QS32X245Q2G8 | QS3VH125QG8 | QS3VH861QG8 | VS330QG8 |
| QS32X384Q1G | QS3VH125S1G | QS3VH862QG | VS512QG |
| QS32X384Q1G8 | QS3VH125S1G8 | QS3VH862QG8 | VS512QG8 |
| QS32X861Q1G | QS3VH126QG | QS4A101QG | |
| QS32X861Q1G8 | QS3VH126QG8 | QS4A101QG8 | |
| QS32XL384Q1G | QS3VH126S1G | QS4A105QG | |
| QS32XL384Q1G8 | QS3VH126S1G8 | QS4A105QG8 | |
| QS32XVH2245Q2G | QS3VH2245PAG | QS4A110QG | |



Integrated Device Technology, Inc.
6024 Silver Creek Valley Road, San Jose, CA 95138

PRODUCT/PROCESS CHANGE NOTICE (PCN)

PCN #: **TB0910-01**

DATE: **15-Nov-2009**

Product Affected: IDT selective Plastic packages -
QVSOP, SSOP, TSSOP, QSOP

Date Effective: **15-Feb-2010**

MEANS OF DISTINGUISHING CHANGED DEVICES:

- Product Mark
- Back Mark
- Date Code
- Other Shipment starting from 15-Feb-2010

Contact: Geoffrey Cortes

Title: Product Quality

Phone #: (408) 284-8321

Fax #: (408) 284-1450

E-mail: Geoffrey.Cortes@idt.com

Attachment: Yes No

Samples: Contact your local IDT sales representative for sample requests.

DESCRIPTION AND PURPOSE OF CHANGE:

- Die Technology
- Wafer Fabrication Process
- Assembly Process
- Equipment
- Material
- Testing
- Manufacturing Site
- Data Sheet
- Other - Product Top Mark

This notification is to advise our customers that IDT will convert lot traceability mark from the bottom of the package to the top of the package to facilitate lot traceability after board mount. This change is for a select group of products that were not previously converted to top mark traceability.

During the transition, shipments to customers may contain products with lot traceability mark on either the top or bottom of the package until old inventory has been depleted.

Attachment 1: Illustrates the location of the lot traceability mark on top of the package for all the affected package families.

Attachment 2: List of the affected part numbers.

RELIABILITY/QUALIFICATION SUMMARY:

Not applicable.

CUSTOMER ACKNOWLEDGMENT OF RECEIPT:

IDT records indicate that you require written notification of this change. Please use the acknowledgement below or E-Mail to grant approval or request additional information. If IDT does not receive acknowledgement within 30 days of this notice it will be assumed that this change is acceptable.

IDT reserves the right to ship either version manufactured after the process change effective date until the inventory on the earlier version has been depleted.

Customer: _____

Approval for shipments prior to effective date.

Name/Date: _____

E-Mail Address: _____

Title: _____

Phone # /Fax #: _____

CUSTOMER COMMENTS: _____

IDT ACKNOWLEDGMENT OF RECEIPT:


RECD. BY: _____

DATE: _____

ATTACHMENT 1 - PCN # : TB0910-01

POSITION OF THE TRACEABILITY MARK

- i) SSOP (DC/DCG 14/16, PY/PYG-all lead counts)
- ii) QVSOP (DJ/DJG 48, DM/DMG 40/80)
- iii) TSSOP (EJ/EJG 20/24, EN/ENG 16, PG/PGG-all lead counts)
- iv) QSOP (PC/PCG-all lead counts)



AAAANNNNSS OOO xy - Lot Traceability Mark

Note: Pin 1 indicator could be in the form of:

- i) Package dimple or
- ii) Laser dot or
- iii) Laser dot on top of the dimple if the dimple is not visible clearly by human eyes or vision inspection system

ATTACHMENT 2 - PCN #: TB0910-01
Affected Part Number

| Part Number | Part Number | Part Number | Part Number |
|-----------------|---------------|---------------|---------------|
| 1491AF-10LF | 2304NZG-1LF | 2308-2HPGGI | 2308A-1HPGI8 |
| 1491AF-10LFT | 2304NZG-1LFT | 2308-2HPGGI8 | 2308A-2DC |
| 1491F-10LF | 2304NZG-1T | 2308-3DC | 2308A-2DC8 |
| 1491F-10LFT | 2304NZGI-1 | 2308-3DC8 | 2308A-2DCG |
| 1493AGI-19 | 2304NZGI-1LF | 2308-3DCG | 2308A-2DCG8 |
| 1493AGI-19LF | 2304NZGI-1LFT | 2308-3DCG8 | 2308A-2DCGI |
| 1493AGI-19LFT | 2304NZGI-1T | 2308-3DCGI | 2308A-2DCGI8 |
| 1493AGI-19T | 2305-1PGG | 2308-3DCGI8 | 2308A-2DCI |
| 1493GI-19 | 2305-1PGG8 | 2308-3DCI | 2308A-2DCI8 |
| 1493GI-19LF | 2305B-1PGG | 2308-3DCI8 | 2308A-2HDC |
| 1493GI-19LFT | 2305B-1PGG8 | 2308-4DC | 2308A-2HDC8 |
| 1493GI-19T | 2305B-1PGGI | 2308-4DC8 | 2308A-2HDCG |
| 1526G | 2305B-1PGGI8 | 2308-4DCG | 2308A-2HDCG8 |
| 1526GILF | 2308-1DC | 2308-4DCG8 | 2308A-2HDCI |
| 1526GILFT | 2308-1DC8 | 2308-4DCGI | 2308A-2HDCI8 |
| 1526GLF | 2308-1DCG | 2308-4DCGI8 | 2308A-3DC |
| 1526GLFT | 2308-1DCG8 | 2308-4DCI | 2308A-3DC8 |
| 1526GT | 2308-1DCGI | 2308-4DCI8 | 2308A-3DCG |
| 1527G-110 | 2308-1DCGI8 | 2308-5HDC | 2308A-3DCG8 |
| 1527G-110LF | 2308-1DCI | 2308-5HDC8 | 2308A-3DCGI |
| 1527G-110LFT | 2308-1DCI8 | 2308-5HDCG | 2308A-3DCGI8 |
| 1527G-110T | 2308-1HDC | 2308-5HDCG8 | 2308A-3DCI |
| 1562AM-201 | 2308-1HDC8 | 2308-5HDCGI | 2308A-3DCI8 |
| 1562AM-201T | 2308-1HDCG | 2308-5HDCGI8 | 2308A-4DC |
| 1562BM-001 | 2308-1HDCG8 | 2308-5HDCI | 2308A-4DC8 |
| 1562BM-001T | 2308-1HDCGI | 2308-5HDCI8 | 2308A-4DCG |
| 1562BM-201 | 2308-1HDCGI8 | 2308-5HPG | 2308A-4DCG8 |
| 1562BM-201-4 | 2308-1HDCI | 2308-5HPG8 | 2308A-4DCGI |
| 1562BM-201-4LF | 2308-1HDCI8 | 2308-5HPGG | 2308A-4DCGI8 |
| 1562BM-201-4LFT | 2308-1HPG | 2308-5HPGG8 | 2308A-4DCI |
| 1562BM-201LF | 2308-1HPG8 | 2308-5HPGGI | 2308A-4DCI8 |
| 1562BM-201LFT | 2308-1HPGG | 2308-5HPGGI8 | 2308A-5HPGG |
| 1562BM-201T | 2308-1HPGG8 | 2308-5HPGI | 2308A-5HPGG8 |
| 1574BM | 2308-1HPGGI | 2308-5HPGI8 | 2308B-1DC |
| 1574BMLF | 2308-1HPGGI8 | 2308A-1DC | 2308B-1DC8 |
| 1574BMLFT | 2308-1HPGI | 2308A-1DC8 | 2308B-1DCG |
| 1574BMT | 2308-1HPGI8 | 2308A-1DCG | 2308B-1DCG8 |
| 1574M | 2308-2DC | 2308A-1DCG8 | 2308B-1DCGI |
| 1574MT | 2308-2DC8 | 2308A-1DCGI | 2308B-1DCGI8 |
| 1574MT-IB0 | 2308-2DCG | 2308A-1DCGI8 | 2308B-1DCI |
| 1726G-13LF | 2308-2DCG8 | 2308A-1DCI | 2308B-1DCI8 |
| 1726G-13LFT | 2308-2DCGI | 2308A-1DCI8 | 2308B-1HDC |
| 1726G-16LF | 2308-2DCGI8 | 2308A-1HDCG | 2308B-1HDC8 |
| 1726G-16LFT | 2308-2DCI | 2308A-1HDCG8 | 2308B-1HDCG |
| 1726GI-16LF | 2308-2DCI8 | 2308A-1HDCGI | 2308B-1HDCG8 |
| 1726GI-16LFT | 2308-2HDC | 2308A-1HDCGI8 | 2308B-1HDCGI |
| 1727G-05LF | 2308-2HDC8 | 2308A-1HDCI | 2308B-1HDCGI8 |
| 1727G-05LFT | 2308-2HDCG | 2308A-1HDCI8 | 2308B-1HDCI |
| 1727GI-05LF | 2308-2HDCG8 | 2308A-1HPG | 2308B-1HDCI8 |
| 1727GI-05LFT | 2308-2HDCGI | 2308A-1HPG8 | 2308B-1HPG |
| 2059GI-02 | 2308-2HDCGI8 | 2308A-1HPGG | 2308B-1HPG8 |
| 2059GI-02LF | 2308-2HDCI | 2308A-1HPGG8 | 2308B-1HPGG |
| 2059GI-02LFT | 2308-2HDCI8 | 2308A-1HPGGI | 2308B-1HPGG8 |
| 2059GI-02T | 2308-2HPGG | 2308A-1HPGGI8 | 2308B-1HPGGI |
| 2304NZG-1 | 2308-2HPGG8 | 2308A-1HPGI | 2308B-1HPGGI8 |

ATTACHMENT 2 - PCN #: TB0910-01
Affected Part Number

| Part Number | Part Number | Part Number | Part Number |
|--------------|----------------|---------------|----------------|
| 2308B-1HPGI | 2309A-1HDC8 | 23S08-1DC | 23S08E-1DC8 |
| 2308B-1HPGI8 | 2309A-1HDCG | 23S08-1DC8 | 23S08E-1DCG |
| 2308B-2DC | 2309A-1HDCG8 | 23S08-1DCG | 23S08E-1DCG8 |
| 2308B-2DC8 | 2309A-1HDCI | 23S08-1DCG8 | 23S08E-1DCGI |
| 2308B-2DCG | 2309A-1HDCI8 | 23S08-1DCGI | 23S08E-1DCGI8 |
| 2308B-2DCG8 | 2309A-1HPG | 23S08-1DCGI8 | 23S08E-1DCI |
| 2308B-2DCGI | 2309A-1HPG8 | 23S08-1DCI | 23S08E-1DCI8 |
| 2308B-2DCGI8 | 2309A-1HPGG | 23S08-1DCI8 | 23S08E-1HDC |
| 2308B-2DCI | 2309A-1HPGG8 | 23S08-1HDC | 23S08E-1HDC8 |
| 2308B-2DCI8 | 2309A-1HPGGI | 23S08-1HDC8 | 23S08E-1HDCG |
| 2308B-3DC | 2309A-1HPGGI8 | 23S08-1HDCG | 23S08E-1HDCG8 |
| 2308B-3DC8 | 2309A-1HPGI | 23S08-1HDCG8 | 23S08E-1HDCGI |
| 2308B-3DCG | 2309A-1HPGI8 | 23S08-1HDCGI | 23S08E-1HDCGI8 |
| 2308B-3DCG8 | 2309B-1DC | 23S08-1HDCGI8 | 23S08E-1HDCI |
| 2308B-4DC | 2309B-1DC8 | 23S08-1HDCI | 23S08E-1HDCI8 |
| 2308B-4DC8 | 2309B-1DCG | 23S08-1HDCI8 | 23S08E-1HPG |
| 2308B-4DCG | 2309B-1DCG8 | 23S08-1HPGG | 23S08E-1HPG8 |
| 2308B-4DCG8 | 2309B-1DCI | 23S08-1HPGG8 | 23S08E-1HPGG |
| 2308B-4DCI | 2309B-1DCI8 | 23S08-1HPGGI | 23S08E-1HPGG8 |
| 2308B-4DCI8 | 2309B-1HDC | 23S08-1HPGGI8 | 23S08E-1HPGGI |
| 2308B-5HPG | 2309B-1HDC8 | 23S08-2DC | 23S08E-1HPGGI8 |
| 2308B-5HPG8 | 2309B-1HDCG | 23S08-2DC8 | 23S08E-2DC |
| 2309-1DC | 2309B-1HDCG8 | 23S08-2DCG | 23S08E-2DC8 |
| 2309-1DC8 | 2309B-1HDCGI | 23S08-2DCG8 | 23S08E-2DCG |
| 2309-1DCG | 2309B-1HDCGI8 | 23S08-2DCGI | 23S08E-2DCG8 |
| 2309-1DCG8 | 2309B-1HDCI | 23S08-2DCGI8 | 23S08E-2DCGI |
| 2309-1DCGI | 2309B-1HDCI8 | 23S08-2DCI | 23S08E-2DCGI8 |
| 2309-1DCGI8 | 2309B-1HPG | 23S08-2DCI8 | 23S08E-2DCI |
| 2309-1DCI | 2309B-1HPG8 | 23S08-2HDC | 23S08E-2DCI8 |
| 2309-1DCI8 | 2309B-1HPGG | 23S08-2HDC8 | 23S08E-2HDCG |
| 2309-1HDC | 2309B-1HPGG8 | 23S08-2HDCG | 23S08E-2HDCG8 |
| 2309-1HDC8 | 2309B-1HPGGI | 23S08-2HDCG8 | 23S08E-2HDCGI |
| 2309-1HDCG | 2309B-1HPGGI8 | 23S08-2HDCGI | 23S08E-2HDCGI8 |
| 2309-1HDCG8 | 2309B-1HPGI | 23S08-2HDCGI8 | 23S08E-3DC |
| 2309-1HDCGI | 2309B-1HPGI8 | 23S08-3DC | 23S08E-3DC8 |
| 2309-1HDCGI8 | 2309M-1 | 23S08-3DC8 | 23S08E-3DCG |
| 2309-1HDCI | 2309M-1T | 23S08-3DCG | 23S08E-3DCG8 |
| 2309-1HDCI8 | 2309MI-1 | 23S08-3DCG8 | 23S08E-3DCGI |
| 2309-1HPG | 2309MI-1T | 23S08-3DCGI | 23S08E-3DCGI8 |
| 2309-1HPG8 | 2309NZ-1HDC | 23S08-3DCGI8 | 23S08E-3DCI |
| 2309-1HPGG | 2309NZ-1HDC8 | 23S08-4DCG | 23S08E-3DCI8 |
| 2309-1HPGG8 | 2309NZ-1HDCG | 23S08-4DCG8 | 23S08E-4DC |
| 2309-1HPGGI | 2309NZ-1HDCG8 | 23S08-4DCGI | 23S08E-4DC8 |
| 2309-1HPGGI8 | 2309NZ-1HDCGI | 23S08-4DCGI8 | 23S08E-4DCG |
| 2309-1HPGI | 2309NZ-1HDCGI8 | 23S08-4DCI | 23S08E-4DCG8 |
| 2309-1HPGI8 | 2309NZ-1HDCI | 23S08-4DCI8 | 23S08E-4DCGI |
| 2309A-1DC | 2309NZ-1HDCI8 | 23S08-5HDC | 23S08E-4DCGI8 |
| 2309A-1DC8 | 2309NZ-1HPG | 23S08-5HDC8 | 23S08E-5HDC |
| 2309A-1DCG | 2309NZ-1HPG8 | 23S08-5HDCG | 23S08E-5HDC8 |
| 2309A-1DCG8 | 2309NZ-1HPGG | 23S08-5HDCG8 | 23S08E-5HDCG |
| 2309A-1DCGI | 2309NZ-1HPGG8 | 23S08-5HDCGI | 23S08E-5HDCG8 |
| 2309A-1DCGI8 | 2309NZ-1HPGGI | 23S08-5HDCGI8 | 23S08E-5HDCGI |
| 2309A-1DCI | 2309NZ-1HPGGI8 | 23S08-5HPGG | 23S08E-5HDCGI8 |
| 2309A-1DCI8 | 2309NZ-1HPGI | 23S08-5HPGG8 | 23S08E-5HPGI |
| 2309A-1HDC | 2309NZ-1HPGI8 | 23S08E-1DC | 23S08E-5HPGI8 |

ATTACHMENT 2 - PCN #: TB0910-01
Affected Part Number

| Part Number | Part Number | Part Number | Part Number |
|----------------|-------------|-------------|-------------|
| 23S08T-1DCG | 270PGI | 280G-02LFT | 281PGILFT |
| 23S08T-1DCG8 | 270PGILF | 280G-02T | 281PGIT |
| 23S09-1DC | 270PGILFT | 280G-11LF | 281PGLF |
| 23S09-1DC8 | 270PGIT | 280G-11LFT | 281PGLFT |
| 23S09-1DCG | 270PGLF | 280G-13 | 281PGT |
| 23S09-1DCG8 | 270PGLFT | 280G-13LF | 290G-05LF |
| 23S09-1DCGI | 270PGT | 280G-13LFT | 290G-05LFT |
| 23S09-1DCGI8 | 271PG | 280G-13T | 290G-14LF |
| 23S09-1HDC | 271PGI | 280G-25LF | 290G-14LFT |
| 23S09-1HDC8 | 271PGILF | 280G-25LFT | 290G-18LF |
| 23S09-1HDCG | 271PGILFT | 280G-30LF | 290G-18LFT |
| 23S09-1HDCG8 | 271PGIT | 280G-30LFT | 290G-19LF |
| 23S09-1HDCGI | 271PGLF | 280G-35LF | 290G-19LFT |
| 23S09-1HDCGI8 | 271PGLFT | 280G-35LFT | 290G-22LF |
| 23S09-1HPG | 271PGT | 280G-36LF | 290G-22LFT |
| 23S09-1HPG8 | 275G-01 | 280G-36LFT | 290G-23LF |
| 23S09-1HPGG | 275G-01LF | 280G-37LF | 290G-23LFT |
| 23S09-1HPGG8 | 275G-01LFT | 280G-37LFT | 290G-24LF |
| 23S09-1HPGGI | 275G-01T | 280G-38LF | 290G-24LFT |
| 23S09-1HPGGI8 | 275G-03LF | 280G-38LFT | 290G-26LF |
| 23S09E-1DC | 275G-03LFT | 280G-39LF | 290G-26LFT |
| 23S09E-1DC8 | 275G-09LF | 280G-39LFT | 290G-27LF |
| 23S09E-1DCG | 275G-09LFT | 280GI-10LF | 290G-27LFT |
| 23S09E-1DCG8 | 275G-20LF | 280GI-10LFT | 290G-29LF |
| 23S09E-1DCGI | 275G-20LFT | 280GI-11LF | 290G-29LFT |
| 23S09E-1DCGI8 | 275G-22LF | 280GI-11LFT | 290GI-13LF |
| 23S09E-1DCI | 275G-22LFT | 280GI-13 | 290GI-13LFT |
| 23S09E-1DCI8 | 275GI-01 | 280GI-13LF | 290GI-15LF |
| 23S09E-1HDC | 275GI-01LF | 280GI-13LFT | 290GI-15LFT |
| 23S09E-1HDC8 | 275GI-01LFT | 280GI-13T | 290GI-20LF |
| 23S09E-1HDCGI | 275GI-01T | 280GI-29LF | 290GI-20LFT |
| 23S09E-1HDCGI8 | 275GI-09LF | 280GI-29LFT | 290GI-21LF |
| 23S09E-1HDCI | 275GI-09LFT | 280GI-30LF | 290GI-21LFT |
| 23S09E-1HDCI8 | 275GI-13LF | 280GI-30LFT | 290GI-28LF |
| 23S09E-1HPG | 275GI-13LFT | 280GI-33LF | 290GI-28LFT |
| 23S09E-1HPG8 | 275PG | 280GI-33LFT | 290PG |
| 23S09E-1HPGG | 275PGI | 280GI-34LF | 290PGI |
| 23S09E-1HPGG8 | 275PGILF | 280GI-34LFT | 290PGILF |
| 23S09E-1HPGGI | 275PGILFT | 280GI-41LF | 290PGILFT |
| 23S09E-1HPGGI8 | 275PGIT | 280GI-41LFT | 290PGIT |
| 23S09E-1HPGI | 275PGLF | 280PG | 290PGLF |
| 23S09E-1HPGI8 | 275PGLFT | 280PGI | 290PGLFT |
| 23S09T-1DC | 275PGT | 280PGILF | 290PGT |
| 23S09T-1DC8 | 276G-01LF | 280PGILFT | 291G-06LF |
| 23S09T-1DCG | 276G-01LFT | 280PGIT | 291G-06LFT |
| 23S09T-1DCG8 | 276PG | 280PGLF | 291G-07 |
| 2510CG | 276PGI | 280PGLFT | 291G-07LF |
| 2510CGLF | 276PGILF | 280PGT | 291G-07LFT |
| 2510CGLFT | 276PGILFT | 281G-04LF | 291G-07T |
| 2510CGT | 276PGIT | 281G-04LFT | 291G-09LF |
| 25210AG | 276PGLF | 281GI-03LF | 291G-09LFT |
| 25210AGT | 276PGLFT | 281GI-03LFT | 291GI-07LF |
| 270G-01LF | 276PGT | 281PG | 291GI-07LFT |
| 270G-01LFT | 280G-02 | 281PGI | 291PG |
| 270PG | 280G-02LF | 281PGILF | 291PGI |

ATTACHMENT 2 - PCN #: TB0910-01
Affected Part Number

| Part Number | Part Number | Part Number | Part Number |
|-------------|-------------|--------------|-------------|
| 291PGILF | 345R-29LF | 348R-22LFT | 3732G-33LFT |
| 291PGILFT | 345R-29LFT | 348R-29 | 3732R-34LF |
| 291PGIT | 345R-33LF | 348R-29LF | 3732R-34LFT |
| 291PGLF | 345R-33LFT | 348R-29LFT | 3771G-18LF |
| 291PGLFT | 345R-40LF | 348R-29T | 3771G-18LFT |
| 291PGT | 345R-40LFT | 348R-36LF | 377R-05 |
| 307G-03 | 345R-55LF | 348R-36LFT | 377R-05T |
| 307G-03LF | 345R-55LFT | 348R-37LF | 388R-12 |
| 307G-03LFT | 345R-56LF | 348R-37LFT | 388R-12T |
| 307G-03T | 345R-56LFT | 348R-40LF | 403G-03LF |
| 307GI-03LF | 345R-60LF | 348R-40LFT | 403G-03LFT |
| 307GI-03LFT | 345R-60LFT | 348R-43LF | 414G-01 |
| 307M-01 | 345R-63LF | 348R-43LFT | 414G-01LF |
| 307M-01I | 345R-63LFT | 348R-45LF | 414G-01LFT |
| 307M-01IT | 345RI-13 | 348R-45LFT | 414G-01T |
| 307M-01T | 345RI-13LF | 348RI-36LF | 414G-02 |
| 307M-02 | 345RI-13LFT | 348RI-36LFT | 414G-02LF |
| 307M-02I | 345RI-13T | 348RILF | 414G-02LFT |
| 307M-02ILF | 345RI-18LF | 348RILFT | 414G-02T |
| 307M-02ILFT | 345RI-18LFT | 348RIP | 417AG |
| 307M-02IT | 345RI-21 | 348RIPLF | 417AGT |
| 307M-02LF | 345RI-21LF | 348RIPLFT | 420BG |
| 307M-02LFT | 345RI-21LFT | 348RIPT | 420BGT |
| 307M-02T | 345RI-21T | 348RLF | 421AG-05LF |
| 308R | 345RI-40LF | 348RLFT | 421AG-05LFT |
| 308RI | 345RI-40LFT | 348RP | 421AG-07LF |
| 308RILF | 345RIP | 348RPLF | 421AG-07LFT |
| 308RILFT | 345RIPLF | 348RPLFT | 422AG-07LF |
| 308RIT | 345RIPLFT | 348RPT | 422AG-07LFT |
| 308RLF | 345RIPT | 348RT | 422AG-12LF |
| 308RLFT | 345RLF | 354G-11 | 422AG-12LFT |
| 308RT | 345RLFT | 354G-11T | 422BG-07LF |
| 309R | 345RP | 355R-23 | 422BG-07LFT |
| 309RI | 345RPLF | 355R-23LF | 422CG-13LF |
| 309RILF | 345RPLFT | 355R-23LFT | 422CG-13LFT |
| 309RILFT | 345RPT | 355R-23T | 422G-07 |
| 309RIT | 345RT | 355R-26 | 422G-07LF |
| 309RLF | 348R | 355R-26T | 422G-07LFT |
| 309RLFT | 348R-02 | 3725G-01LF | 422G-07T |
| 309RT | 348R-02LF | 3725G-01LFT | 422G-16 |
| 345R | 348R-02LFT | 3732AG-28LF | 422G-16T |
| 345R-07LF | 348R-02T | 3732AG-28LFT | 422G-18LF |
| 345R-07LFT | 348R-10 | 3732AG-31LF | 422G-18LFT |
| 345R-08 | 348R-10LN | 3732AG-31LFT | 422G-19LF |
| 345R-08LF | 348R-10LNT | 3732AG-32LF | 422G-19LFT |
| 345R-08LFT | 348R-10T | 3732AG-32LFT | 422G-20LF |
| 345R-08T | 348R-19 | 3732CG-28LF | 422G-20LFT |
| 345R-23LF | 348R-19LF | 3732CG-28LFT | 422G-21LF |
| 345R-23LFT | 348R-19LFT | 3732DG-28LF | 422G-21LFT |
| 345R-26LF | 348R-19T | 3732DG-28LFT | 422G-27LF |
| 345R-26LFT | 348R-20 | 3732DG-32LF | 422G-27LFT |
| 345R-27 | 348R-20LF | 3732DG-32LFT | 422M-15 |
| 345R-27LF | 348R-20LFT | 3732G-31LF | 422M-15LF |
| 345R-27LFT | 348R-20T | 3732G-31LFT | 422M-15LFT |
| 345R-27T | 348R-22LF | 3732G-33LF | 422M-15T |

ATTACHMENT 2 - PCN #: TB0910-01
Affected Part Number

| Part Number | Part Number | Part Number | Part Number |
|-------------|-------------|--------------|-----------------|
| 423AG-01LF | 448R-21LFT | 475G-21LF | 480G-23LFT |
| 423AG-01LFT | 448R-46LF | 475G-21LFT | 480G-24LF |
| 423G-01LF | 448R-46LFT | 475GI-01LF | 480G-24LFT |
| 423G-01LFT | 448R-47LF | 475GI-01LFT | 480G-28LF |
| 423G-05LF | 448R-47LFT | 475GI-14LF | 480G-28LFT |
| 423G-05LFT | 448R-48LF | 475GI-14LFT | 480GI-11 |
| 423GI-05LF | 448R-48LFT | 476AG-08LF | 480GI-11LF |
| 423GI-05LFT | 448RI-27LF | 476AG-08LFT | 480GI-11LFT |
| 445R-02 | 448RI-27LFT | 476BG-08LF | 480GI-11T |
| 445R-02LF | 454G-22 | 476BG-08LFT | 480GI-12LF |
| 445R-02LFT | 454G-22LF | 476BGI-08LF | 480GI-12LFT |
| 445R-02T | 454G-22LFT | 476BGI-08LFT | 480GI-24LF |
| 445R-09LF | 454G-22T | 476CG-08LF | 480GI-24LFT |
| 445R-09LFT | 454G-25 | 476CG-08LFT | 480GI-28LF |
| 445R-10LF | 454G-25T | 476EG-08LF | 480GI-28LFT |
| 445R-10LFT | 455R-19I | 476EG-08LFT | 487G-25 |
| 445R-20LF | 455R-19ILF | 476G-10LF | 487G-25LF |
| 445R-20LFT | 455R-19ILFT | 476G-10LFT | 487G-25LFT |
| 445R-24LF | 455R-19IT | 476G-11LF | 487G-25T |
| 445R-24LFT | 455R-25 | 476G-11LFT | 487G-30 |
| 445R-31 | 455R-25LF | 476G-14LF | 487G-30T |
| 445R-31LF | 455R-25LFT | 476G-14LFT | 487G-33 |
| 445R-31LFT | 455R-25T | 476GI-14LF | 487G-33LF |
| 445R-31T | 455R-31 | 476GI-14LFT | 487G-33LFT |
| 445R-34 | 455R-31LF | 477R-05 | 487G-33T |
| 445R-34LF | 455R-31LFT | 477R-05ILF | 487G-35 |
| 445R-34LFT | 455R-31T | 477R-05ILFT | 487G-35LF |
| 445R-34T | 455R-32 | 477R-05LF | 487G-35LFT |
| 445R-36LF | 455R-32LF | 477R-05LFT | 487G-35T |
| 445R-36LFT | 455R-32LFT | 477R-05T | 488R-12 |
| 445R-37LF | 455R-32T | 477R-06LF | 488R-12LF |
| 445R-37LFT | 470AG-03LF | 477R-06LFT | 488R-12LFT |
| 445R-40LF | 470AG-03LFT | 480AG-15LF | 488R-12T |
| 445R-40LFT | 470G-01LF | 480AG-15LFT | 488R-39 |
| 445R-41LF | 470G-01LFT | 480AG-23LF | 488R-39LF |
| 445R-41LFT | 470G-03LF | 480AG-23LFT | 488R-39LFT |
| 445R-57LF | 470G-03LFT | 480BG-15LF | 488R-39T |
| 445R-57LFT | 475G-02LF | 480BG-15LFT | 488R-39T-IB0 |
| 445R-58LF | 475G-02LFT | 480G-09LF | 490GI-10LF |
| 445R-58LFT | 475G-11LF | 480G-09LFT | 490GI-10LFT |
| 445R-63LF | 475G-11LFT | 480G-11 | 491G-06LF |
| 445R-63LFT | 475G-14LF | 480G-11LF | 491G-06LFT |
| 445RI-34LF | 475G-14LFT | 480G-11LFT | 491GI-06LF |
| 445RI-34LFT | 475G-15LF | 480G-11T | 491GI-06LFT |
| 445RI-40LF | 475G-15LFT | 480G-12LF | 49FCT20805PYGI |
| 445RI-40LFT | 475G-16LF | 480G-12LFT | 49FCT20805PYGI8 |
| 448R-01 | 475G-16LFT | 480G-15LF | 49FCT20805PYI |
| 448R-01LF | 475G-17LF | 480G-15LFT | 49FCT20805PYI8 |
| 448R-01LFT | 475G-17LFT | 480G-18LF | 49FCT20805QGI |
| 448R-01T | 475G-18LF | 480G-18LFT | 49FCT20805QGI8 |
| 448R-13LF | 475G-18LFT | 480G-19LF | 49FCT20805QI |
| 448R-13LFT | 475G-19LF | 480G-19LFT | 49FCT20805QI8 |
| 448R-18LF | 475G-19LFT | 480G-22LF | 49FCT3805APY |
| 448R-18LFT | 475G-20LF | 480G-22LFT | 49FCT3805APY8 |
| 448R-21LF | 475G-20LFT | 480G-23LF | 49FCT3805APYG |

ATTACHMENT 2 - PCN #: TB0910-01
Affected Part Number

| Part Number | Part Number | Part Number | Part Number |
|-----------------|----------------|-------------|--------------|
| 49FCT3805APYG8 | 49FCT3805QG | 507M-01ILFT | 527R-03 |
| 49FCT3805APYGI | 49FCT3805QG8 | 507M-01IT | 527R-03LF |
| 49FCT3805APYGI8 | 49FCT3805QGI | 507M-01LF | 527R-03LFT |
| 49FCT3805APYI | 49FCT3805QGI8 | 507M-01LFT | 527R-03T |
| 49FCT3805APYI8 | 49FCT3805QI | 507M-01T | 527R-04 |
| 49FCT3805AQ | 49FCT3805QI8 | 507M-02I | 527R-04LF |
| 49FCT3805AQ8 | 49FCT805APY | 525-01R | 527R-04LFT |
| 49FCT3805AQG | 49FCT805APY8 | 525-01RI | 527R-04T |
| 49FCT3805AQG8 | 49FCT805APYG | 525-01RILF | 548AM-03LF |
| 49FCT3805AQGI | 49FCT805APYG8 | 525-01RILFT | 548AM-03LFT |
| 49FCT3805AQGI8 | 49FCT805APYGI | 525-01RIT | 548AMI-03LF |
| 49FCT3805AQI | 49FCT805APYGI8 | 525-01RLF | 548AMI-03LFT |
| 49FCT3805AQI8 | 49FCT805APYI | 525-01RLFT | 548G-05 |
| 49FCT3805BPY | 49FCT805APYI8 | 525-01RT | 548G-05A |
| 49FCT3805BPY8 | 49FCT805BTPY | 525KIT1 | 548G-05ALF |
| 49FCT3805BPYGI | 49FCT805BTPY8 | 525R-02 | 548G-05ALFT |
| 49FCT3805BPYGI8 | 49FCT805BTPY8 | 525R-02I | 548G-05AT |
| 49FCT3805BPYI | 49FCT805BTPY8 | 525R-02ILF | 548G-05I |
| 49FCT3805BPYI8 | 49FCT805BTQ | 525R-02ILFT | 548G-05IT |
| 49FCT3805BQ | 49FCT805BTQ8 | 525R-02IT | 548G-05LF |
| 49FCT3805BQ8 | 49FCT805BTQG | 525R-02LF | 548G-05LFT |
| 49FCT3805BQG | 49FCT805BTQG8 | 525R-02LFT | 548G-05T |
| 49FCT3805BQG8 | 49FCT805CTPY | 525R-02T | 548GI-05A |
| 49FCT3805BQGI | 49FCT805CTPY8 | 525R-03I | 548GI-05AT |
| 49FCT3805BQGI8 | 49FCT805CTPYG | 525R-03ILF | 548M-02 |
| 49FCT3805BQI | 49FCT805CTPYG8 | 525R-03ILFT | 548M-02T |
| 49FCT3805BQI8 | 49FCT805CTQ | 525R-03IT | 552AR-01 |
| 49FCT3805BQI8 | 49FCT805CTQ8 | 525R-04 | 552AR-01LF |
| 49FCT3805BQI8 | 49FCT805CTQG | 525R-04I | 552AR-01LFT |
| 49FCT3805DPYGI | 49FCT805CTQG8 | 525R-04IT | 552AR-01T |
| 49FCT3805DPYGI8 | 49FCT805PY | 525R-04LF | 552ARI-01 |
| 49FCT3805DPYI | 49FCT805PY8 | 525R-04LFT | 552ARI-01LF |
| 49FCT3805DPYI8 | 49FCT805PYG | 525R-04T | 552ARI-01LFT |
| 49FCT3805DQGI | 49FCT805PYG8 | 525R-11 | 552ARI-01T |
| 49FCT3805DQGI8 | 49FCT805PYGI | 525R-11LF | 552G-02I |
| 49FCT3805DQI | 49FCT805PYGI8 | 525R-11LFT | 552G-02ILN |
| 49FCT3805DQI8 | 49FCT805PYI | 525R-11T | 552G-02ILNT |
| 49FCT3805EPYGI | 49FCT805PYI8 | 525RI-11 | 552G-02IT |
| 49FCT3805EPYGI8 | 49FCT806APY | 525RI-11LF | 552G-03I |
| 49FCT3805EPYI | 49FCT806APY8 | 525RI-11LFT | 552G-03IT |
| 49FCT3805EPYI8 | 49FCT806APYG | 525RI-11T | 552R-01 |
| 49FCT3805EQGI | 49FCT806APYG8 | 527R-01 | 552R-01I |
| 49FCT3805EQGI8 | 49FCT806BTPY | 527R-01I | 552R-01ILF |
| 49FCT3805EQI | 49FCT806BTPY8 | 527R-01ILF | 552R-01ILFT |
| 49FCT3805EQI8 | 49FCT806CTPY | 527R-01ILFT | 552R-01IT |
| 49FCT3805PY | 49FCT806CTPY8 | 527R-01IT | 552R-01LN |
| 49FCT3805PY8 | 49FCT806CTQ | 527R-01LF | 552R-01LNT |
| 49FCT3805PYG | 49FCT806CTQ8 | 527R-01LFT | 552R-01T |
| 49FCT3805PYG8 | 49FCT806PY | 527R-01T | 554G-01AI |
| 49FCT3805PYGI | 49FCT806PY8 | 527R-02 | 554G-01AILF |
| 49FCT3805PYGI8 | 49FCT806PYG | 527R-02I | 554G-01AILFT |
| 49FCT3805PYI | 49FCT806PYG8 | 527R-02IT | 554G-01AIT |
| 49FCT3805PYI8 | 507M-01 | 527R-02LF | 556G-03I |
| 49FCT3805Q | 507M-01I | 527R-02LFT | 556G-03IT |
| 49FCT3805Q8 | 507M-01ILF | 527R-02T | 557G-03 |

ATTACHMENT 2 - PCN #: TB0910-01
Affected Part Number

| Part Number | Part Number | Part Number | Part Number |
|------------------|--------------|----------------|-----------------|
| 557G-03LF | 580M-01IT | 5T9304EJG18 | 5V928PGGI |
| 557G-03LF-PAC | 580M-01LF | 5T9304EJI | 5V928PGG18 |
| 557G-03LFT | 580M-01LFT | 5T9304EJ18 | 5V928PGI |
| 557G-03LFT-PAC | 580M-01T | 5T9304PG | 5V928PG18 |
| 557G-03T | 581AG-02LF | 5T9304PG8 | 5V9882PGGI |
| 557G-05A | 581AG-02LFT | 5T9304PGG | 5V9882PGG18 |
| 557G-05ALF | 581BG-01 | 5T9304PGG8 | 5V9886-002PGGI |
| 557G-05ALFT | 581BG-01T | 5T93GL02PGGI | 5V9886-002PGG18 |
| 557G-05AT | 581BG-02LF | 5T93GL02PGG18 | 5V9886-005PGGI |
| 557G-06 | 581BG-02LFT | 5T93GL02PGI | 5V9886-005PGG18 |
| 557G-06LF | 581G-01 | 5T93GL02PG18 | 5V9886PGGI |
| 557G-06LFT | 581G-01I | 5T93GL04PGGI | 5V9886PGG18 |
| 557G-06T | 581G-01ILF | 5T93GL04PGG18 | 5V993A-2Q |
| 557G-07 | 581G-01LFT | 5T93GL04PGI | 5V993A-2Q8 |
| 557G-07T | 581G-01IT | 5T93GL04PG18 | 5V993A-2QG |
| 557G-08 | 581G-01LF | 5V19EE901PGGI | 5V993A-2QG8 |
| 557G-08LF | 581G-01LFT | 5V19EE901PGG18 | 5V993A-5QGI |
| 557G-08LFT | 581G-01T | 5V2305PGGI | 5V993A-5QG18 |
| 557G-08T | 581G-02 | 5V2305PGG18 | 5V993A-5QI |
| 557GI-03 | 581G-02I | 5V2305PGI | 5V993A-5Q18 |
| 557GI-03LF | 581G-02ILF | 5V2305PG18 | 5V993A-7QGI |
| 557GI-03LFT | 581G-02ILFT | 5V2310PGGI | 5V993A-7QG18 |
| 557GI-03T | 581G-02IT | 5V2310PGG18 | 5V993A-7QI |
| 557GI-05ALF | 581G-02LF | 5V2310PGI | 5V993A-7Q18 |
| 557GI-05ALF-PAC | 581G-02LFT | 5V2310PG18 | 601G-01 |
| 557GI-05ALFT | 581G-02LN | 5V2528APGGI | 601G-01I |
| 557GI-05ALFT-PAC | 581G-02LNT | 5V2528APGG18 | 601G-01ILF |
| 557GI-06 | 581G-02T | 5V2528APGI | 601G-01LFT |
| 557GI-06LF | 5993A-2Q | 5V2528APG18 | 601G-01IT |
| 557GI-06LFT | 5993A-2Q8 | 5V2528PGGI | 601G-01LF |
| 557GI-06T | 5993A-5QI | 5V2528PGG18 | 601G-01LFT |
| 557GI-08LF | 5993A-5Q18 | 5V2528PGI | 601G-01T |
| 557GI-08LFT | 5993A-7QI | 5V2528PG18 | 601G-21 |
| 558AG-02 | 5993A-7Q18 | 5V30002DCG | 601G-21LF |
| 558AG-02LN | 5P61006PGGI | 5V30002DCG8 | 601G-21LFT |
| 558AG-02LNT | 5P61006PGG18 | 5V49EE901PGGI | 601G-21T |
| 558AG-02LNT-INO | 5T30009PGGI | 5V49EE901PGG18 | 601GI-21LF |
| 558AG-02T | 5T30009PGG18 | 5V50015PGG | 601GI-21LFT |
| 558AG-02T-INO | 5T9050PGGI | 5V50015PGG8 | 601M-01 |
| 558G-01 | 5T9050PGG18 | 5V5216PGGI | 601M-01I |
| 558G-01LF | 5T9050PGI | 5V5216PGG18 | 601M-01ILF |
| 558G-01LFT | 5T9050PG18 | 5V5218PGGI | 601M-01LFT |
| 558G-01T | 5T90533PGGI | 5V5218PGG18 | 601M-01IT |
| 558G-02 | 5T90533PGG18 | 5V80001PGGI | 601M-01LF |
| 558G-02T | 5T905PGGI | 5V80001PGG18 | 601M-01LFT |
| 559GI-01 | 5T905PGG18 | 5V925QGI | 601M-01T |
| 559GI-01T | 5T905PGI | 5V925QG18 | 601M-02I |
| 580G-01ILF | 5T905PG18 | 5V925QI | 601M-02ILF |
| 580G-01LFT | 5T9302EJGI | 5V925Q18 | 601M-02LFT |
| 580G-01LF | 5T9302EJG18 | 5V926APGGI | 601M-02IT |
| 580G-01LFT | 5T9302EJI | 5V926APGG18 | 601R-25 |
| 580M-01 | 5T9302EJ18 | 5V927PGGI | 601R-25I |
| 580M-01I | 5T9302PGG | 5V927PGG18 | 601R-25ILF |
| 580M-01ILF | 5T9302PGG8 | 5V927PGI | 601R-25LFT |
| 580M-01LFT | 5T9304EJGI | 5V927PG18 | 601R-25IT |

ATTACHMENT 2 - PCN #: TB0910-01
Affected Part Number

| Part Number | Part Number | Part Number | Part Number |
|--------------|-------------|-------------|----------------|
| 601R-25LF | 650G-40 | 650R-07LF | 664G-02LFT |
| 601R-25LFT | 650G-40A | 650R-07LFT | 664G-02T |
| 601R-25T | 650G-40ALF | 650R-07T | 664G-03 |
| 612G-01I | 650G-40ALFT | 650R-08 | 664G-03LF |
| 612G-01ILF | 650G-40AT | 650R-08I | 664G-03LFT |
| 612G-01ILFT | 650G-40LF | 650R-08IT | 664G-03T |
| 612G-01IT | 650G-40LFT | 650R-08LF | 664G-04LF |
| 613M | 650G-40T | 650R-08LFT | 664G-04LFT |
| 613MLF | 650G-42LF | 650R-08T | 664G-05LF |
| 613MLFT | 650G-42LFT | 650R-11I | 664G-05LFT |
| 613MT | 650G-51 | 650R-11ILF | 664GI-01LF |
| 623AG-02LF | 650G-51LF | 650R-11LFT | 664GI-01LFT |
| 623AG-02LFT | 650G-51LFT | 650R-11IT | 664GI-05LF |
| 623G-03 | 650G-51T | 650R-12 | 664GI-05LFT |
| 623G-03LF | 650G-52LF | 650R-12LF | 670M-01 |
| 623G-03LFT | 650G-52LFT | 650R-12LFT | 670M-01I |
| 623G-03T | 650G-54LF | 650R-12T | 670M-01ILF |
| 626BGLF | 650G-54LFT | 650R-14 | 670M-01LFT |
| 626BGLFT | 650G-56LF | 650R-14I | 670M-01IT |
| 627AG-04LF | 650G-56LFT | 650R-14ILF | 670M-01LF |
| 627AG-04LFT | 650GI-36LF | 650R-14LFT | 670M-01LFT |
| 627G-04LF | 650GI-36LFT | 650R-14IT | 670M-01T |
| 627G-04LFT | 650GI-41 | 650R-14LF | 670M-02 |
| 628AG-01LF | 650GI-41LF | 650R-14LFT | 670M-02LF |
| 628AG-01LFT | 650GI-41LFT | 650R-14T | 670M-02LFT |
| 628G-01LF | 650GI-41T | 650R-21 | 670M-02T |
| 628G-01LFT | 650GI-44 | 650R-21I | 670M-03I |
| 628G-02 | 650GI-44LF | 650R-21ILF | 670M-03ILF |
| 628G-02LF | 650GI-44LFT | 650R-21LFT | 670M-03ILF-PAC |
| 628G-02LFT | 650GI-44T | 650R-21IT | 670M-03LFT |
| 628G-02T | 650GI-47LF | 650R-21LF | 670M-03LFT-PAC |
| 650AG-54LF | 650GI-47LFT | 650R-21LFT | 670M-03IT |
| 650AG-54LFT | 650GI-52LF | 650R-21T | 670M-04I |
| 650AM-29 | 650GI-52LFT | 650R-22 | 670M-04ILF |
| 650AM-29LF | 650GI-54LF | 650R-22LF | 670M-04LFT |
| 650AM-29LFT | 650GI-54LFT | 650R-22LFT | 670M-04IT |
| 650AM-29T | 650GI-55LF | 650R-22T | 670MI-02 |
| 650BF-45LF | 650GI-55LFT | 650R-27I | 670MI-02LF |
| 650BF-45LFT | 650M-38 | 650R-27ILF | 670MI-02LFT |
| 650BFI-45LF | 650M-38LF | 650R-27LFT | 670MI-02T |
| 650BFI-45LFT | 650M-38LFT | 650R-27IT | 671AGI-18LF |
| 650F-45 | 650M-38T | 660GI | 671AGI-18LFT |
| 650F-45LF | 650R-01 | 660GILF | 671G-15 |
| 650F-45LFT | 650R-01I | 660GILFT | 671G-15T |
| 650F-45T | 650R-01ILF | 660GIT | 671G-16LF |
| 650FI-45 | 650R-01LFT | 661GI | 671G-16LFT |
| 650FI-45T | 650R-01IT | 661GILF | 671GI-16LF |
| 650G-35 | 650R-01LF | 661GILFT | 671GI-16LFT |
| 650G-35LF | 650R-01LFT | 661GIT | 671M-01 |
| 650G-35LFT | 650R-01T | 664G-01 | 671M-01LF |
| 650G-35T | 650R-07 | 664G-01LF | 671M-01LFT |
| 650G-36 | 650R-07I | 664G-01LFT | 671M-01T |
| 650G-36LF | 650R-07ILF | 664G-01T | 671M-03I |
| 650G-36LFT | 650R-07LFT | 664G-02 | 671M-03ILF |
| 650G-36T | 650R-07IT | 664G-02LF | 671M-03LFT |

ATTACHMENT 2 - PCN #: TB0910-01
Affected Part Number

| Part Number | Part Number | Part Number | Part Number |
|---------------|---------------|-----------------|-----------------|
| 671M-03IT | 6V10016PGGI | 6V40105PGGI8 | 74CBTLV3253QG |
| 672M-01 | 6V10016PGGI8 | 6V40107PGGW3 | 74CBTLV3253QG8 |
| 672M-01LF | 6V10020APGG | 6V40107PGGW38 | 74CBTLV3257PGG |
| 672M-01LFT | 6V10020APGG8 | 6V40112PGG | 74CBTLV3257PGG8 |
| 672M-01T | 6V10020PGG | 6V40112PGG8 | 74CBTLV3257QG |
| 672M-02 | 6V10020PGG8 | 6V40113PGG | 74CBTLV3257QG8 |
| 672M-02I | 6V10022PGG | 6V40113PGG8 | 74CBTLV3384PGG |
| 672M-02ILF | 6V10022PGG8 | 6V40114PGG | 74CBTLV3384PGG8 |
| 672M-02ILFT | 6V10023PGG | 6V40114PGG8 | 74CBTLV3384QG |
| 672M-02IT | 6V10023PGG8 | 6V40120PGG | 74CBTLV3384QG8 |
| 672M-02LF | 6V10025PGG | 6V40120PGG8 | 74CBTLV3861PGG |
| 672M-02LFT | 6V10025PGG8 | 6V49061PGG | 74CBTLV3861PGG8 |
| 672M-02T | 6V10026PGG | 6V49061PGG8 | 74CBTLV3861QG |
| 673M-01 | 6V10026PGG8 | 6V49108PGGI | 74CBTLV3861QG8 |
| 673M-01I | 6V40006APGG | 6V49108PGGI8 | 74CBTLV3862PGG |
| 673M-01ILF | 6V40006APGG8 | 6V50006PGG | 74CBTLV3862PGG8 |
| 673M-01ILFT | 6V40006APGGI | 6V50006PGG8 | 74CBTLV3862PYG |
| 673M-01IT | 6V40006APGGI8 | 6V50007PGG | 74CBTLV3862PYG8 |
| 673M-01LF | 6V40006PGG | 6V50007PGG8 | 74CBTLV3862QG |
| 673M-01LFT | 6V40006PGG8 | 6V50008PGG | 74CBTLV3862QG8 |
| 673M-01T | 6V40016PGG | 6V50008PGG8 | 74CBTLV6800PGG |
| 674R-01 | 6V40016PGG8 | 7150G | 74CBTLV6800PGG8 |
| 674R-01I | 6V40019PGG | 7150GLF | 74CBTLV6800QG |
| 674R-01ILF | 6V40019PGG8 | 7150GLFT | 74CBTLV6800QG8 |
| 674R-01ILFT | 6V40021PGGI | 7150GT | 74FCT157ATQG |
| 674R-01IT | 6V40021PGGI8 | 74CB218AR | 74FCT157ATQG8 |
| 674R-01LF | 6V40031PGGI | 74CB218ARLF | 74FCT157CTQG |
| 674R-01LFT | 6V40031PGGI8 | 74CB218ARLFTR | 74FCT157CTQG8 |
| 674R-01T | 6V40033PGGI | 74CB218ARTR | 74FCT157DTQG |
| 680G-01 | 6V40033PGGI8 | 74CB218CR | 74FCT157DTQG8 |
| 680G-01LF | 6V40033PGGW3 | 74CB218CRLF | 74FCT20807PYGI |
| 680G-01LFT | 6V40033PGGW38 | 74CB218CRLFTR | 74FCT20807PYGI8 |
| 680G-01T | 6V40036PGGI | 74CB218CRTR | 74FCT20807PYI |
| 6P40086PGG | 6V40036PGGI8 | 74CBTLV3125PGG | 74FCT20807PYI8 |
| 6P40086PGG8 | 6V40043PGG | 74CBTLV3125PGG8 | 74FCT20807QGI |
| 6P40097PGG | 6V40043PGG8 | 74CBTLV3125QG | 74FCT20807QGI8 |
| 6P40097PGG8 | 6V40046APGGI | 74CBTLV3125QG8 | 74FCT20807QI |
| 6P40098PGG | 6V40046APGGI8 | 74CBTLV3126PGG | 74FCT20807QI8 |
| 6P40098PGG8 | 6V40046PGGI | 74CBTLV3126PGG8 | 74FCT2244ATQG |
| 6T40059PGG | 6V40046PGGI8 | 74CBTLV3126QG | 74FCT2244ATQG8 |
| 6T40059PGG8 | 6V40048PGGI | 74CBTLV3126QG8 | 74FCT2244CTQG |
| 6U40R001APGG | 6V40048PGGI8 | 74CBTLV3244PGG | 74FCT2244CTQG8 |
| 6U40R001APGG8 | 6V40052PGG | 74CBTLV3244PGG8 | 74FCT2245ATQG |
| 6U40R001PGG | 6V40052PGG8 | 74CBTLV3244QG | 74FCT2245ATQG8 |
| 6U40R001PGG8 | 6V40054PGG | 74CBTLV3244QG8 | 74FCT2245CTQG |
| 6V10001PGG | 6V40054PGG8 | 74CBTLV3245PGG | 74FCT2245CTQG8 |
| 6V10001PGG8 | 6V40056PGGI | 74CBTLV3245PGG8 | 74FCT2373ATQG |
| 6V10003APYGI | 6V40056PGGI8 | 74CBTLV3245QG | 74FCT2373ATQG8 |
| 6V10003APYGI8 | 6V40058PGG | 74CBTLV3245QG8 | 74FCT2373CTQG |
| 6V10003PYGI | 6V40058PGG8 | 74CBTLV3251PGG | 74FCT2373CTQG8 |
| 6V10003PYGI8 | 6V40074PGGI | 74CBTLV3251PGG8 | 74FCT2374ATQG |
| 6V10006APGGI | 6V40074PGGI8 | 74CBTLV3251QG | 74FCT2374ATQG8 |
| 6V10006APGGI8 | 6V40096PGG | 74CBTLV3251QG8 | 74FCT2374CTQG |
| 6V10012PGG | 6V40096PGG8 | 74CBTLV3253PGG | 74FCT2374CTQG8 |
| 6V10012PGG8 | 6V40105PGGI | 74CBTLV3253PGG8 | 74FCT240ATPYG |

ATTACHMENT 2 - PCN #: TB0910-01
Affected Part Number

| Part Number | Part Number | Part Number | Part Number |
|----------------|-----------------|--------------------|-----------------|
| 74FCT240ATPYG8 | 74FCT3245QG | 74FCT3807DQI | 74FCT521CTPYG8 |
| 74FCT240ATQG | 74FCT3245QG8 | 74FCT3807DQI8 | 74FCT521CTQG |
| 74FCT240ATQG8 | 74FCT3573AQQ | 74FCT3807EPGGI | 74FCT521CTQG8 |
| 74FCT240CTPYG | 74FCT3573AQQ8 | 74FCT3807EPGGI8 | 74FCT540ATPYG |
| 74FCT240CTPYG8 | 74FCT3573QG | 74FCT3807EPGI | 74FCT540ATPYG8 |
| 74FCT240CTQG | 74FCT3573QG8 | 74FCT3807EPGI8 | 74FCT540ATQG |
| 74FCT240CTQG8 | 74FCT373ATPYG | 74FCT3807EPYGI | 74FCT540ATQG8 |
| 74FCT244ATPGG | 74FCT373ATPYG8 | 74FCT3807EPYGI8 | 74FCT540CTPYG |
| 74FCT244ATPGG8 | 74FCT373ATQG | 74FCT3807EPYI | 74FCT540CTPYG8 |
| 74FCT244ATPYG | 74FCT373ATQG8 | 74FCT3807EPYI8 | 74FCT540CTQG |
| 74FCT244ATPYG8 | 74FCT373CTPYG | 74FCT3807EQGI | 74FCT540CTQG8 |
| 74FCT244ATQG | 74FCT373CTPYG8 | 74FCT3807EQGI8 | 74FCT543ATQG |
| 74FCT244ATQG8 | 74FCT373CTQG | 74FCT3807EQI | 74FCT543ATQG8 |
| 74FCT244CTPGG | 74FCT373CTQG8 | 74FCT3807EQI8 | 74FCT543CTQG |
| 74FCT244CTPGG8 | 74FCT374ATPYG | 74FCT3807PY | 74FCT543CTQG8 |
| 74FCT244CTPYG | 74FCT374ATPYG8 | 74FCT3807PY8 | 74FCT543DTQG |
| 74FCT244CTPYG8 | 74FCT374ATQG | 74FCT3807PYG | 74FCT543DTQG8 |
| 74FCT244CTQG | 74FCT374ATQG8 | 74FCT3807PYG8 | 74FCT573ATQG |
| 74FCT244CTQG8 | 74FCT374CTPYG | 74FCT3807PYGI | 74FCT573ATQG8 |
| 74FCT245ATPGG | 74FCT374CTPYG8 | 74FCT3807PYGI8 | 74FCT573CTQG |
| 74FCT245ATPGG8 | 74FCT374CTQG | 74FCT3807PYI | 74FCT573CTQG8 |
| 74FCT245ATPYG | 74FCT374CTQG8 | 74FCT3807PYI8 | 74FCT574ATQG |
| 74FCT245ATPYG8 | 74FCT377ATQG | 74FCT3807Q | 74FCT574ATQG8 |
| 74FCT245ATQG | 74FCT377ATQG8 | 74FCT3807Q8 | 74FCT574CTQG |
| 74FCT245ATQG8 | 74FCT377CTQG | 74FCT3807QG | 74FCT574CTQG8 |
| 74FCT245CTPGG | 74FCT377CTQG8 | 74FCT3807QG8 | 74FCT807BTPY |
| 74FCT245CTPGG8 | 74FCT377DTQG | 74FCT3807QGI | 74FCT807BTPY8 |
| 74FCT245CTPYG | 74FCT377DTQG8 | 74FCT3807QGI8 | 74FCT807BTPY8 |
| 74FCT245CTPYG8 | 74FCT3807APY | 74FCT3807QI | 74FCT807BTPY8 |
| 74FCT245CTQG | 74FCT3807APY8 | 74FCT3807QI8 | 74FCT807BTPYGI |
| 74FCT245CTQG8 | 74FCT3807APY8/C | 74FCT3811PYGI | 74FCT807BTPYGI8 |
| 74FCT257ATQG | 74FCT3807APYG | 74FCT3811PYGI8 | 74FCT807BTPYI |
| 74FCT257ATQG8 | 74FCT3807APYG8 | 74FCT3811PYI | 74FCT807BTPYI8 |
| 74FCT257CTQG | 74FCT3807APYGI | 74FCT3811PYI8 | 74FCT807BTQ |
| 74FCT257CTQG8 | 74FCT3807APYGI8 | 74FCT388915T100PY | 74FCT807BTQ8 |
| 74FCT257DTQG | 74FCT3807APYI | 74FCT388915T100PY8 | 74FCT807BTQG |
| 74FCT257DTQG8 | 74FCT3807APYI8 | 74FCT388915T133PY | 74FCT807BTQG8 |
| 74FCT3244APGG | 74FCT3807AQ | 74FCT388915T133PY8 | 74FCT807BTQGI |
| 74FCT3244APGG8 | 74FCT3807AQ8 | 74FCT388915T150PY | 74FCT807BTQGI8 |
| 74FCT3244APYG | 74FCT3807AQQ | 74FCT388915T150PY8 | 74FCT807BTQI |
| 74FCT3244APYG8 | 74FCT3807AQQ8 | 74FCT388915T70PY | 74FCT807BTQI8 |
| 74FCT3244AQQ | 74FCT3807AQQI | 74FCT388915T70PY8 | 74FCT807CTPY |
| 74FCT3244AQQ8 | 74FCT3807AQQI8 | 74FCT388915TBPYG | 74FCT807CTPY8 |
| 74FCT3244PGG | 74FCT3807AQI | 74FCT388915TBPYG8 | 74FCT807CTPYG |
| 74FCT3244PGG8 | 74FCT3807AQI8 | 74FCT388915TCPYG | 74FCT807CTPYG8 |
| 74FCT3244PYG | 74FCT3807DPGGI | 74FCT388915TCPYG8 | 74FCT807CTPYGI |
| 74FCT3244PYG8 | 74FCT3807DPGGI8 | 74FCT388915TDPYG | 74FCT807CTPYGI8 |
| 74FCT3244QG | 74FCT3807DPGI | 74FCT388915TDPYG8 | 74FCT807CTPYI |
| 74FCT3244QG8 | 74FCT3807DPGI8 | 74FCT388915TEPYG | 74FCT807CTPYI8 |
| 74FCT3245APGG | 74FCT3807DPYGI | 74FCT388915TEPYG8 | 74FCT807CTQ |
| 74FCT3245APGG8 | 74FCT3807DPYGI8 | 74FCT521ATPYG | 74FCT807CTQ8 |
| 74FCT3245AQQ | 74FCT3807DPYI | 74FCT521ATPYG8 | 74FCT807CTQG |
| 74FCT3245AQQ8 | 74FCT3807DPYI8 | 74FCT521ATQG | 74FCT807CTQG8 |
| 74FCT3245PGG | 74FCT3807DQGI | 74FCT521ATQG8 | 74FCT807CTQGI |
| 74FCT3245PGG8 | 74FCT3807DQGI8 | 74FCT521CTPYG | 74FCT807CTQGI8 |

ATTACHMENT 2 - PCN #: TB0910-01
Affected Part Number

| Part Number | Part Number | Part Number | Part Number |
|--------------------|------------------|-----------------|----------------|
| 74FCT807CTQI | 74LVC273APGG8 | 83005AGILFT | 83054AGI-01LFT |
| 74FCT807CTQI8 | 74LVC4245APGG | 83005AGIT | 83054AGI-01T |
| 74FCT810BTPY | 74LVC4245APGG8 | 83005BGI | 83054AGILF |
| 74FCT810BTPY8 | 74LVC4245APYG | 83005BGILF | 83054AGILFT |
| 74FCT810BTPYG | 74LVC4245APYG8 | 83005BGILFT | 83054AGIT |
| 74FCT810BTPYG8 | 74LVC4245AQQ | 83005BGIT | 83056AGI |
| 74FCT810BTQ | 74LVC4245AQQ8 | 830154AGI-08LF | 83056AGI-01 |
| 74FCT810BTQ8 | 74LVC541AQQ | 830154AGI-08LFT | 83056AGI-01LF |
| 74FCT810BTQG | 74LVC541AQQ8 | 830154AGILF | 83056AGI-01LFT |
| 74FCT810BTQG8 | 74LVCC3245APGG | 830154AGILFT | 83056AGI-01T |
| 74FCT810CTPY | 74LVCC3245APGG8 | 830154BGI-09 | 83056AGILF |
| 74FCT810CTPY8 | 8101925AGILF | 830154BGI-09LF | 83056AGILFT |
| 74FCT810CTPYG | 8101925AGILFT | 830154BGI-09LFT | 83056AGIT |
| 74FCT810CTPYG8 | 810251AGI | 830154BGI-09T | 830584AGI |
| 74FCT810CTQ | 810251AGI-01LF | 830154BGILF | 830584AGILF |
| 74FCT810CTQ8 | 810251AGI-01LFT | 830154BGILFT | 830584AGILFT |
| 74FCT810CTQG | 810251AGI-08LF | 830158BGILF | 830584AGIT |
| 74FCT810CTQG8 | 810251AGI-08LFT | 830158BGILFT | 830584AGI |
| 74FCT823ATQG | 810251AGILF | 830258BGILF | 830584AGILF |
| 74FCT823ATQG8 | 810251AGILF-EXT | 830258BGILFT | 830584AGILFT |
| 74FCT823CTQG | 810251AGILFT | 83026BGI-01 | 830584AGIT |
| 74FCT823CTQG8 | 810251AGILFT-EXT | 83026BGI-01LF | 8305AG |
| 74FCT88915TT100PY | 810251AGIT | 83026BGI-01LFT | 8305AG-02 |
| 74FCT88915TT100PY8 | 810525AGILF | 83026BGI-01T | 8305AG-02LF |
| 74FCT88915TT133PY | 810525AGILFT | 83032AGI | 8305AG-02LFT |
| 74FCT88915TT133PY8 | 813001AGI | 83032AGILF | 8305AG-02T |
| 74FCT88915TT55PY | 813001AGILF | 83032AGILFT | 8305AGI |
| 74FCT88915TT55PY8 | 813001AGILFT | 83032AGIT | 8305AGILF |
| 74FCT88915TT70PY | 813001AGIT | 830354BGILF | 8305AGILFT |
| 74FCT88915TT70PY8 | 813253AG | 830354BGILFT | 8305AGIT |
| 74FCT88915TTAPYG | 813253AGI | 830454BGILF | 8305AGLF |
| 74FCT88915TTAPYG8 | 813253AGILF | 830454BGILFT | 8305AGLFT |
| 74FCT88915TTBPYG | 813253AGILFT | 8304AG-02 | 8305AGT |
| 74FCT88915TTBPYG8 | 813253AGIT | 8304AG-02LF | 8308AGI |
| 74FCT88915TTCPYG | 813253AGLF | 8304AG-02LFT | 8308AGILF |
| 74FCT88915TTCPYG8 | 813253AGLFT | 8304AG-02T | 8308AGILFT |
| 74FCT88915TTDPYG | 813253AGT | 8304AG-03 | 8308AGIT |
| 74FCT88915TTDPYG8 | 813253BGLF | 8304AG-03LF | 83115BR |
| 74FST6800PGG | 813253BGLFT | 8304AG-03LFT | 83115BRI |
| 74FST6800PGG8 | 813321AG-04 | 8304AG-03T | 83115BRILF |
| 74FST6800QG | 813321AG-04LF | 8304AG-04LF | 83115BRILFT |
| 74FST6800QG8 | 813321AG-04LFT | 8304AG-04LFT | 83115BRIT |
| 74LVC244APGG | 813321AG-04T | 8304AGI-04LF | 83115BRLF |
| 74LVC244APGG8 | 813321AG-ALPLF | 8304AGI-04LFT | 83115BRLFT |
| 74LVC244APYG | 813321AG-ALPLFT | 83052AGI | 83115BRT |
| 74LVC244APYG8 | 813323BG | 83052AGI-01 | 831721AGILF |
| 74LVC244AQQ | 813323BGLF | 83052AGI-01LF | 831721AGILFT |
| 74LVC244AQQ8 | 813323BGLFT | 83052AGI-01LFT | 831741AGILF |
| 74LVC245APGG | 813323BGT | 83052AGI-01T | 831741AGILFT |
| 74LVC245APGG8 | 814253AG | 83052AGILF | 831742AGILF |
| 74LVC245APYG | 814253AGT | 83052AGILFT | 831742AGILFT |
| 74LVC245APYG8 | 814253BGLF | 83052AGIT | 83904AG-02 |
| 74LVC245AQQ | 814253BGLFT | 83054AGI | 83904AG-02LF |
| 74LVC245AQQ8 | 83005AGI | 83054AGI-01 | 83904AG-02LFT |
| 74LVC273APGG | 83005AGILF | 83054AGI-01LF | 83904AG-02T |

ATTACHMENT 2 - PCN #: TB0910-01
Affected Part Number

| Part Number | Part Number | Part Number | Part Number |
|-----------------|-----------------|---------------|-----------------|
| 83904AGI-02 | 840002AGT | 840021AGILF | 840CG-125LFT |
| 83904AGI-02LF | 840004AG | 840021AGILFT | 840NTVAGLF |
| 83904AGI-02LFT | 840004AG-01 | 840021AGIT | 840NTVAGLFT |
| 83904AGI-02T | 840004AG-01LF | 840021AGLF | 840S2306AGI |
| 83905AG | 840004AG-01LFT | 840021AGLFT | 840S2306AGILF |
| 83905AG-01LF | 840004AG-01T | 840021AGT | 840S2306AGILFT |
| 83905AG-01LFT | 840004AG-11LF | 840022AG | 840S2306AGIT |
| 83905AGI | 840004AG-11LFT | 840022AGI | 840S2316AGI |
| 83905AGILF | 840004AGI | 840022AGI-01 | 840S2316AGILF |
| 83905AGILFT | 840004AGI-01 | 840022AGI-01T | 840S2316AGILFT |
| 83905AGIT | 840004AGI-01LF | 840022AGIT | 840S2316AGIT |
| 83905AGLF | 840004AGI-01LFT | 840022AGLF | 840S2326AGI |
| 83905AGLFT | 840004AGI-01T | 840022AGLFT | 840S2326AGILF |
| 83905AGT | 840004AGI-HPLF | 840022AGT | 840S2326AGILFT |
| 83905AM | 840004AGI-HPLFT | 840024AGI | 840S2326AGIT |
| 83905AML | 840004AGIT | 840024AGILF | 841201AGI-45LF |
| 83905AMLFT | 840004AGLF | 840024AGILFT | 841201AGI-45LFT |
| 83905AMT | 840004AGLFT | 840024AGIT | 841201BGI-45 |
| 83908AG-02 | 840004AGT | 840051AG | 841201BGI-45LF |
| 83908AG-02LF | 840004BGI | 840051AGI | 841201BGI-45LFT |
| 83908AG-02LFT | 840004BGI-01 | 840051AGILF | 841201BGI-45T |
| 83908AG-02T | 840004BGI-01LF | 840051AGILFT | 841S01BG |
| 83908AGI-02 | 840004BGI-01LFT | 840051AGIT | 841S01BGLF |
| 83908AGI-02LF | 840004BGI-01T | 840051AGLF | 841S01BGLFT |
| 83908AGI-02LFT | 840004BGI-11 | 840051AGLFT | 841S01BGT |
| 83908AGI-02T | 840004BGI-11LF | 840051AGT | 841S01DGILF |
| 840001AGI | 840004BGI-11LFT | 840245AGI | 841S01DGILFT |
| 840001AGIT | 840004BGI-11T | 840245AGILF | 841S02BGI |
| 840001BG | 840004BGILF | 840245AGILFT | 841S02BGILF |
| 840001BGI | 840004BGILFT | 840245AGIT | 841S02BGILFT |
| 840001BGI-25 | 840004BGIT | 840271AGILF | 841S02BGIT |
| 840001BGI-25LF | 840008AR-01 | 840271AGILFT | 841S02DGILF |
| 840001BGI-25LFT | 840008AR-01T | 840271BGILF | 841S02DGILFT |
| 840001BGI-25T | 840011AG | 840271BGILFT | 841S04BGI |
| 840001BGILF | 840011AGI | 840272AGILF | 841S04BGI-09LF |
| 840001BGILFT | 840011AGIT | 840272AGILFT | 841S04BGI-09LFT |
| 840001BGIT | 840011AGLN | 840304BGI | 841S04BGILF |
| 840001BGLF | 840011AGLNT | 840304BGILF | 841S04BGILFT |
| 840001BGLFT | 840011AGT | 840304BGILFT | 841S04BGIT |
| 840001BGT | 840012AGI | 840304BGIT | 841S04DGILF |
| 840002AG | 840012AGIT | 840AG-125 | 841S04DGILFT |
| 840002AG-01 | 840014AGI | 840AG-125T | 841S102BGILF |
| 840002AG-01LF | 840014AGIT | 840AG-156 | 841S102BGILFT |
| 840002AG-01LFT | 840016AG-01 | 840AG-156LF | 841S102DGILF |
| 840002AG-01T | 840016AG-01LF | 840AG-156LFT | 841S102DGILFT |
| 840002AGI | 840016AG-01LFT | 840AG-156T | 841S104DGILF |
| 840002AGI-01 | 840016AG-01T | 840AG-75 | 841S104DGILFT |
| 840002AGI-01LF | 840016AGI-01LF | 840AG-75LF | 842002AGI |
| 840002AGI-01LFT | 840016AGI-01LFT | 840AG-75LFT | 842002AGI-01 |
| 840002AGI-01T | 840016BGI-01LF | 840AG-75T | 842002AGI-01T |
| 840002AGILF | 840016BGI-01LFT | 840AG-77 | 842002AGIT |
| 840002AGILFT | 840016CGI-01LF | 840AG-77T | 842004AGI |
| 840002AGIT | 840016CGI-01LFT | 840BG-125LF | 842004AGI-01 |
| 840002AGLF | 840021AG | 840BG-125LFT | 842004AGI-01T |
| 840002AGLFT | 840021AGI | 840CG-125LF | 842004AGIT |

ATTACHMENT 2 - PCN #: TB0910-01
Affected Part Number

| Part Number | Part Number | Part Number | Part Number |
|------------------|--------------------|-----------------|-----------------|
| 842011AGI | 843001AGI-100T | 843004AG-01 | 843021AG-57LF |
| 842011AGIT | 843001AGI-123 | 843004AG-01LF | 843021AG-57LFT |
| 842021AGI-01 | 843001AGI-123LF | 843004AG-01LFT | 843021AG-57T |
| 842021AGI-01T | 843001AGI-123LFT | 843004AG-01T | 843021AGI-01 |
| 842022AGI-02 | 843001AGI-123T | 843004AG-02 | 843021AGI-01LF |
| 842022AGI-02T | 843001AGI-22 | 843004AG-02LF | 843021AGI-01LFT |
| 842023BGLF | 843001AGI-22LF | 843004AG-02LFT | 843021AGI-01T |
| 842023BGLFT | 843001AGI-22LFT | 843004AG-02T | 843021AGLF |
| 842051AGI-01 | 843001AGI-22T | 843004AG-125 | 843021AGLFT |
| 842051AGI-01LF | 843001AGIT | 843004AG-125LF | 843021AGT |
| 842051AGI-01LFT | 843001AGLF | 843004AG-125LFT | 843021AGT-IN0 |
| 842051AGI-01T | 843001AGLFT | 843004AG-125T | 843022AG |
| 842071AGI | 843001AGT | 843004AG-ALPLF | 843022AGI |
| 842071AGIT | 843001BG | 843004AG-ALPLFT | 843022AGI-48 |
| 8421002AGI-01 | 843001BGI-23 | 843004AGI | 843022AGI-48LF |
| 8421002AGI-01LF | 843001BGI-23LF | 843004AGI-01 | 843022AGI-48LFT |
| 8421002AGI-01LFT | 843001BGI-23LFT | 843004AGI-01LF | 843022AGI-48T |
| 8421002AGI-01T | 843001BGI-23T | 843004AGI-01LFT | 843022AGIT |
| 8421004AGI | 843001BGT | 843004AGI-01T | 843022AGLF |
| 8421004AGI-01 | 843001CGILF | 843004AGI-02 | 843022AGLFT |
| 8421004AGI-01T | 843001CGILFT | 843004AGI-02LF | 843022AGT |
| 8421004AGIT | 843001MG | 843004AGI-02LFT | 843023AG |
| 8422002AGI | 843001MGT | 843004AGI-02T | 843023AGI |
| 8422002AGI-01 | 843002AG | 843004AGI-04 | 843023AGILF |
| 8422002AGI-01T | 843002AG-01 | 843004AGI-04LF | 843023AGILFT |
| 8422002AGI-07LF | 843002AG-01LF | 843004AGI-04LFT | 843023AGIT |
| 8422002AGI-07LFT | 843002AG-01LFT | 843004AGI-04T | 843023AGLF |
| 8422002AGILF | 843002AG-01LFT-IB0 | 843004AGI-09 | 843023AGLFT |
| 8422002AGILFT | 843002AG-01T | 843004AGI-09LF | 843023AGT |
| 8422002AGIT | 843002AGI | 843004AGI-09LFT | 8430252CG-45 |
| 8422004AGI | 843002AGI-01 | 843004AGI-09T | 8430252CG-45LF |
| 8422004AGI-01 | 843002AGI-01LF | 843004AGIT | 8430252CG-45LFT |
| 8422004AGI-01T | 843002AGI-01LFT | 843004AGLF | 8430252CG-45T |
| 8422004AGIT | 843002AGI-01T | 843004AGLFT | 8430252CGI-45 |
| 842S104BGLF | 843002AGILF | 843004AGT | 8430252CGI-45T |
| 842S104BGLFT | 843002AGILFT | 843011AG | 843031AG |
| 842S104CGLF | 843002AGIT | 843011AG-01 | 843031AG-01 |
| 842S104CGLFT | 843002AGLF | 843011AG-01T | 843031AG-01LF |
| 843001AG | 843002AGLFT | 843011AGLF | 843031AG-01LFT |
| 843001AG-123 | 843002AGT | 843011AGLFT | 843031AG-01T |
| 843001AG-123LF | 843002CG-01LF | 843011AGT | 843031AGI |
| 843001AG-123LFT | 843002CG-01LFT | 843011BG | 843031AGI-01 |
| 843001AG-123T | 843003AG | 843011BGLF | 843031AGI-01LF |
| 843001AG-21 | 843003AGI-01 | 843011BGLFT | 843031AGI-01LFT |
| 843001AG-21LF | 843003AGI-01LF | 843011BGT | 843031AGI-01T |
| 843001AG-21LFT | 843003AGI-01LFT | 843011CG | 843031AGIT |
| 843001AG-21T | 843003AGI-01T | 843011CGLF | 843031AGLF |
| 843001AG-22 | 843003AGLF | 843011CGLFT | 843031AGLFT |
| 843001AG-22LF | 843003AGLFT | 843011CGT | 843031AGT |
| 843001AG-22LFT | 843003AGT | 843021AG | 843051AG |
| 843001AG-22T | 843003BGI-09 | 843021AG-01 | 843051AG-57 |
| 843001AG-23LF | 843003BGI-09LF | 843021AG-01LF | 843051AG-57LF |
| 843001AG-23LFT | 843003BGI-09LFT | 843021AG-01LFT | 843051AG-57LFT |
| 843001AGI | 843003BGI-09T | 843021AG-01T | 843051AG-57T |
| 843001AGI-100 | 843004AG | 843021AG-57 | 843051AGILF |

ATTACHMENT 2 - PCN #: TB0910-01
Affected Part Number

| Part Number | Part Number | Part Number | Part Number |
|------------------|-----------------|------------------|------------------|
| 843051AGILFT | 843241BGLFT | 843252AGI-04LF | 843801AG-24T |
| 843051AGLF | 843242AG | 843252AGI-04LFT | 843801AGI-24 |
| 843051AGLFT | 843242AGLF | 843252AGI-04T | 843801AGI-24LF |
| 843051AGT | 843242AGLFT | 843252AGLF | 843801AGI-24LFT |
| 843051CGI | 843242AGT | 843252AGLFT | 843801AGI-24T |
| 843051CGIT | 843243AG-08 | 843252AGT | 843AG-106 |
| 843071AGI | 843243AG-08LF | 843253AGI-45 | 843AG-106T |
| 843071AGILF | 843243AG-08LFT | 843253AGI-45LF | 843AG-125 |
| 843071AGILFT | 843243AG-08T | 843253AGI-45LFT | 843AG-125LF |
| 843071AGIT | 843245AGLF | 843253AGI-45T | 843AG-125LFT |
| 843071AGLF | 843245AGLFT | 843256AG | 843AG-125T |
| 843081AGI-01 | 843245BGLF | 843256AGI-45LF | 843AG-75 |
| 843081AGI-01LF | 843245BGLFT | 843256AGI-45LFT | 843AG-75LF |
| 843081AGI-01T | 843246BG | 843256AGT | 843AG-75LFT |
| 843081AGI-33LF | 843246BGI | 843256BG | 843AG-75T |
| 843081AGI-33LFT | 843246BGILF | 843256BGI | 843AGI-106 |
| 843101AG-100 | 843246BGILFT | 843256BGILF | 843AGI-106T |
| 843101AG-100LF | 843246BGIT | 843256BGILFT | 843AGI-75 |
| 843101AG-100LFT | 843246BGLF | 843256BGIT | 843AGI-75LF |
| 843101AG-100T | 843246BGLFT | 843256BGLF | 843AGI-75LFT |
| 843101AG-250 | 843246BGT | 843256BGLFT | 843AGI-75T |
| 843101AG-250LF | 843251AG-04 | 843256BGT | 843N156CG-125LF |
| 843101AG-250LFT | 843251AG-04LF | 843301BGI-103 | 843N156CG-125LFT |
| 843101AG-250T | 843251AG-04LFT | 843301BGI-103T | 843N252BG-45LF |
| 843101AG-312 | 843251AG-04T | 843301BGI-108 | 843N252BG-45LFT |
| 843101AG-312LF | 843251AG-GOOLF | 843301BGI-108LF | 843N252CG-45LF |
| 843101AG-312LFT | 843251AG-GOOLF | 843301BGI-108LFT | 843N252CG-45LFT |
| 843101AG-312T | 843251AGI-04 | 843301BGI-108T | 843N252EG-45LF |
| 843101AGI-100 | 843251AGI-04LF | 843321AG-12 | 843N252EG-45LFT |
| 843101AGI-100LF | 843251AGI-04LFT | 843321AG-12LF | 843N3960BGILF |
| 843101AGI-100LFT | 843251AGI-04T | 843321AG-12LFT | 843N3960BGILFT |
| 843101AGI-100T | 843251AGI-14 | 843321AG-12T | 843S1066CGLF |
| 843101AGI-250LF | 843251AGI-14LF | 843321AGI-12 | 843S1066CGLFT |
| 843101AGI-250LFT | 843251AGI-14LFT | 843321AGI-12LF | 843S1333CGLF |
| 843101AGI-312LF | 843251AGI-14T | 843321AGI-12LFT | 843S1333CGLFT |
| 843101AGI-312LFT | 843251AGI-HPLF | 843321AGI-12T | 843SDNAG |
| 843201AG-375 | 843251AGI-HPLFT | 8433625AGLF | 843SDNAGLF |
| 843201AG-375LF | 843251BGI-12 | 8433625AGLFT | 843SDNAGLFT |
| 843201AG-375LFT | 843251BGI-12LF | 843404AG | 843SDNAGT |
| 843201AG-375T | 843251BGI-12LFT | 843404AGLF | 843SDNCG-01 |
| 843201AGI-45LF | 843251BGI-12T | 843404AGLFT | 843SDNCG-01LF |
| 843201AGI-45LFT | 843251BGI-15 | 843404AGT | 843SDNCG-01LFT |
| 843201BGI-45 | 843251BGI-15LF | 843441AGILF | 843SDNCG-01T |
| 843201BGI-45LF | 843251BGI-15LFT | 843441AGILFT | 844001AG-21 |
| 843201BGI-45LFT | 843251BGI-15T | 843441AGLF | 844001AG-21T |
| 843201BGI-45T | 843252AG | 843441AGLFT | 844001AGI |
| 843241AG | 843252AG-04 | 843442AGILF | 844001AGILF |
| 843241AGI-04 | 843252AG-04LF | 843442AGILFT | 844001AGILFT |
| 843241AGI-04LF | 843252AG-04LFT | 84351AG | 844001AGIT |
| 843241AGI-04LFT | 843252AG-04T | 84351AGLF | 844001AGLF |
| 843241AGI-04T | 843252AG-45 | 84351AGLFT | 844001AGLFT |
| 843241AGLF | 843252AG-45LF | 84351AGT | 844002AG |
| 843241AGLFT | 843252AG-45LFT | 843801AG-24 | 844002AG-01 |
| 843241AGT | 843252AG-45T | 843801AG-24LF | 844002AG-01LF |
| 843241BGLF | 843252AGI-04 | 843801AG-24LFT | 844002AG-01LFT |

ATTACHMENT 2 - PCN #: TB0910-01
Affected Part Number

| Part Number | Part Number | Part Number | Part Number |
|-----------------|------------------|-----------------|-------------------|
| 844002AG-01T | 844022AGT | 844251BG-14LFT | 85104AGILF |
| 844002AGI-01 | 844023AGLF | 844251BG-14T | 85104AGILFT |
| 844002AGI-01LF | 844023AGLFT | 844251BGI-12LF | 85104AGIT |
| 844002AGI-01LFT | 844031BG-01 | 844251BGI-12LFT | 85105AGI |
| 844002AGI-01T | 844031BG-01LF | 844251BGI-15 | 85105AGILF |
| 844002AGLF | 844031BG-01LFT | 844251BGI-15LF | 85105AGILFT |
| 844002AGLFT | 844031BG-01T | 844251BGI-15LFT | 85105AGIT |
| 844002AGT | 844031BGI-01 | 844251BGI-15T | 85108AGI |
| 844003AG | 844031BGI-01LF | 844252AG-04 | 85108AGILF |
| 844003AGLF | 844031BGI-01LFT | 844252AG-04LF | 85108AGILFT |
| 844003AGLFT | 844031BGI-01T | 844252AG-04LFT | 85108AGIT |
| 844003AGT | 844051CGILF | 844252AG-04T | 8512061AGI |
| 844003BG-01 | 844051CGILFT | 844252BGLF | 8512061AGILF |
| 844003BG-01LF | 844051CGLF | 844252BGLFT | 8512061AGILFT |
| 844003BG-01LFT | 844051CGLFT | 844256BG | 8512061AGIT |
| 844003BG-01T | 844071AGLF | 844256BGILF | 8512062AGILF |
| 844003BGI-01 | 844071AGLFT | 844256BGILFT | 8512062AGILFT |
| 844003BGI-01LF | 844101AG-125LF | 844256BGLF | 85214AG |
| 844003BGI-01LFT | 844101AG-125LFT | 844256BGLFT | 85214AGI |
| 844003BGI-01T | 844101AGI-125LF | 844256BGT | 85214AGILF |
| 844003EGI-01 | 844101AGI-125LFT | 844256CGILF | 85214AGILFT |
| 844003EGI-01LF | 844201BG-45LF | 844256CGILFT | 85214AGIT |
| 844003EGI-01LFT | 844201BG-45LFT | 844441DGILF | 85214AGLF |
| 844003EGI-01T | 844201BGI-45 | 844441DGILFT | 85214AGLFT |
| 844004AGI-04LF | 844201BGI-45T | 844801AG-24 | 85214AGT |
| 844004AGI-04LFT | 844242AGI-04 | 844801AG-24LF | 8523AGI-03 |
| 844004BGI-01 | 844242AGI-04LF | 844801AG-24LFT | 8523AGI-03LN |
| 844004BGI-01LF | 844242AGI-04LFT | 844801AG-24T | 8523AGI-03LNT |
| 844004BGI-01LFT | 844242AGI-04T | 844801AGI-24 | 8523AGI-03LNT-IB0 |
| 844004BGI-01T | 844242AGI-08 | 844801AGI-24LF | 8523AGI-03T |
| 844004BGLF | 844242AGI-08LF | 844801AGI-24LFT | 8523AGI-03T-IB0 |
| 844004BGLFT | 844242AGI-08LFT | 844801AGI-24T | 8523BG |
| 844006AG-45LF | 844242AGI-08T | 848002AGI | 8523BGI |
| 844006AG-45LFT | 844244AGI-04 | 848002AGI-01 | 8523BGILF |
| 844006AGI-45LF | 844244AGI-04LF | 848002AGI-01T | 8523BGILFT |
| 844006AGI-45LFT | 844244AGI-04LFT | 848002AGIT | 8523BGIT |
| 844006BG-45LF | 844244AGI-04T | 848004AGI | 8523BGIT-IB0 |
| 844006BG-45LFT | 844244AGI-08 | 848004AGI-01 | 8523BGLF |
| 844006BGLF | 844244AGI-08LF | 848004AGI-01T | 8523BGLFT |
| 844006BGLFT | 844244AGI-08LFT | 848004AGILF | 8523BGT |
| 844011AGLF | 844244AGI-08T | 848004AGILFT | 8523CG |
| 844011AGLFT | 844246BGLF | 848004AGIT | 8523CGI |
| 844011CGI | 844246BGLFT | 850S1201AGILF | 8523CGILF |
| 844011CGILF | 844246CGILF | 850S1201AGILFT | 8523CGILFT |
| 844011CGILFT | 844246CGILFT | 850S1201BGI | 8523CGIT |
| 844011CGIT | 844251AGI-04 | 850S1201BGILF | 8523CGLF |
| 844021BG-01 | 844251AGI-04LF | 850S1201BGILFT | 8523CGLFT |
| 844021BG-01LF | 844251AGI-04LFT | 850S1201BGIT | 8523CGT |
| 844021BG-01LFT | 844251AGI-04T | 850S1601BGILF | 8525BG |
| 844021BG-01T | 844251AGI-12 | 850S1601BGILFT | 8525BGLF |
| 844021BGI-01 | 844251AGI-12LF | 85102AGI | 8525BGLFT |
| 844021BGI-01LF | 844251AGI-12LFT | 85102AGILF | 8525BGT |
| 844021BGI-01LFT | 844251AGI-12T | 85102AGILFT | 853006AG |
| 844021BGI-01T | 844251BG-14 | 85102AGIT | 853006AGLF |
| 844022AG | 844251BG-14LF | 85104AGI | 853006AGLFT |

ATTACHMENT 2 - PCN #: TB0910-01
Affected Part Number

| Part Number | Part Number | Part Number | Part Number |
|-----------------|------------------|----------------|----------------|
| 853006AGT | 8533AGI-01LFT | 8535AG-31T-ACT | 853S058AGILF |
| 853014BG | 8533AGI-01T | 8535AG-ACT | 853S058AGILFT |
| 853014BGLF | 8533AGI-31 | 8535AGI-01 | 853S1204AGI |
| 853014BGLFT | 8533AGI-31LF | 8535AGI-01LF | 853S1204AGILF |
| 853014BGT | 8533AGI-31LFT | 8535AGI-01LFT | 853S1204AGILFT |
| 85301AG | 8533AGI-31T | 8535AGI-01T | 853S1204AGIT |
| 85301AGLF | 8534AMI-13 | 8535AGI-11 | 853S314AFI |
| 85301AGLFT | 8534AMI-13LF | 8535AGI-11T | 853S314AFILF |
| 85301AGT | 8534AMI-13LFT | 8535AGI-21LF | 853S314AFILFT |
| 85304-01PG | 8534AMI-13T | 8535AGI-21LFT | 853S314AFIT |
| 85304-01PG8 | 8534BMI-13LF | 8535AGI-31 | 853S314AGI |
| 85304-01PGG | 8534BMI-13LFT | 8535AGI-31LF | 853S314AGILF |
| 85304-01PGG8 | 8535-01PG | 8535AGI-31LFT | 853S314AGILFT |
| 85304-01PGGI | 8535-01PG8 | 8535AGI-31T | 853S314AGIT |
| 85304-01PGGI8 | 8535-01PGG | 8535AGLF-ACT | 854054AG |
| 85304-01PGI | 8535-01PGG8 | 8535AGLFT-ACT | 854054AGLF |
| 85304-01PGI8 | 8535-01PGGI | 8535AGT-ACT | 854054AGLFT |
| 85304AG-01 | 8535-01PGGI8 | 8535BG-01 | 854054AGT |
| 85304AG-01LF | 8535-01PGI | 8535BG-01T | 854057AG |
| 85304AG-01LFT | 8535-01PGI8 | 8536AG-01 | 854057AGLF |
| 85304AG-01T | 85356AGI | 8536AG-01LF | 854057AGLFT |
| 85304AG-01T-IB0 | 85356AGILF | 8536AG-01LFT | 854057AGT |
| 85304AGI-01 | 85356AGILFT | 8536AG-01T | 854058AG |
| 85304AGI-01T | 85356AGIT | 8536AG-02 | 854058AGLF |
| 853054AG | 85357AG-01 | 8536AG-02LF | 854058AGLFT |
| 853054AGLF | 85357AG-01LF | 8536AG-02LFT | 854058AGT |
| 853054AGLFT | 85357AG-01LFT | 8536AG-02T | 85408BG |
| 853054AGT | 85357AG-01T | 8536CGI-33 | 85408BGI |
| 853058AG | 85357AG-11 | 8536CGI-33LF | 85408BGILF |
| 853058AGLF | 85357AG-11LF | 8536CGI-33LFT | 85408BGILFT |
| 853058AGLFT | 85357AG-11LFT | 8536CGI-33T | 85408BGIT |
| 853058AGT | 85357AG-11T | 8538AG-31 | 85408BGLF |
| 85314AGI-11 | 85357AGI-01 | 8538AG-31T | 85408BGLFT |
| 85314AGI-11LF | 85357AGI-01LF | 8538AG-31TVLF | 85408BGT |
| 85314AGI-11LFT | 85357AGI-01LFT | 8538AG-31TVLFT | 854104AG |
| 85314AGI-11T | 85357AGI-01T | 8538BG-31 | 854104AGILF |
| 85314BGI-01 | 8535AG-01 | 8538BG-31LF | 854104AGILFT |
| 85314BGI-01LF | 8535AG-01LF | 8538BG-31LFT | 854104AGLF |
| 85314BGI-01LFT | 8535AG-01LFT | 8538BG-31T | 854104AGLFT |
| 85314BGI-01T | 8535AG-01T | 8538BGI-26 | 854104AGT |
| 85314BGI-09LF | 8535AG-11 | 8538BGI-26LF | 854105AG |
| 85314BGI-09LFT | 8535AG-11LF | 8538BGI-26LFT | 854105AGLF |
| 8533AG-01 | 8535AG-11LFT | 8538BGI-26T | 854105AGLFT |
| 8533AG-01LF | 8535AG-11T | 8538BGI-31 | 854105AGT |
| 8533AG-01LFT | 8535AG-21 | 8538BGI-31LF | 8543AG-09LF |
| 8533AG-01LN | 8535AG-21LF | 8538BGI-31LFT | 8543AG-09LFT |
| 8533AG-01LN-IB0 | 8535AG-21LFT | 8538BGI-31T | 8543BG |
| 8533AG-01LNT | 8535AG-21T | 853S006AGILF | 8543BGI |
| 8533AG-01T | 8535AG-31 | 853S006AGILFT | 8543BGILF |
| 8533AG-11 | 8535AG-31-ACT | 853S014AGILF | 8543BGILFT |
| 8533AG-11LF | 8535AG-31LF | 853S014AGILFT | 8543BGIT |
| 8533AG-11LFT | 8535AG-31LF-ACT | 853S01AGILF | 8543BGLF |
| 8533AG-11T | 8535AG-31LFT | 853S01AGILFT | 8543BGLFT |
| 8533AGI-01 | 8535AG-31LFT-ACT | 853S057AGILF | 8543BGT |
| 8533AGI-01LF | 8535AG-31T | 853S057AGILFT | 8544BM-13LF |

ATTACHMENT 2 - PCN #: TB0910-01
Affected Part Number

| Part Number | Part Number | Part Number | Part Number |
|------------------|----------------|-----------------|-----------------|
| 8544BM-13LFT | 854S204AGILFT | 87002AG-02LF | 871004AGI-04 |
| 8545AG-01 | 854S204AGIT | 87002AG-02LFT | 871004AGI-04LF |
| 8545AG-01LF | 854S204BGILF | 87002AG-02T | 871004AGI-04LFT |
| 8545AG-01LFT | 854S204BGILFT | 87004AG | 871004AGI-04T |
| 8545AG-01T | 854S306AGI | 87004AGI | 873034AG |
| 8545AG-02 | 854S306AGILF | 87004AGILF | 873034AGLF |
| 8545AG-02LF | 854S306AGILFT | 87004AGILFT | 873034AGLFT |
| 8545AG-02LFT | 854S306AGIT | 87004AGIT | 873034AGT |
| 8545AG-02T | 854S44AGILF | 87004AGLF | 873034AM |
| 8545AGI-02LF | 854S44AGILFT | 87004AGLFT | 873034AMLF |
| 8545AGI-02LFT | 854S44AGLF | 87004AGT | 873034AMLFT |
| 8545BG | 854S44AGLFT | 87004BG-03LF | 873034AMT |
| 8545BGI | 859S0212AGILF | 87004BG-03LFT | 87339AGI-11 |
| 8545BGILF | 859S0212AGILFT | 87004BGI-03LF | 87339AGI-11LF |
| 8545BGILFT | 859S0214AGILF | 87004BGI-03LFT | 87339AGI-11LFT |
| 8545BGIT | 859S0214AGILFT | 87006BG-01 | 87339AGI-11T |
| 8545BGLF | 859S0224AGILF | 87006BG-01LF | 8737-11PGG |
| 8545BGLFT | 859S0224AGILFT | 87006BG-01LFT | 8737-11PGG8 |
| 8545BGT | 859S0412BGILF | 87006BG-01T | 8737AG-11 |
| 8546AG-01 | 859S0412BGILFT | 87008AG | 8737AG-11LF |
| 8546AG-01LF | 859S0414AGILF | 87008AG-01 | 8737AG-11LFT |
| 8546AG-01LFT | 859S0414AGILFT | 87008AG-01T | 8737AG-11T |
| 8546AG-01T | 859S0424BGILF | 87008AGI | 8737AGI-11 |
| 8546AGI-33 | 859S0424BGILFT | 87008AGILF | 8737AGI-11LF |
| 8546AGI-33LF | 859S1201AGILF | 87008AGILFT | 8737AGI-11LFT |
| 8546AGI-33LFT | 859S1201AGILFT | 87008AGIT | 8737AGI-11T |
| 8546AGI-33T | 859S1601BGILF | 87008AGT | 873N486AGILF |
| 8546BGI-33LF | 859S1601BGILFT | 87008BG-01 | 873N486AGILFT |
| 8546BGI-33LFT | 86004AG-02 | 87008BG-01LF | 873N486BGILF |
| 8548AG-26 | 86004AG-02LF | 87008BG-01LFT | 873N486BGILFT |
| 8548AG-26T | 86004AG-02LFT | 87008BG-01T | 874001AGI-02LF |
| 8548AGI-26 | 86004AG-02T | 870919BRI-01 | 874001AGI-02LFT |
| 8548AGI-26T | 86004BG | 870919BRI-01LF | 874001AGI-05LF |
| 8548BG-26LF | 86004BG-01 | 870919BRI-01LFT | 874001AGI-05LFT |
| 8548BG-26LFT | 86004BG-01LF | 870919BRI-01T | 874002AG |
| 854S006AGI | 86004BG-01LFT | 870919BRILF | 874002AG-02LF |
| 854S006AGILF | 86004BG-01T | 870919BRILFT | 874002AG-02LFT |
| 854S006AGILFT | 86004BGI | 870931ARI-01 | 874002AGLF |
| 854S006AGIT | 86004BGI-01 | 870931ARI-01LF | 874002AGLFT |
| 854S013BGILF | 86004BGI-01T | 870931ARI-01LFT | 874002AGT |
| 854S013BGILFT | 86004BGILF | 870931ARI-01T | 874003AG |
| 854S015CG-01LF | 86004BGILFT | 870931BRILF | 874003AG-02 |
| 854S015CG-01LFT | 86004BGIT | 870931BRILFT | 874003AG-02LF |
| 854S015CGI-01LF | 86004BGLF | 870S204BG | 874003AG-02LFT |
| 854S015CGI-01LFT | 86004BGLFT | 870S204BGLF | 874003AG-02T |
| 854S057AGILF | 86004BGT | 870S204BGLFT | 874003AG-04 |
| 854S057AGILFT | 8633AF-01 | 870S204BGT | 874003AG-04LF |
| 854S058AGILF | 8633AF-01LF | 871001AGI-02 | 874003AG-04LFT |
| 854S058AGILFT | 8633AF-01LFT | 871001AGI-02LF | 874003AG-04T |
| 854S1204AGI | 8633AF-01T | 871001AGI-02LFT | 874003AG-05 |
| 854S1204AGILF | 87001BG-01 | 871001AGI-02T | 874003AG-05T |
| 854S1204AGILFT | 87001BG-01LF | 871002AGI-02 | 874003AGI-02 |
| 854S1204AGIT | 87001BG-01LFT | 871002AGI-02LF | 874003AGI-02LF |
| 854S204AGI | 87001BG-01T | 871002AGI-02LFT | 874003AGI-02LFT |
| 854S204AGILF | 87002AG-02 | 871002AGI-02T | 874003AGI-02T |

ATTACHMENT 2 - PCN #: TB0910-01
Affected Part Number

| Part Number | Part Number | Part Number | Part Number |
|------------------|-------------------|-----------------|-------------------|
| 874003AGI-03 | 8D5017AG | 9112BFI-17LFT | 9154A-27CS16T |
| 874003AGI-03LF | 8S73034AGILF | 9112BG-17 | 9154A-27CS16T-IB0 |
| 874003AGI-03LFT | 8S73034AGILFT | 9112BG-17T | 9154A-42CS16 |
| 874003AGI-03T | 8S73034AMILF | 9112BM-17 | 9154A-42CS16T |
| 874003AGI-04 | 8S73034AMILFT | 9112BM-17LF | 9154A-43CS16LF |
| 874003AGI-04LF | 9107C-03CS14T | 9112BM-17LFT | 9154A-43CS16LFT |
| 874003AGI-04LFT | 9107C-03CS14T-IB0 | 9112BM-17T | 9154A-57CS16 |
| 874003AGI-04T | 9107C-03CS14T-IB1 | 9112BM-18 | 9154A-57CS16T |
| 874003AGLF | 9107C-03CS14T-INT | 9112BM-18T | 91715AFT |
| 874003AGLFT | 9110-01CS14 | 9112CM-18 | 91718CG |
| 874003AGT | 9110-01CS14LF | 9112CM-18LF | 91718CGLF |
| 874003BG-05LF | 9110-01CS14LFT | 9112CM-18LFT | 91718CGLFT |
| 874003BG-05LFT | 9110-01CS14T | 9112CM-18T | 91718CGT |
| 874003CGI-02LF | 9110-01CS14T-A | 9112M-07 | 91719AG |
| 874003CGI-02LFT | 9110-02CS14 | 9112M-07LF | 91719AG-SC0 |
| 874003DG-02 | 9110-02CS14LF | 9112M-07LFT | 91719AGLF |
| 874003DG-02LF | 9110-02CS14LFT | 9112M-07T | 91719AGLF-SC0 |
| 874003DG-02LFT | 9110-02CS14T | 91305AG | 91719AGLFT |
| 874003DG-02T | 9110-02CS14T-DE0 | 91305AGILF | 91719AGLFT-SC0 |
| 874003DGI-02 | 9110-02CS14T-IB0 | 91305AGILFT | 91719AGT |
| 874003DGI-02LF | 9112AF-17 | 91305AGIT | 91719AGT-SC0 |
| 874003DGI-02LFT | 9112AF-17LF | 91305AGLF | 91719BG |
| 874003DGI-02T | 9112AF-17LFT | 91305AGLFT | 91719BGLF |
| 874004AG | 9112AF-17LFT-IB0 | 91305AGT | 91719BGLFT |
| 874004AGT | 9112AF-17T | 91309AF | 91719BGT |
| 874005AG | 9112AF-17T-IB0 | 91309AFI | 9172-03CS16 |
| 874005AG-04 | 9112AF-17T-IB1 | 91309AFIT | 9172-03CS16T |
| 874005AG-04LF | 9112AF-17T-INO | 91309AFT | 9172-07CS16 |
| 874005AG-04LFT | 9112AG-16 | 91309AGI | 9172-07CS16T |
| 874005AG-04T | 9112AG-16LF | 91309AGILF | 91720BG |
| 874005AGLF | 9112AG-16LFT | 91309AGILFT | 91720BGLF |
| 874005AGLFT | 9112AG-16T | 91309AGIT | 91720BGLFT |
| 874005AGT | 9112AG-26 | 91309AGLF | 91720BGT |
| 8741004AG | 9112AG-26LF | 91309AGLFT | 9179AF-12 |
| 8741004AGLF | 9112AG-26LFT | 91309AM | 9179AF-12LF |
| 8741004AGLFT | 9112AG-26T | 91309AMI | 9179AF-12LFT |
| 8741004AGT | 9112AG-26T-INO | 91309AMILF | 9179AF-12T |
| 8741004BGI | 9112AG-27 | 91309AMILFT | 9179BF-03 |
| 8741004BGILF | 9112AG-27LF | 91309AMIT | 9179BF-03LF |
| 8741004BGILFT | 9112AG-27LFT | 91309AMLF | 9179BF-03LFT |
| 8741004BGIT | 9112AG-27T | 91309AMLFT | 9179BF-03T |
| 874S336AGLF | 9112AG-28 | 91309AMT | 9212AF-13 |
| 874S336AGLFT | 9112AG-28T | 9148F-18 | 9212AF-13LF |
| 894D115AGI-04 | 9112AM-17 | 9148F-18LF | 9212AF-13LF-INO |
| 894D115AGI-04LF | 9112AM-17LF | 9148F-18LFT | 9212AF-13LFT |
| 894D115AGI-04LFT | 9112AM-17LFT | 9148F-18T | 9212AF-13LFT-INO |
| 894D115AGI-04T | 9112AM-17T | 9154A-04CS16 | 9212AF-13T |
| 894D115AGI-05LF | 9112BF-17 | 9154A-04CS16LF | 9212CF-01 |
| 894D115AGI-05LFT | 9112BF-17LF | 9154A-04CS16LFT | 9212CF-01LF |
| 894D115BGI-01 | 9112BF-17LFT | 9154A-04CS16T | 9212CF-01LFT |
| 894D115BGI-01LF | 9112BF-17LN-INO | 9154A-10CS16LF | 9212CF-01T |
| 894D115BGI-01LFT | 9112BF-17LNT-INO | 9154A-10CS16LFT | 9212CF-03 |
| 894D115BGI-01T | 9112BF-17T | 9154A-27CS16 | 9212CF-03T |
| 894D115BGILF | 9112BF-17T-INO | 9154A-27CS16LF | 9212CF-03T-IB0 |
| 894D115BGILFT | 9112BFI-17LF | 9154A-27CS16LFT | 9212DF-03LF |

ATTACHMENT 2 - PCN #: TB0910-01
Affected Part Number

| Part Number | Part Number | Part Number | Part Number |
|----------------|----------------|--------------|-----------------|
| 9212DF-03LFT | 9279AF-03T | 93786AFLFT | 9DB104AFT-INO |
| 9214BGLF | 93712EF | 93786AFT | 9DB104AG |
| 9214BGLFT | 93712EFLF | 93789BF | 9DB104AGLF |
| 9214DGLF | 93712EFLF-TE0 | 93789BFLF | 9DB104AGLFT |
| 9214DGLFT | 93712EFLF-TE0T | 93789BFLFT | 9DB104AGLN |
| 9218AGLF | 93712EFLFT | 93789BFT | 9DB104AGLNT |
| 9218AGLFT | 93712EFT | 93789DF | 9DB104AGT |
| 9218BGLF | 93716AF | 93789DFLF | 9DB104BF |
| 9218BGLFT | 93716AFLF | 93789DFLFT | 9DB104BFLF |
| 9219BGLF | 93716AFLFT | 93789DFT | 9DB104BFLFT |
| 9219BGLFT | 93716AFT | 93V847AGLF | 9DB104BFLN |
| 9220AGLF | 93716AFT-IB0 | 93V855AG | 9DB104BFLNT |
| 9220AGLFT | 93716BFLF | 93V855AGI | 9DB104BFLNT-INO |
| 9220BGILF | 93716BFLFT | 93V855AGIT | 9DB104BFT |
| 9220BGILFT | 93722BF | 93V855AGLF | 9DB104BFT-INO |
| 9222AG-01LF | 93722BFLF | 93V855AGLFT | 9DB104BG |
| 9222AG-01LFT | 93722BFLFT | 93V855AGT | 9DB104BGLF |
| 9222AG-01T-INO | 93722BFT | 95V842AF | 9DB104BGLFT |
| 9248AF-176 | 93722CF | 95V842AFILF | 9DB104BGLN |
| 9248AF-176T | 93722CFLF | 95V842AFILFT | 9DB104BGLNT |
| 9248AF-185 | 93722CFLFT | 95V842AFLF | 9DB104BGT |
| 9248AF-185LF | 93722CFT | 95V842AFLFT | 9DB106BFILF |
| 9248AF-185LFT | 93722DFLF | 95V842AFT | 9DB106BFILFT |
| 9248AF-185T | 93722DFLFT | 95V847AG | 9DB106BFLF |
| 9248AF-198 | 93732AF | 95V847AGI | 9DB106BFLFT |
| 9248AF-198LF | 93732AFLF | 95V847AGIT | 9DB106BGILF |
| 9248AF-198LFT | 93732AFLFT | 95V847AGLF | 9DB106BGILFT |
| 9248AF-198T | 93732AFT | 95V847AGLFT | 9DB106BGLF |
| 9248AF-50 | 93732AG | 95V847AGT | 9DB106BGLFT |
| 9248AF-61 | 93732AGT | 960002AF | 9DB124AFT |
| 9248AF-61LF | 93741CF | 960002AFLF | 9DB124AGT |
| 9248AF-61LFT | 93741CFT | 960002AFLFT | 9DB200AFLF |
| 9248AF-61T | 93742AF | 960002AFT | 9DB200AFLFT |
| 9248AF-80 | 93742AFLF | 960007AFLF | 9DB202CF |
| 9248AF-80LF | 93742AFLFT | 960007AFLFT | 9DB202CFLF |
| 9248AF-80LFT | 93742AFT | 960008AFLF | 9DB202CFLFT |
| 9248AF-80T | 93772AF | 960008AFLFT | 9DB202CFT |
| 9248AG-185LF | 93772AFLF | 960010AF | 9DB202CG |
| 9248AG-185LFT | 93772AFLFT | 960010AFLF | 9DB202CGLF |
| 9248AG-185T | 93772AFT | 960010AFLFT | 9DB202CGLFT |
| 9248AG-192 | 93772CF | 960010AFT | 9DB202CGT |
| 9248AG-192LF | 93772CFLF | 9DB102BFILF | 9DB206CF |
| 9248AG-192LFT | 93772CFLFT | 9DB102BFILFT | 9DB206CFLF |
| 9248AG-192T | 93772CFT | 9DB102BFLF | 9DB206CFLFT |
| 9248AG-198 | 93776AF | 9DB102BFLFT | 9DB206CFT |
| 9248AG-198LF | 93776AFT | 9DB102BGILF | 9DB206CL |
| 9248AG-198LFT | 93776BF | 9DB102BGILFT | 9DB206CLLF |
| 9248AG-198T | 93776BFT | 9DB102BGLF | 9DB206CLLFT |
| 9248BF-137 | 93777BF | 9DB102BGLFT | 9DB206CLT |
| 9248BF-137T | 93777BFIT | 9DB104AF | 9DB306BF |
| 9248BF-50LF | 93777BFLF | 9DB104AFLF | 9DB306BFLF |
| 9248BF-50LFT | 93777BFLFT | 9DB104AFLFT | 9DB306BFLFT |
| 9279AF-03 | 93777BFT | 9DB104AFLN | 9DB306BFT |
| 9279AF-03LF | 93786AF | 9DB104AFLNT | 9DB306BL |
| 9279AF-03LFT | 93786AFLF | 9DB104AFT | 9DB306BLI |

ATTACHMENT 2 - PCN #: TB0910-01
Affected Part Number

| Part Number | Part Number | Part Number | Part Number |
|-----------------|----------------|-----------------|------------------|
| 9DB306BLILF | 9FG104DGLF | CSPT855PGG8 | MC100ES6535EJ |
| 9DB306BLILFT | 9FG104DGLFT | CSPT855PGI | MC100ES6535EJR2 |
| 9DB306BLIT | 9FG110CF | CSPT855PGI8 | MK1491-06R |
| 9DB306BLLF | 9FG110CFLF | CV112-3PGG | MK1491-06RLF |
| 9DB306BLLFT | 9FG110CFLFT | CV112-3PGG8 | MK1491-06RLFTR |
| 9DB306BLT | 9FG110CFT | CV143PY | MK1491-06RTR |
| 9DB401BF | 9FG110CG | CV143PY8 | MK1491-09F |
| 9DB401BFLF | 9FG110CGLF | CV143PYG | MK1491-09FILN |
| 9DB401BFLFT | 9FG110CGLFT | CV143PYG8 | MK1491-09FILNTR |
| 9DB401BFT | 9FG110CGT | LDS6000PYGI | MK1491-09FLN |
| 9DB401BG | 9FG130AFLF | LDS6000PYGI8 | MK1491-09FLNTR |
| 9DB401BGLF | 9FG130AFLFT | LDS6003PYGI | MK1491-09FTR |
| 9DB401BGLFT | 9P935AFLF | LDS6003PYGI8 | MK1491E-14R |
| 9DB401BGT | 9P935AFLF-QN0 | LDS6005PYGI | MK1491E-14RLF |
| 9DB401CFLF | 9P935AFLFT | LDS6005PYGI8 | MK1491E-14RLFTR |
| 9DB401CFLF-IN0 | 9P935AFLFT-QN0 | LDS6020PYGI | MK1491E-14RTR |
| 9DB401CFLFT | 9P935AGLF | LDS6020PYGI8 | MK1492-03R |
| 9DB401CFLFT-IN0 | 9P935AGLFT | LDS6023PYGI | MK1492-03RTR |
| 9DB401CGLF | 9P936AFLF | LDS6023PYGI8 | MK1493-05G |
| 9DB401CGLFT | 9P936AFLFT | LDS6025PYGI | MK1493-05GILF |
| 9DB401CGLFT-IN0 | 9P936AGLF | LDS6025PYGI8 | MK1493-05GILFTR |
| 9DB402AF | 9P936AGLFT | LDS6104PYGI | MK1493-05GLF |
| 9DB402AFT | 9P937AF | LDS6104PYGI8 | MK1493-05GLFTR |
| 9DB403DFILF | 9P937AFT | LDS6107PYGI | MK1493-05GTR |
| 9DB403DFILFT | 9P939AFLF | LDS6107PYGI8 | MK1493-14GLF |
| 9DB403DFLF | 9P939AFLFT | LDS6124PYGI | MK1493-14GLFTR |
| 9DB403DFLFT | 9P939AGLF | LDS6124PYGI8 | MK1493-15GLF |
| 9DB403DGILF | 9P939AGLFT | LDS6126PYGI | MK1493-15GLFTR |
| 9DB403DGILFT | 9P956AFLF | LDS6126PYGI8 | MK1493AG-15LF |
| 9DB403DGLF | 9P956AFLFT | LV810FI | MK1493AG-15LFTR |
| 9DB403DGLFT | 9P956AGLF | LV810FILF | MK1574-01AS |
| 9DB423BFLF | 9P956AGLFT | LV810FILFT | MK1574-01ASI |
| 9DB423BFLFT | 9V41001AGLF | LV810FIT | MK1574-01ASITR |
| 9DB423BGLF | 9V41001AGLFT | LV810RI | MK1574-01ASTR |
| 9DB423BGLFT | 9WDV3501BGLF | LV810RILF | MK1574-01BS |
| 9DBL411AGLF | 9WDV3501BGLFT | LV810RILFT | MK1574-01BSI |
| 9DBL411AGLFT | CSP2510CPG | LV810RIT | MK1574-01BSILF |
| 9DS400AGLF | CSP2510CPG8 | MC100ES6014DT | MK1574-01BSILFTR |
| 9DS400AGLFT | CSP2510CPGG | MC100ES6014DTR2 | MK1574-01BSITR |
| 9FG104CF | CSP2510CPGG8 | MC100ES6014EJ | MK1574-01BSTR |
| 9FG104CFLF | CSP2510CPGI | MC100ES6014EJR2 | MK1574-01S |
| 9FG104CFLFT | CSP2510CPGI8 | MC100ES6056DT | MK1574-01SI |
| 9FG104CFT | CSP2510DPG | MC100ES6056DTR2 | MK1574-01SILF |
| 9FG104CG | CSP2510DPG8 | MC100ES6056EJ | MK1574-01SILFTR |
| 9FG104CGLF | CSP2510DPGG | MC100ES6056EJR2 | MK1574-01SITR |
| 9FG104CGLF-PAC | CSP2510DPGG8 | MC100ES6130DT | MK1574-01SLF |
| 9FG104CGLFT | CSP2510DPGGI | MC100ES6130DTR2 | MK1574-01SLFTR |
| 9FG104CGLFT-PAC | CSP2510DPGGI8 | MC100ES6130EJ | MK1574-01STR |
| 9FG104CGT | CSP2510DPGI | MC100ES6130EJR2 | MK1575-01G |
| 9FG104DFILF | CSP2510DPGI8 | MC100ES6139DT | MK1575-01GI |
| 9FG104DFILFT | CSPT855PG | MC100ES6139DTR2 | MK1575-01GILF |
| 9FG104DFLF | CSPT855PG8 | MC100ES6139EJ | MK1575-01GILFTR |
| 9FG104DFLFT | CSPT855PGG | MC100ES6139EJR2 | MK1575-01GITR |
| 9FG104DGILF | CSPT855PGG8 | MC100ES6535DT | MK1575-01GLF |
| 9FG104DGILFT | CSPT855PGGI | MC100ES6535DTR2 | MK1575-01GLFTR |

ATTACHMENT 2 - PCN #: TB0910-01
Affected Part Number

| Part Number | Part Number | Part Number | Part Number |
|------------------|-----------------|----------------|------------------|
| MK1575-01GTR | MK2308G-1HITR | MK2746-01G | MK3732-25BFLF |
| MK1581-01GI | MK2308G-1HLF | MK2746-01GLF | MK3732-25BFLFTR |
| MK1581-01GILF | MK2308G-1HLFTR | MK2746-01GLFTR | MK3732-26GLF |
| MK1581-01GILFTR | MK2308G-1HTR | MK2746-01GTR | MK3732-26GLFTR |
| MK1581-01GITR | MK2308S-1 | MK2746G | MK3732-27GLF |
| MK1709AG | MK2308S-1H | MK2746GLF | MK3732-27GLFTR |
| MK1709AGLF | MK2308S-1HI | MK2746GLFTR | MK3732A-26GLF |
| MK1709AGLFTR | MK2308S-1HILF | MK2746GTR | MK3732A-26GLFT |
| MK1709AGT | MK2308S-1HILFTR | MK2761AS | MK3771-17R |
| MK1714-01R | MK2308S-1HITR | MK2761ASLF | MK3771-17RLF |
| MK1714-01RI | MK2308S-1HLF | MK2761ASLFTR | MK3771-17RLFTR |
| MK1714-01RILF | MK2308S-1HLFTR | MK2761ASTR | MK3771-17RTR |
| MK1714-01RILFTR | MK2308S-1HTR | MK2771-15R | MK3805RI |
| MK1714-01RITR | MK2308S-1I | MK2771-15RLF | MK3805RILF |
| MK1714-01RLF | MK2308S-1ITR | MK2771-15RLFTR | MK3805RILFTR |
| MK1714-01RLFTR | MK2308S-1TR | MK2771-15RTR | MK3805RITR |
| MK1714-01RTR | MK2308S-2 | MK2771-16R | MK3807-01RI |
| MK1714-02R | MK2308S-2I | MK2771-16RLF | MK3807-01RILF |
| MK1714-02RI | MK2308S-2ILF | MK2771-16RLFTR | MK3807-01RILFTR |
| MK1714-02RILF | MK2308S-2ITR | MK2771-16RTR | MK3807-01RITR |
| MK1714-02RILFTR | MK2308S-2LF | MK3230-01S | MK5812G |
| MK1714-02RIT | MK2308S-2LFTR | MK3230-01STR | MK5812GTR |
| MK1714-02RLF | MK2308S-2TR | MK3233-01S | MK5814G |
| MK1714-02RLFTR | MK2731-03S | MK3233-01STR | MK5814GLF |
| MK1714-02RTR | MK2731-03STR | MK3235-02S | MK5814GLFTR |
| MK1716-01R | MK2732-06G | MK3235-02STR | MK5814GTR |
| MK1716-01RLF | MK2732-06GI | MK3722G | MK712R |
| MK1716-01RLFTR | MK2732-06GITR | MK3722GLF | MK712RI |
| MK1716-01RTR | MK2732-06GLF | MK3722GLFTR | MK712RITR |
| MK1725GILF | MK2732-06GLFTR | MK3722GTR | MK712RLF |
| MK1725GILFTR | MK2732-06GTR | MK3724G | MK712RLFTR |
| MK1725GLF | MK2745-21S | MK3724GILF | MK712RTR |
| MK1725GLFTR | MK2745-21SLF | MK3724GILFTR | MK712RW |
| MK1726-09ARLF | MK2745-21SLFTR | MK3724GLF | MK712RWLF |
| MK1726-09ARLFTR | MK2745-21STR | MK3724GLFTR | MK712RWLFTR |
| MK1726-09RLF | MK2745-24S | MK3724GTR | MK712RWTR |
| MK1726-09RLFTR | MK2745-24SLF | MK3732-08R | MK74CB218BR |
| MK1726-12GLF | MK2745-24SLFTR | MK3732-08RTR | MK74CB218BRLF |
| MK1726-12GLFTR | MK2745-24STR | MK3732-10S | MK74CB218BRLFTR |
| MK1727-01DGI | MK2745-26S | MK3732-10SLF | MK74CB218BRTR |
| MK1727-01DGILF | MK2745-26SLF | MK3732-10SLFTR | MK74CB218R |
| MK1727-01DGILFTR | MK2745-26SLFTR | MK3732-10STR | MK74CB218RLF |
| MK1727-01DGITR | MK2745-26STR | MK3732-17S | MK74CB218RLFTR |
| MK1727G-02LF | MK2745-27R | MK3732-17STR | MK74CB218RTR |
| MK1727G-02LFT | MK2745-27RTR | MK3732-19G | MK74CB44R |
| MK1727GI-02LF | MK2745-28BR | MK3732-19GLF | MK74CB44RLF |
| MK1727GI-02LFT | MK2745-28BRLF | MK3732-19GLFTR | MK74CB44RLFTR |
| MK1728-01G | MK2745-28BRLFTR | MK3732-19GTR | MK74CB44RTR |
| MK1728-01GTR | MK2745-28BRTR | MK3732-22RLF | MPC905D |
| MK1728AG-01LF | MK2745-31RLF | MK3732-22RLFTR | MPC905DR2 |
| MK1728AG-01LFT | MK2745-31RLFTR | MK3732-23R | MPC905EF |
| MK2308G-1H | MK2745-33G | MK3732-23RLF | MPC905EFR2 |
| MK2308G-1HI | MK2745-33GLF | MK3732-23RLFTR | MPC962305DT-1H |
| MK2308G-1HILF | MK2745-33GLFTR | MK3732-23RTR | MPC962305DT-1HR2 |
| MK2308G-1HILFTR | MK2745-33GTR | MK3732-25BF | MPC962305EJ-1H |

ATTACHMENT 2 - PCN #: TB0910-01
Affected Part Number

| Part Number | Part Number | Part Number | Part Number |
|------------------|-----------------|---------------|-----------------|
| MPC962305EJ-1HR2 | QS3253QG | QS3L384QG8 | QS4A201QG |
| MPC962308D-1H | QS3253QG8 | QS3VH125QG | QS4A201QG8 |
| MPC962308D-1HR2 | QS3253S1G | QS3VH125QG8 | QS4A205QG |
| MPC962308DT-1H | QS3253S1G8 | QS3VH125S1G | QS4A205QG8 |
| MPC962308DT-1HR2 | QS3257QG | QS3VH125S1G8 | QS4A210QG |
| MPC962308EF-1H | QS3257QG8 | QS3VH126QG | QS4A210QG8 |
| MPC962308EF-1HR2 | QS3257S1G | QS3VH126QG8 | QS4A215Q1G |
| MPC962308EJ-1H | QS3257S1G8 | QS3VH126S1G | QS4A215Q1G8 |
| MPC962308EJ-1HR2 | QS32X2245Q2G | QS3VH126S1G8 | QS5917T-100TQ |
| MPC962309D-1 | QS32X2245Q2G8 | QS3VH2245PAG | QS5917T-100TQ8 |
| MPC962309D-1H | QS32X2384Q1G | QS3VH2245PAG8 | QS5917T-100TQG |
| MPC962309D-1HR2 | QS32X2384Q1G8 | QS3VH2245QG | QS5917T-100TQG8 |
| MPC962309D-1R2 | QS32X245Q2G | QS3VH2245QG8 | QS5917T-132TQ |
| MPC962309DT-1H | QS32X245Q2G8 | QS3VH244PAG | QS5917T-132TQ8 |
| MPC962309DT-1HR2 | QS32X384Q1G | QS3VH244PAG8 | QS5917T-132TQG |
| MPC962309EF-1H | QS32X384Q1G8 | QS3VH244QG | QS5917T-132TQG8 |
| MPC962309EF-1HR2 | QS32X861Q1G | QS3VH244QG8 | QS5917T-70TQ |
| MPC962309EJ-1H | QS32X861Q1G8 | QS3VH245PAG | QS5917T-70TQ8 |
| MPC962309EJ-1HR2 | QS32XL384Q1G | QS3VH245PAG8 | QS5917T-70TQG |
| MPC9817EN | QS32XL384Q1G8 | QS3VH245QG | QS5917T-70TQG8 |
| MPC9817ENR2 | QS32XVH2245Q2G | QS3VH245QG8 | QS5930-50TQ |
| MPC9817SD | QS32XVH2245Q2G8 | QS3VH251PAG | QS5930-50TQ8 |
| MPC9817SDR2 | QS32XVH245Q2G | QS3VH251PAG8 | QS5930-66TQ |
| MPC9819EN | QS32XVH245Q2G8 | QS3VH251QG | QS5930-66TQ8 |
| MPC9819ENR2 | QS32XVH384Q1G | QS3VH251QG8 | QS5LV919-100Q |
| MPC9819SD | QS32XVH384Q1G8 | QS3VH253PAG | QS5LV919-100Q8 |
| MPC9819SDR2 | QS3383QG | QS3VH253PAG8 | QS5LV919-100QG |
| NV021AG | QS3383QG8 | QS3VH253QG | QS5LV919-100QG8 |
| NV021AGLF | QS3384PAG | QS3VH253QG8 | QS5LV919-55Q |
| NV021AGLFT | QS3384PAG8 | QS3VH257PAG | QS5LV919-55Q8 |
| NV021AGT | QS3384QG | QS3VH257PAG8 | QS5LV919-70Q |
| QS3125QG | QS3384QG8 | QS3VH257QG | QS5LV919-70Q8 |
| QS3125QG8 | QS3390QG | QS3VH257QG8 | QS5LV931-80QG |
| QS3125S1G | QS3390QG8 | QS3VH257S1G | QS5LV931-80QG8 |
| QS3125S1G8 | QS33X257Q1G | QS3VH257S1G8 | VF2510BG |
| QS3126QG | QS33X257Q1G8 | QS3VH2861QG | VF2510BGILF |
| QS3126QG8 | QS34X2245Q3G | QS3VH2861QG8 | VF2510BGILFT |
| QS3126S1G | QS34X2245Q3G8 | QS3VH384PAG | VF2510BGLF |
| QS3126S1G8 | QS34X245Q3G | QS3VH384PAG8 | VF2510BGLFT |
| QS32245PAG | QS34X245Q3G8 | QS3VH384QG | VF2510BGLN |
| QS32245PAG8 | QS34X383Q3G | QS3VH384QG8 | VF2510BGLNT |
| QS32245QG | QS34X383Q3G8 | QS3VH800PAG | VF2510BGT |
| QS32245QG8 | QS34XVH2245Q3G | QS3VH800PAG8 | VS330DCG |
| QS32390QG | QS34XVH2245Q3G8 | QS3VH800QG | VS330DCG8 |
| QS32390QG8 | QS34XVH245Q3G | QS3VH800QG8 | VS330QG |
| QS3244PAG | QS34XVH245Q3G8 | QS3VH861QG | VS330QG8 |
| QS3244PAG8 | QS3800QG | QS3VH861QG8 | VS512QG |
| QS3244QG | QS3800QG8 | QS3VH862QG | VS512QG8 |
| QS3244QG8 | QS3861PAG | QS3VH862QG8 | |
| QS3245QG | QS3861PAG8 | QS4A101QG | |
| QS3245QG8 | QS3861QG | QS4A101QG8 | |
| QS3251QG | QS3861QG8 | QS4A105QG | |
| QS3251QG8 | QS3L384PAG | QS4A105QG8 | |
| QS3251S1G | QS3L384PAG8 | QS4A110QG | |
| QS3251S1G8 | QS3L384QG | QS4A110QG8 | |