



Integrated Device Technology, Inc.
6024 Silver Creek Valley Road
San Jose, CA 95138

PRODUCT DISCONTINUANCE NOTICE# CQ-13-03

ISSUE DATE: October 28, 2013

LAST BUY DATE: October 28, 2014

LAST SHIP DATE: January 28, 2015

REASON FOR DISCONTINUANCE:

The sales activity has declined to a level that warrants the discontinuance of these products. Some of these devices may have an alternate standard device or a suggested functional replacement.

Attached is a list of affected parts with any potential drop in replacement parts or suggested functional replacement parts.

Customers should contact IDT within 90 days of receipt of this notification if they have any additional questions or concerns related to this Product Discontinuance Notice. You may contact your local IDT Sales office listed on our web site at www.IDT.com or the marketing contact listed below:

SPO	Carl May 408-284-2718 carl.may@idt.com
TPC,NCS,NET	clocks@idt.com

Final orders may be submitted at any time prior to the last buy date indicated above. All orders shall be subject to acceptance per IDT standard terms and conditions.

Device to be Discontinued	Drop in Replacement	Functional Replacement	Replacement Part Availability	Product Group
71V35761S166BG	71V35761SA166BG	None	Available now	SPO
71V35761S166BG8	71V35761SA166BG8	None	Available now	SPO
71V35761S166BGG	71V35761SA166BGG	None	Available now	SPO
71V35761S166BGG8	71V35761SA166BGG8	None	Available now	SPO
71V35761S166BGGI	71V35761SA166BGGI	None	Available now	SPO
71V35761S166BGGI8	71V35761SA166BGGI8	None	Available now	SPO
71V35761S166BGI	71V35761SA166BGI	None	Available now	SPO
71V35761S166BGI8	71V35761SA166BGI8	None	Available now	SPO
71V35761S183BG	71V35761SA183BG	None	Available now	SPO
71V35761S183BG8	71V35761SA183BG8	None	Available now	SPO
71V35761S183BGG	71V35761SA183BGG	None	Available now	SPO
71V35761S183BGG8	71V35761SA183BGG8	None	Available now	SPO
71V35761S183BGGI	71V35761SA183BGGI	None	Available now	SPO
71V35761S183BGGI8	71V35761SA183BGGI8	None	Available now	SPO
71V35761S183BGI	71V35761SA183BGI	None	Available now	SPO
71V35761S183BGI8	71V35761SA183BGI8	None	Available now	SPO
71V35761S200BG	71V35761SA200BG	None	Available now	SPO
71V35761S200BG8	71V35761SA200BG8	None	Available now	SPO
71V35761S200BGG	71V35761SA200BGG	None	Available now	SPO
71V35761S200BGG8	71V35761SA200BGG8	None	Available now	SPO
71V35761S200BGGI	None	None	N/A	SPO
71V35761S200BGGI8	None	None	N/A	SPO
71V35761S200BGI	None	None	N/A	SPO
71V35761S200BGI8	None	None	N/A	SPO
71V35761SA200BGGI	None	None	N/A	SPO
71V35761SA200BGGI8	None	None	N/A	SPO
71V35761SA200BGI	None	None	N/A	SPO
71V35761SA200BGI8	None	None	N/A	SPO
71V35761SA200BQGI	None	None	N/A	SPO
71V35761SA200BQGI8	None	None	N/A	SPO
72V71650DA	None	None	N/A	NCS
72V71650DA8	None	None	N/A	NCS
72V90823APFG	None	72V90823BCG or 72V90823PFG or 72V90823PQFG	Available now	NCS
72V90823APFG8	None	72V90823BCG or 72V90823PFG or 72V90823PQFG	Available now	NCS
74FCT16501ATPAG	None	None	N/A	SPO
74FCT16501ATPAG8	None	None	N/A	SPO
74LVCH16601APVG	None	None	N/A	SPO
74LVCH16601APVG8	None	None	N/A	SPO
821024J/6512	None	None	N/A	NCS
821024J8/6512	None	None	N/A	NCS
82P2294BBG	None	None	N/A	NCS
82P2294BBG8	None	None	N/A	NCS
82P2294BCG	None	None	N/A	NCS
82P2294BCG8	None	None	N/A	NCS
82P5084BCG	None	None	N/A	NCS
82P5084BCG8	None	None	N/A	NCS
82P5088BCG	None	82P5088BBG	Available now	NCS
82P5088BCG8	None	82P5088BBG8	Available now	NCS
82V2048EDR	None	82V2048BBG or 82V2048DAG	Available now	NCS
82V2048EDR8	None	82V2048BBG8 or 82V2048DAG	Available now	NCS
82V2058ADAG	None	82V2058BBG	Available now	NCS
82V2058ADAG8	None	82V2058BBG8	Available now	NCS
82V2088DR	82V2088DRG	None	Available now	NCS
82V2088DR8	82V2088DRG8	None	Available now	NCS
82V2108PX	82V2108PXG	None	Available now	NCS
82V2108PX8	82V2108PXG8	None	Available now	NCS
82V2616BB	None	None	N/A	NCS
82V2616BB8	None	None	N/A	NCS
82V3001APV-09	82V3001APVG	None	Available now	NCS
82V3002A-01PVG	82V3002APVG	None	Available now	NCS
82V3002A-01PVG8	82V3002APVG8	None	Available now	NCS
82V3285APFG	None	82V3285EQG	Available now	NCS
82V3285APFG8	None	82V3285EQG8	Available now	NCS
82V3352TF	82V3352TFG	None	Available now	NCS
82V3352TF8	82V3352TFG8	None	Available now	NCS
82V5068DAG	None	82V5068BBG	Available now	NCS
82V5068DAG8	None	82V5068BBG8	Available now	NCS
82V5097DAG	None	82V5097BPFG	Available now	NCS
82V5097DAG8	None	82V5097BPFG8	Available now	NCS
82V5097PFG	None	82V5097BPFG	Available now	NCS
82V5097PFG8	None	82V5097BPFG8	Available now	NCS
84321AY	None	8T49N004-dddNLGI	Available now	NET
84321AYT	None	8T49N004-dddNLGI8	Available now	NET
843N4062AKILF	None	8T49N004-dddNLGI	Available now	NET
843N4062AKILFT	None	8T49N004-dddNLGI8	Available now	NET
849S1000BKLF	None	8T49N004-dddNLGI	Available now	NET
849S1000BKLFT	None	8T49N004-dddNLGI8	Available now	NET
88P8341BHGI	None	None	N/A	NCS



Integrated Device Technology, Inc.
 6024 Silver Creek Valley Road
 San Jose, CA 95138

Device to be Discontinued	Drop in Replacement	Functional Replacement	Replacement Part Availability	Product Group
88P8342BHGI	None	None	N/A	NCS
88P8344BHGI	None	None	N/A	NCS
8MJ4-156.250AJ	8N4S270EC-1028CDI	None	Available now	NET
8MJ4-156.250AJT	8N4S270EC-1028CDI8	None	Available now	NET
9DS400AGLF	None	None	N/A	TPC
9DS400AGLFT	None	None	N/A	TPC
XC9850VM	None	8T49N282B-dddNLGI	Available now	NET
XC9850VMR2	None	8T49N282B-dddNLGI8	Available now	NET