



Integrated Device Technology, Inc.
 6024 Silver Creek Valley Road, San Jose, CA 95138
 Phone #: (408) 284-8200

PRODUCT DISCONTINUANCE NOTICE (PDN)

PDN #: L-07-02

Last Buy Date: 10/29/08

Issue Date: 10/29/07

Last Ship Date: 01/29/09
 (3 months after last buy date)

Contact: Al Hornstein
 Title: Marketing Director
 Phone #: 1-408-284-6409
 Fax #: 1-408-284-8362
 E-mail: Al.Hornstein@idt.com

PRODUCT(S) AFFECTED: **ATTACHMENT** Yes No
(List Replacement Part #(s), if any)

Refer to Attachment 1 for discontinued product part number list and the recommend replacement part number.

REASON FOR DISCONTINUANCE:

- | | |
|--|---|
| <input type="checkbox"/> Replace slower speed with faster speed offerings <input type="checkbox"/> Obsolete Fab Technology / Process <input type="checkbox"/> Obsolete Assembly Technology / Process <input type="checkbox"/> Obsolete Package / Material <input type="checkbox"/> Declined Market | <input checked="" type="checkbox"/> Other: <u>Converting to green (RoHS compliant) product</u> <hr/> <hr/> <hr/> |
|--|---|

CUSTOMER NOTIFICATION:

As a result of discontinuance reason(s) listed above, IDT has decided to discontinue certain products and notify you through this Product Discontinuance Notice (PDN). We recommend you to check detailed specifications before converting to equivalent devices offered. Please use acknowledgement below or E-Mail to request additional information.

If you have any questions, please feel free to contact your local IDT distributor or sales representative.

Customer: _____

E-Mail Address: _____

Name/Date: _____

Phone#: _____

Title: _____

Fax# : _____

CUSTOMER COMMENTS: _____

IDT ACKNOWLEDGEMENT:

Received By: _____

Date: _____



Integrated Device Technology, Inc.
6024 Silver Creek Valley Road, San Jose, CA 95138
Phone #: (408) 284-8200

PRODUCT DISCONTINUANCE NOTICE (PDN)

Attachment A for PDN # L-07-02

Discontinued Product External Part Number and Recommend Replacement Part Number List.

| External Part | Replacement Part |
|---------------------|-------------------|
| IDT74ALVC162244PA | 74ALVC162244PAG |
| IDT74ALVC162245PA | 74ALVC162245PAG |
| IDT74ALVC162334PA | 74ALVC162334PAG |
| IDT74ALVC16244APA | 74ALVC16244PAG |
| IDT74ALVC16245PA | 74ALVC16245PAG |
| IDT74ALVC164245PA | 74ALVC164245PAG |
| IDT74ALVC164245PV | 74ALVC164245PVG |
| IDT74ALVC16835PF | 74ALVC16835PFG |
| IDT74ALVCH162244PA | 74ALVCH162244PAG |
| IDT74ALVCH162244PV | 74ALVCH162244PVG |
| IDT74ALVCH162245PA | 74ALVCH162245PAG |
| IDT74ALVCH162373PA | 74ALVCH162373PAG |
| IDT74ALVCH162373PV | 74ALVCH162373PVG |
| IDT74ALVCH162374PA | 74ALVCH162374PAG |
| IDT74ALVCH16244PA | 74ALVCH16244PAG |
| IDT74ALVCH16245PA | 74ALVCH16245PAG |
| IDT74ALVCH16245PF | 74ALVCH16245PFG |
| IDT74ALVCH16260PA | 74ALVCH16260PAG |
| IDT74ALVCH162820PA | 74ALVCH162820PAG |
| IDT74ALVCH16501PA | 74ALVCH16501PAG |
| IDT74ALVCH16501PV | 74ALVCH16501PVG |
| IDT74ALVCH16721PA | 74ALVCH16721PAG |
| IDT74ALVCH16823PA | 74ALVCH16823PAG |
| IDT74ALVCH16863PA | 74ALVCH16863PAG |
| IDT74ALVCH16901PA | 74ALVCH16901PAG |
| IDT74ALVCH16903PA | 74ALVCH16903PAG |
| IDT74ALVCHR162245PA | 74ALVCHR162245PAG |
| IDT74ALVCHR16601PA | 74ALVCHR16601PAG |
| IDT74CBTLV16210PA | 74CBTLV16210PAG |
| IDT74CBTLV16211PA | 74CBTLV16211PAG |
| IDT74CBTLV16211PF | 74CBTLV16211PFG |
| IDT74CBTLV16212PA | 74CBTLV16212PAG |
| IDT74CBTLV16245PA | 74CBTLV16245PAG |
| IDT74CBTLV16292PA | 74CBTLV16292PAG |
| IDT74CBTLV16800PA | 74CBTLV16800PAG |
| IDT74CBTLV16800PV | 74CBTLV16800PVG |
| IDT74CBTLV3125PG | 74CBTLV3125PGG |
| IDT74CBTLV3125Q | 74CBTLV3125QG |
| IDT74CBTLV3126PG | 74CBTLV3126PGG |
| IDT74CBTLV3126Q | 74CBTLV3126QG |
| IDT74CBTLV3244PG | 74CBTLV3244PGG |
| IDT74CBTLV3244Q | 74CBTLV3244QG |
| IDT74CBTLV3245PG | 74CBTLV3245PGG |
| IDT74CBTLV3245Q | 74CBTLV3245QG |



Integrated Device Technology, Inc.
6024 Silver Creek Valley Road, San Jose, CA 95138
Phone #: (408) 284-8200

PRODUCT DISCONTINUANCE NOTICE (PDN)

Attachment A for PDN # L-07-02

Discontinued Product External Part Number and Recommend Replacement Part Number List.

| External Part | Replacement Part |
|--------------------|------------------|
| IDT74CBTLV3251PG | 74CBTLV3251PGG |
| IDT74CBTLV3251Q | 74CBTLV3251QG |
| IDT74CBTLV3253Q | 74CBTLV3253QG |
| IDT74CBTLV3257PG | 74CBTLV3257PGG |
| IDT74CBTLV3257Q | 74CBTLV3257QG |
| IDT74CBTLV3384PG | 74CBTLV3384PGG |
| IDT74CBTLV3384Q | 74CBTLV3384QG |
| IDT74CBTLV3861PG | 74CBTLV3861PGG |
| IDT74CBTLV3861Q | 74CBTLV3861QG |
| IDT74CBTLV3862PG | 74CBTLV3862PGG |
| IDT74CBTLV3862PY | 74CBTLV3862PYG |
| IDT74CBTLV3862Q | 74CBTLV3862QG |
| IDT74CBTLV6800PG | 74CBTLV6800PGG |
| IDT74CBTLV6800Q | 74CBTLV6800QG |
| IDT74FCT157ATQ | 74FCT157ATQG |
| IDT74FCT157ATSO | 74FCT157ATSOG |
| IDT74FCT157CTQ | 74FCT157CTQG |
| IDT74FCT157CTSO | 74FCT157CTSOG |
| IDT74FCT157DTQ | 74FCT157DTQG |
| IDT74FCT157DTSO | 74FCT157DTSOG |
| IDT74FCT162244ATPA | 74FCT162244ATPAG |
| IDT74FCT162244ATPV | 74FCT162244ATPVG |
| IDT74FCT162244CTPA | 74FCT162244CTPAG |
| IDT74FCT162244CTPV | 74FCT162244CTPVG |
| IDT74FCT162244ETPA | 74FCT162244ETPAG |
| IDT74FCT162244ETPV | 74FCT162244ETPVG |
| IDT74FCT162245ATPA | 74FCT162245ATPAG |
| IDT74FCT162245ATPV | 74FCT162245ATPVG |
| IDT74FCT162245CTPA | 74FCT162245CTPAG |
| IDT74FCT162245CTPV | 74FCT162245CTPVG |
| IDT74FCT162373ATPA | 74FCT162373ATPAG |
| IDT74FCT162373ATPV | 74FCT162373ATPVG |
| IDT74FCT162373CTPA | 74FCT162373CTPAG |
| IDT74FCT162373CTPV | 74FCT162373CTPVG |
| IDT74FCT162373ETPA | 74FCT162373ETPAG |
| IDT74FCT162373ETPV | 74FCT162373ETPVG |
| IDT74FCT162374ATPA | 74FCT162374ATPAG |
| IDT74FCT162374ATPV | 74FCT162374ATPVG |
| IDT74FCT162374CTPA | 74FCT162374CTPAG |
| IDT74FCT162374CTPV | 74FCT162374CTPVG |
| IDT74FCT162374ETPA | 74FCT162374ETPAG |
| IDT74FCT162374ETPV | 74FCT162374ETPVG |
| IDT74FCT16244ATPA | 74FCT16244ATPAG |
| IDT74FCT16244ATPV | 74FCT16244ATPVG |



Integrated Device Technology, Inc.
 6024 Silver Creek Valley Road, San Jose, CA 95138
 Phone #: (408) 284-8200

PRODUCT DISCONTINUANCE NOTICE (PDN)

Attachment A for PDN # L-07-02

Discontinued Product External Part Number and Recommend Replacement Part Number List.

| External Part | Replacement Part |
|---------------------|-------------------|
| IDT74FCT16244CTPA | 74FCT16244CTPAG |
| IDT74FCT16244CTPV | 74FCT16244CTPVG |
| IDT74FCT16245ATPA | 74FCT16245ATPAG |
| IDT74FCT16245ATPV | 74FCT16245ATPVG |
| IDT74FCT16245CTPA | 74FCT16245CTPAG |
| IDT74FCT16245CTPV | 74FCT16245CTPVG |
| IDT74FCT16245ETPA | 74FCT16245ETPAG |
| IDT74FCT16245ETPV | 74FCT16245ETPVG |
| IDT74FCT162500ATPV | 74FCT162500ATPVG |
| IDT74FCT162500CTPV | 74FCT162500CTPVG |
| IDT74FCT162501ATPA | 74FCT162501ATPAG |
| IDT74FCT162501ATPV | 74FCT162501ATPVG |
| IDT74FCT162501CTPA | 74FCT162501CTPAG |
| IDT74FCT162501CTPV | 74FCT162501CTPVG |
| IDT74FCT162511ATPA | 74FCT162511ATPAG |
| IDT74FCT162511ATPV | 74FCT162511ATPVG |
| IDT74FCT162511CTPA | 74FCT162511CTPAG |
| IDT74FCT162511CTPV | 74FCT162511CTPVG |
| IDT74FCT162823ATPA | 74FCT162823ATPAG |
| IDT74FCT162823ATPV | 74FCT162823ATPVG |
| IDT74FCT162823CTPA | 74FCT162823CTPAG |
| IDT74FCT162823CTPV | 74FCT162823CTPVG |
| IDT74FCT162827ATPA | 74FCT162827ATPAG |
| IDT74FCT162827ATPV | 74FCT162827ATPVG |
| IDT74FCT162827CTPA | 74FCT162827CTPAG |
| IDT74FCT162827CTPV | 74FCT162827CTPVG |
| IDT74FCT162H245ATPA | 74FCT162H245ATPAG |
| IDT74FCT162H245ATPV | 74FCT162H245ATPVG |
| IDT74FCT162H245CTPA | 74FCT162H245CTPAG |
| IDT74FCT162H245CTPV | 74FCT162H245CTPVG |
| IDT74FCT163244APA | 74FCT163244APAG |
| IDT74FCT163244APF | 74FCT163244APFG |
| IDT74FCT163244APV | 74FCT163244APVG |
| IDT74FCT163244CPA | 74FCT163244CPAG |
| IDT74FCT163244CPF | 74FCT163244CPFG |
| IDT74FCT163244CPV | 74FCT163244CPVG |
| IDT74FCT163245APA | 74FCT163245APAG |
| IDT74FCT163245APF | 74FCT163245APFG |
| IDT74FCT163245APV | 74FCT163245APVG |
| IDT74FCT163245CPA | 74FCT163245CPAG |
| IDT74FCT163245CPF | 74FCT163245CPFG |
| IDT74FCT163245CPV | 74FCT163245CPVG |
| IDT74FCT163344APA | 74FCT163344APAG |
| IDT74FCT163344CPA | 74FCT163344CPAG |



Integrated Device Technology, Inc.
 6024 Silver Creek Valley Road, San Jose, CA 95138
 Phone #: (408) 284-8200

PRODUCT DISCONTINUANCE NOTICE (PDN)

Attachment A for PDN # L-07-02

Discontinued Product External Part Number and Recommend Replacement Part Number List.

| External Part | Replacement Part |
|--------------------|------------------|
| IDT74FCT163373APA | 74FCT163373APAG |
| IDT74FCT163373APV | 74FCT163373APVG |
| IDT74FCT163373CPA | 74FCT163373CPAG |
| IDT74FCT163373CPV | 74FCT163373CPVG |
| IDT74FCT163374APA | 74FCT163374APAG |
| IDT74FCT163374APV | 74FCT163374APVG |
| IDT74FCT163374CPA | 74FCT163374CPAG |
| IDT74FCT163374CPV | 74FCT163374CPVG |
| IDT74FCT163373ATPA | 74FCT163373ATPAG |
| IDT74FCT163373ATPV | 74FCT163373ATPVG |
| IDT74FCT163373CTPA | 74FCT163373CTPAG |
| IDT74FCT163373CTPV | 74FCT163373CTPVG |
| IDT74FCT163374ATPA | 74FCT163374ATPAG |
| IDT74FCT163374ATPV | 74FCT163374ATPVG |
| IDT74FCT163374CTPA | 74FCT163374CTPAG |
| IDT74FCT163374CTPV | 74FCT163374CTPVG |
| IDT74FCT163374ETPA | 74FCT163374ETPAG |
| IDT74FCT163374ETPV | 74FCT163374ETPVG |
| IDT74FCT163827APA | 74FCT163827APAG |
| IDT74FCT163827CPA | 74FCT163827CPAG |
| IDT74FCT164245TPA | 74FCT164245TPAG |
| IDT74FCT164245TPV | 74FCT164245TPVG |
| IDT74FCT16500ATPV | 74FCT16500ATPVG |
| IDT74FCT16500CTPV | 74FCT16500CTPVG |
| IDT74FCT16501ATPA | 74FCT16501ATPAG |
| IDT74FCT16501CTPA | 74FCT16501CTPAG |
| IDT74FCT16543ATPA | 74FCT16543ATPAG |
| IDT74FCT16543ATPV | 74FCT16543ATPVG |
| IDT74FCT16543CTPA | 74FCT16543CTPAG |
| IDT74FCT16543CTPV | 74FCT16543CTPVG |
| IDT74FCT16543ETPA | 74FCT16543ETPAG |
| IDT74FCT16543ETPV | 74FCT16543ETPVG |
| IDT74FCT166244ATPV | 74FCT166244ATPVG |
| IDT74FCT166244CTPV | 74FCT166244CTPVG |
| IDT74FCT16952ATPA | 74FCT16952ATPAG |
| IDT74FCT16952ATPV | 74FCT16952ATPVG |
| IDT74FCT16952CTPA | 74FCT16952CTPAG |
| IDT74FCT16952CTPV | 74FCT16952CTPVG |
| IDT74FCT16952ETPA | 74FCT16952ETPAG |
| IDT74FCT16952ETPV | 74FCT16952ETPVG |
| IDT74FCT2244ATQ | 74FCT2244ATQG |
| IDT74FCT2244ATSO | 74FCT2244ATSOG |
| IDT74FCT2244CTQ | 74FCT2244CTQG |
| IDT74FCT2244CTSO | 74FCT2244CTSOG |



Integrated Device Technology, Inc.
6024 Silver Creek Valley Road, San Jose, CA 95138
Phone #: (408) 284-8200

PRODUCT DISCONTINUANCE NOTICE (PDN)

Attachment A for PDN # L-07-02

Discontinued Product External Part Number and Recommend Replacement Part Number List.

| External Part | Replacement Part |
|------------------|------------------|
| IDT74FCT2245ATQ | 74FCT2245ATQG |
| IDT74FCT2245ATSO | 74FCT2245ATSOG |
| IDT74FCT2245CTQ | 74FCT2245CTQG |
| IDT74FCT2245CTSO | 74FCT2245CTSOG |
| IDT74FCT2373ATQ | 74FCT2373ATQG |
| IDT74FCT2373CTQ | 74FCT2373CTQG |
| IDT74FCT2374ATQ | 74FCT2374ATQG |
| IDT74FCT2374CTQ | 74FCT2374CTQG |
| IDT74FCT240ATPY | 74FCT240ATPYG |
| IDT74FCT240ATQ | 74FCT240ATQG |
| IDT74FCT240ATSO | 74FCT240ATSOG |
| IDT74FCT240CTPY | 74FCT240CTPYG |
| IDT74FCT240CTQ | 74FCT240CTQG |
| IDT74FCT240CTSO | 74FCT240CTSOG |
| IDT74FCT244ATPG | 74FCT244ATPGG |
| IDT74FCT244ATPY | 74FCT244ATPYG |
| IDT74FCT244ATQ | 74FCT244ATQG |
| IDT74FCT244ATSO | 74FCT244ATSOG |
| IDT74FCT244CTPG | 74FCT244CTPGG |
| IDT74FCT244CTPY | 74FCT244CTPYG |
| IDT74FCT244CTQ | 74FCT244CTQG |
| IDT74FCT244CTSO | 74FCT244CTSOG |
| IDT74FCT245ATPG | 74FCT245ATPGG |
| IDT74FCT245ATPY | 74FCT245ATPYG |
| IDT74FCT245ATQ | 74FCT245ATQG |
| IDT74FCT245ATSO | 74FCT245ATSOG |
| IDT74FCT245CTPG | 74FCT245CTPGG |
| IDT74FCT245CTPY | 74FCT245CTPYG |
| IDT74FCT245CTQ | 74FCT245CTQG |
| IDT74FCT245CTSO | 74FCT245CTSOG |
| IDT74FCT257ATQ | 74FCT257ATQG |
| IDT74FCT257ATSO | 74FCT257ATSOG |
| IDT74FCT257CTQ | 74FCT257CTQG |
| IDT74FCT257CTSO | 74FCT257CTSOG |
| IDT74FCT257DTQ | 74FCT257DTQG |
| IDT74FCT257DTSO | 74FCT257DTSOG |
| IDT74FCT3244APG | 74FCT3244APGG |
| IDT74FCT3244APY | 74FCT3244APYG |
| IDT74FCT3244AQ | 74FCT3244AQG |
| IDT74FCT3244ASO | 74FCT3244ASOG |
| IDT74FCT3244PG | 74FCT3244PGG |
| IDT74FCT3244PY | 74FCT3244PYG |
| IDT74FCT3244Q | 74FCT3244QG |
| IDT74FCT3244SO | 74FCT3244SOG |



Integrated Device Technology, Inc.
 6024 Silver Creek Valley Road, San Jose, CA 95138
 Phone #: (408) 284-8200

PRODUCT DISCONTINUANCE NOTICE (PDN)

Attachment A for PDN # L-07-02

Discontinued Product External Part Number and Recommend Replacement Part Number List.

| External Part | Replacement Part |
|-----------------|------------------|
| IDT74FCT3245APG | 74FCT3245APGG |
| IDT74FCT3245AQ | 74FCT3245AQQ |
| IDT74FCT3245PG | 74FCT3245PGG |
| IDT74FCT3245Q | 74FCT3245QG |
| IDT74FCT3573AQ | 74FCT3573AQQ |
| IDT74FCT3573Q | 74FCT3573QG |
| IDT74FCT373ATPY | 74FCT373ATPYG |
| IDT74FCT373ATQ | 74FCT373ATQG |
| IDT74FCT373ATSO | 74FCT373ATSOG |
| IDT74FCT373CTPY | 74FCT373CTPYG |
| IDT74FCT373CTQ | 74FCT373CTQG |
| IDT74FCT373CTSO | 74FCT373CTSOG |
| IDT74FCT374ATPY | 74FCT374ATPYG |
| IDT74FCT374ATQ | 74FCT374ATQG |
| IDT74FCT374ATSO | 74FCT374ATSOG |
| IDT74FCT374CTPY | 74FCT374CTPYG |
| IDT74FCT374CTQ | 74FCT374CTQG |
| IDT74FCT374CTSO | 74FCT374CTSOG |
| IDT74FCT377ATQ | 74FCT377ATQG |
| IDT74FCT377ATSO | 74FCT377ATSOG |
| IDT74FCT377CTQ | 74FCT377CTQG |
| IDT74FCT377CTSO | 74FCT377CTSOG |
| IDT74FCT377DTQ | 74FCT377DTQG |
| IDT74FCT377DTSO | 74FCT377DTSOG |
| IDT74FCT521ATPY | 74FCT521ATPYG |
| IDT74FCT521ATQ | 74FCT521ATQG |
| IDT74FCT521ATSO | 74FCT521ATSOG |
| IDT74FCT521CTPY | 74FCT521CTPYG |
| IDT74FCT521CTQ | 74FCT521CTQG |
| IDT74FCT521CTSO | 74FCT521CTSOG |
| IDT74FCT540ATPY | 74FCT540ATPYG |
| IDT74FCT540ATQ | 74FCT540ATQG |
| IDT74FCT540ATSO | 74FCT540ATSOG |
| IDT74FCT540CTPY | 74FCT540CTPYG |
| IDT74FCT540CTQ | 74FCT540CTQG |
| IDT74FCT540CTSO | 74FCT540CTSOG |
| IDT74FCT543ATQ | 74FCT543ATQG |
| IDT74FCT543ATSO | 74FCT543ATSOG |
| IDT74FCT543CTQ | 74FCT543CTQG |
| IDT74FCT543CTSO | 74FCT543CTSOG |
| IDT74FCT543DTQ | 74FCT543DTQG |
| IDT74FCT543DTSO | 74FCT543DTSOG |
| IDT74FCT573ATQ | 74FCT573ATQG |
| IDT74FCT573ATSO | 74FCT573ATSOG |



Integrated Device Technology, Inc.
6024 Silver Creek Valley Road, San Jose, CA 95138
Phone #: (408) 284-8200

PRODUCT DISCONTINUANCE NOTICE (PDN)

Attachment A for PDN # L-07-02

Discontinued Product External Part Number and Recommend Replacement Part Number List.

| External Part | Replacement Part |
|--------------------|------------------|
| IDT74FCT573CTQ | 74FCT573CTQG |
| IDT74FCT573CTSO | 74FCT573CTSOG |
| IDT74FCT574ATQ | 74FCT574ATQG |
| IDT74FCT574ATSO | 74FCT574ATSOG |
| IDT74FCT574CTQ | 74FCT574CTQG |
| IDT74FCT574CTSO | 74FCT574CTSOG |
| IDT74FCT823ATQ | 74FCT823ATQG |
| IDT74FCT823ATSO | 74FCT823ATSOG |
| IDT74FCT823CTQ | 74FCT823CTQG |
| IDT74FCT823CTSO | 74FCT823CTSOG |
| IDT74FST163244PA | 74FST163244PAG |
| IDT74FST163245PA | 74FST163245PAG |
| IDT74FST1632861PA | 74FST1632861PAG |
| IDT74FST32XL2384PA | 74FST32XL2384PAG |
| IDT74FST32XL384PA | 74FST32XL384PAG |
| IDT74FST6800PG | 74FST6800PGG |
| IDT74FST6800Q | 74FST6800QG |
| IDT74LVC162244APA | 74LVC162244APAG |
| IDT74LVC162244APF | 74LVC162244APFG |
| IDT74LVC162244APV | 74LVC162244APVG |
| IDT74LVC162245APA | 74LVC162245APAG |
| IDT74LVC162245APF | 74LVC162245APFG |
| IDT74LVC162245APV | 74LVC162245APVG |
| IDT74LVC16244APA | 74LVC16244APAG |
| IDT74LVC16244APF | 74LVC16244APFG |
| IDT74LVC16244APV | 74LVC16244APVG |
| IDT74LVC16245APA | 74LVC16245APAG |
| IDT74LVC16245APF | 74LVC16245APFG |
| IDT74LVC16245APV | 74LVC16245APVG |
| IDT74LVC16344APA | 74LVC16344APAG |
| IDT74LVC16344APV | 74LVC16344APVG |
| IDT74LVC16373APA | 74LVC16373APAG |
| IDT74LVC16373APV | 74LVC16373APVG |
| IDT74LVC16374APA | 74LVC16374APAG |
| IDT74LVC16374APV | 74LVC16374APVG |
| IDT74LVC16501APA | 74LVC16501APAG |
| IDT74LVC16501APV | 74LVC16501APVG |
| IDT74LVC16601APA | 74LVC16601APAG |
| IDT74LVC16601APV | 74LVC16601APVG |
| IDT74LVC16823APA | 74LVC16823APAG |
| IDT74LVC16823APV | 74LVC16823APVG |
| IDT74LVC16827APA | 74LVC16827APAG |
| IDT74LVC244APG | 74LVC244APGG |
| IDT74LVC244APY | 74LVC244APYG |



Integrated Device Technology, Inc.
6024 Silver Creek Valley Road, San Jose, CA 95138
Phone #: (408) 284-8200

PRODUCT DISCONTINUANCE NOTICE (PDN)

Attachment A for PDN # L-07-02

Discontinued Product External Part Number and Recommend Replacement Part Number List.

| External Part | Replacement Part |
|---------------------|-------------------|
| IDT74LVC244AQ | 74LVC244AQQ |
| IDT74LVC244ASO | 74LVC244ASOG |
| IDT74LVC245APG | 74LVC245APGG |
| IDT74LVC245APY | 74LVC245APYG |
| IDT74LVC245AQ | 74LVC245AQQ |
| IDT74LVC245ASO | 74LVC245ASOG |
| IDT74LVC273APG | 74LVC273APGG |
| IDT74LVC273APY | 74LVC273APYG |
| IDT74LVC4245APG | 74LVC4245APGG |
| IDT74LVC4245APY | 74LVC4245APYG |
| IDT74LVC4245AQ | 74LVC4245AQQ |
| IDT74LVC4245ASO | 74LVC4245ASOG |
| IDT74LVC541AQ | 74LVC541AQQ |
| IDT74LVCC3245APG | 74LVCC3245APGG |
| IDT74LVCC3245ASO | 74LVCC3245ASOG |
| IDT74LVCH162244APA | 74LVCH162244APAG |
| IDT74LVCH162244APF | 74LVCH162244APFG |
| IDT74LVCH162245APA | 74LVCH162245APAG |
| IDT74LVCH162245APF | 74LVCH162245APFG |
| IDT74LVCH162245APV | 74LVCH162245APVG |
| IDT74LVCH162373APA | 74LVCH162373APAG |
| IDT74LVCH162373APV | 74LVCH162373APVG |
| IDT74LVCH162374APA | 74LVCH162374APAG |
| IDT74LVCH162374APV | 74LVCH162374APVG |
| IDT74LVCH16244APA | 74LVCH16244APAG |
| IDT74LVCH16244APV | 74LVCH16244APVG |
| IDT74LVCH16245APA | 74LVCH16245APAG |
| IDT74LVCH16245APV | 74LVCH16245APVG |
| IDT74LVCH16373APA | 74LVCH16373APAG |
| IDT74LVCH16374APA | 74LVCH16374APAG |
| IDT74LVCH16374APV | 74LVCH16374APVG |
| IDT74LVCH16543APA | 74LVCH16543APAG |
| IDT74LVCH16601APV | 74LVCH16601APVG |
| IDT74LVCH16646APA | 74LVCH16646APAG |
| IDT74LVCH16646APF | 74LVCH16646APFG |
| IDT74LVCHR162245APA | 74LVCHR162245APAG |
| IDT74LVCHR16646APA | 74LVCHR16646APAG |
| IDT74LVCR162245APA | 74LVCR162245APAG |
| IDT74LVCR162245APV | 74LVCR162245APVG |
| IDTQS3125Q | QS3125QG |
| IDTQS3125S1 | QS3125S1G |
| IDTQS3126Q | QS3126QG |
| IDTQS3126S1 | QS3126S1G |
| IDTQS32245PA | QS32245PAG |



Integrated Device Technology, Inc.
 6024 Silver Creek Valley Road, San Jose, CA 95138
 Phone #: (408) 284-8200

PRODUCT DISCONTINUANCE NOTICE (PDN)

Attachment A for PDN # L-07-02

Discontinued Product External Part Number and Recommend Replacement Part Number List.

| External Part | Replacement Part |
|------------------|------------------|
| IDTQS32245Q | QS32245QG |
| IDTQS32390Q | QS32390QG |
| IDTQS3244Q | QS3244QG |
| IDTQS3244SO | QS3244SOG |
| IDTQS3245Q | QS3245QG |
| IDTQS3245SO | QS3245SOG |
| IDTQS3251Q | QS3251QG |
| IDTQS3251S1 | QS3251S1G |
| IDTQS3253Q | QS3253QG |
| IDTQS3253S1 | QS3253S1G |
| IDTQS3257Q | QS3257QG |
| IDTQS3257S1 | QS3257S1G |
| IDTQS32X2245Q2 | QS32X2245Q2G |
| IDTQS32X2384Q1 | QS32X2384Q1G |
| IDTQS32X245Q2 | QS32X245Q2G |
| IDTQS32X384Q1 | QS32X384Q1G |
| IDTQS32X861Q1 | QS32X861Q1G |
| IDTQS32XL384Q1 | QS32XL384Q1G |
| IDTQS32XVH2245Q2 | QS32XVH2245Q2G |
| IDTQS32XVH245Q2 | QS32XVH245Q2G |
| IDTQS32XVH384Q1 | QS32XVH384Q1G |
| IDTQS3306AS1 | QS3306AS1G |
| IDTQS3383Q | QS3383QG |
| IDTQS3384PA | QS3384PAG |
| IDTQS3384Q | QS3384QG |
| IDTQS3390Q | QS3390QG |
| IDTQS3390SO | QS3390SOG |
| IDTQS33X257Q1 | QS33X257Q1G |
| IDTQS34X2245Q3 | QS34X2245Q3G |
| IDTQS34X245Q3 | QS34X245Q3G8 |
| IDTQS34X383Q3 | QS34X383Q3G |
| IDTQS34XVH2245Q3 | QS34XVH2245Q3G |
| IDTQS34XVH245Q3 | QS34XVH245Q3G |
| IDTQS3800Q | QS3800QG |
| IDTQS3861PA | QS3861PAG |
| IDTQS3861Q | QS3861QG |
| IDTQS3L384PA | QS3L384PAG |
| IDTQS3L384Q | QS3L384QG |
| IDTQS3VH125Q | QS3VH125QG |
| IDTQS3VH125S1 | QS3VH125S1G |
| IDTQS3VH126Q | QS3VH126QG |
| IDTQS3VH126S1 | QS3VH126S1G |
| IDTQS3VH16210PA | QS3VH16210PAG |
| IDTQS3VH16211PA | QS3VH16211PAG |



Integrated Device Technology, Inc.
6024 Silver Creek Valley Road, San Jose, CA 95138
Phone #: (408) 284-8200

PRODUCT DISCONTINUANCE NOTICE (PDN)

Attachment A for PDN # L-07-02

Discontinued Product External Part Number and Recommend Replacement Part Number List.

| External Part | Replacement Part |
|-----------------|------------------|
| IDTQS3VH16212PA | QS3VH16212PAG |
| IDTQS3VH16233PA | QS3VH16233PAG |
| IDTQS3VH16244PA | QS3VH16244PAG |
| IDTQS3VH16245PA | QS3VH16245PAG |
| IDTQS3VH16800PA | QS3VH16800PAG |
| IDTQS3VH16861PA | QS3VH16861PAG |
| IDTQS3VH16862PA | QS3VH16862PAG |
| IDTQS3VH2245PA | QS3VH2245PAG |
| IDTQS3VH2245Q | QS3VH2245QG |
| IDTQS3VH244PA | QS3VH244PAG |
| IDTQS3VH244Q | QS3VH244QG |
| IDTQS3VH245PA | QS3VH245PAG |
| IDTQS3VH245Q | QS3VH245QG |
| IDTQS3VH251PA | QS3VH251PAG |
| IDTQS3VH251Q | QS3VH251QG |
| IDTQS3VH253PA | QS3VH253PAG |
| IDTQS3VH253Q | QS3VH253QG |
| IDTQS3VH257PA | QS3VH257PAG |
| IDTQS3VH257Q | QS3VH257QG |
| IDTQS3VH257S1 | QS3VH257S1G |
| IDTQS3VH2861Q | QS3VH2861QG |
| IDTQS3VH384Q | QS3VH384QG |
| IDTQS3VH800PA | QS3VH800PAG |
| IDTQS3VH800Q | QS3VH800QG |
| IDTQS3VH861Q | QS3VH861QG |
| IDTQS3VH862Q | QS3VH862QG |
| IDTQS4A101Q | QS4A101QG |
| IDTQS4A105Q | QS4A105QG |
| IDTQS4A110Q | QS4A110QG |
| IDTQS4A201Q | QS4A201QG |
| IDTQS4A205Q | QS4A205QG |
| IDTQS4A210Q | QS4A210QG |
| IDTQS4A215Q1 | QS4A215Q1G |

For T&R shipping method, suffix '8' is added to the Part Number